

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R.W.W.M.

MOORE-CHAPMAN CO. EUGENE, ORE. 97801

29

$\frac{1}{4}$ Corner to Sections 25 and 26.
Found - Orig. 7", now 28" Fir, Alive, N. $84\frac{1}{2}^{\circ}$ W. 36.3 ft.,
shows scar, do not open.
Orig. 8", now 32" Fir, Alive, S. 5° E. 17.8 ft., scribe marks
visible on previously opened blaze.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W
Office, 1967 $\frac{1}{4}$ S 26 | S 25
New BT: 15" Hemlock S. 82° E. 53.4 ft. mkd. $\frac{1}{4}$ S25 CS BT.
Note - This corner lies 25 ft. south of access road, course E. & W.

30

$\frac{1}{4}$ Corner to Sections 22 and 23.
Found - 1962 Co. Surv. Brass Cap properly marked & recorded in Ren. #7-B.
Also, fragments of Orig. Sandstone Corner Rock used to fill
hole for Brass Cap.
Orig. 36", now 48" Fir, N. 10° E. 9.2 ft. from face. Alive, unopened.
Shows good scar.
Orig. 30", now 34" Fir S. 21° W. 9.2 ft. from face. Alive,
unopened & shows good scar.
New BT's: 8" Hemlock S. 70° W. 16.7 ft. mkd. $\frac{1}{4}$ S22 CS BT.
11" Hemlock S. 72° E. 13.4 ft. mkd. $\frac{1}{4}$ S23 CS BT.
Note - This corner lies 25 ft. W. & 35 ft. N. of top of main ridge,
course NE - SW.

31

Witness Corner to $\frac{1}{4}$ Corner Sections 26 and 27.
Found - 27" D. Fir, now 5' high Stump, N. 41° W. 11.7 ft., scribe visible
on pitched blazes. See Ren. #7-A. (See other BT. below)
No trace of I. Rod or any other BT's. Due to slide & logging,
 $\frac{1}{4}$ corner falls on nearly verticle rock face. Destroyed Wit. Cor. was
75 ft. south of true corner. We set new Wit. Cor. out of slide area,
105 ft. south of true corner.
Set - Brass Cap at Wit. Cor. Mkd: County Surveyor T 23 S R 9 W
Office, 1967 $\frac{1}{4}$ S 27 | S 26
(Wit. Cor. to $\frac{1}{4}$ Cor. 105' N. to Corner)
New BT's: No live trees near:
9" Hemlock Stump S. 78° E. 28.2 ft. mkd. W.C. $\frac{1}{4}$ S26 CS BT.
18" D. Fir Stump N. 78° W. 34.4 ft. mkd. W.C. $\frac{1}{4}$ S27 CS BT.
Ren. #7A BT.-27" D. Fir Stump bears N. $10\frac{1}{2}^{\circ}$ W. 38.7 ft.

32

$\frac{1}{4}$ Corner common to Sections 27 and 34.
Found - GLO Survey Record, Post - Gone.
24" Fir, N. 53° W. 25 lks., now 26" Fir Stub busted off below
scribing--bottom of face visible.
20" Fir S. 32° W. 27 lks., now 32" Fir, chopped open--scribe visible. **61**
Set - 4' x $\frac{3}{4}$ " Pipe & square post, re-reference with "W" nail &
Weyerhaeuser tags: 30" Fir N. 53° W. 36.2 ft.
32" Fir S. 33° W. 16.7 ft.

33

Section Corner common to Secs. 26-27-34 & 35.
Found - GLO Record Post -- Gone.
10" Alder N. 53° E. 7 lks., now Gone, stub, rotted off below scribe.
6" hemlock S. $51\frac{1}{2}^{\circ}$ E. 47 lks., now 8" hem. stub, rotted off below scribe.
8" Fir S. 5° W. 8 lks., now 17" fir stub broken off below
scribing; scribing visible on downed part of log.
10" fir, N. 68° W. 43 lks., now 22" fir snag--face visible-- healed
over-- cruiser's marks.
Set - 4' x $\frac{3}{4}$ " Pipe & square post, re-referenced with "W" nail &
Weyerhaeuser Tapes: 28" Fir N. 62° E. 25.4 ft.
22" hem S. 47° E. 38.5 ft.
27" hem S. 5° W. 14.5 ft.
17" hem N. 45° W. 31.4 ft.

Vernon "Ray" Tracy
Jack Heritage & E. West
March & April, 1967
C.S. File No. 54/60

Donald L. Peel
For Weyerhaeuser Co.
March, 1967
C. S. File No. 55/30