

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21821

39

$\frac{1}{4}$  Corner to Section 2 only, T23-9W.  
Found -  $1\frac{1}{2}$ " Iron Pipe & brazed Iron Cap, unrecorded.  
Orig. 16", now 38" Fir, alive, East 23.1 ft., shows scar, do not open.  
Orig. 8", now 30" Fir, now down, broken off, West 34.3 ft, broken off  
stump in place, scribed " $\frac{1}{4}$ ".  
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W  $\frac{1}{4}$   $\frac{S^* 2}{S}$   
Office, 1967 T23S  
New BT's: 16" Maple S.89°W. 14.2 ft. mkd. " $\frac{1}{4}$ " S 2 CS BT".  
7" D. Fir S. 31° E. 18.4 ft. mkd. " $\frac{1}{4}$ " S2 CS BT".  
Deposit Iron pipe alongside Brass Cap.  
Note - This corner lies on moderate north slope of ridge.

40

Section Corner to Sections 4 - 5 - 8 - 39.  
Found - Orig. 40", now 50" Fir, alive, N.35°E. 21.1 ft., shows "T2 S" bark  
scribe in poor condition.  
Other Bearing Trees turned out.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W  
Office S 5 | S 4  
1967 S 8 | S 9  
New BT's: 18" Hemlock N. 79° E. 10.0 ft. mkd. T23S R9W S 4 CS BT.  
16" Alder N. 35° W. 15.2 ft. mkd. T23S R9W S 5 CS BT.  
15" Alder S. 53° E. 23.2 ft. mkd. T23S R9W S9 CS BT.  
No suitable tree to S. W. This corner lies 75 ft. East of  
creek, course N.

41

Sec. Cor. to Secs. 31 & 32, T22-9W. & Sans. 5 & 6, T23-9W.  
Found - Orig. 30" Cedar, now 40" decayed stump, N.65°E. 37.0 ft., find  
partial axe notch, no scribe, unable to get ring count.  
Orig. 36", now 52" Cedar, alive, N.30°W. 69.3 ft., prev.  
opened, no scribe. We open higher & find top of old axe  
blaze & open lower & find axe notch, under 85+ years, ring count.  
No trace other BT's. Calls north to creek fit well.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W S 31 | S 32  
Office, 1968 T23S S 6 | S 5  
New BT's: 22" Hemlock N. 22° W. 17.0 ft. mkd. T22S R9W S31 CS BT.  
24" Hemlock N. 7° E. 18.7 ft. mkd. T22S R9W S32 CS BT.  
35" Hemlock S. 77° W. 65.8 ft. mkd. T23S R9W S 6 CS BT.  
22" Hemlock S. 44° E. 25.0 ft. mkd. T22S R9W S 5 CS BT.  
1/4/68

42

Section Corner to Sections 1 and 2 only, T23-9W.  
Found - Orig. BT marked in 1894, & 36", now 46" Fir, S.66°W. 178.2 ft.,  
tree down, chop open & find scribe "T23S R9W".  
At point established from this BT, we find probable remains  
of Original Bearing Trees, as follows:  
Burned remains of Stump N. 45° E. 6.6 ft.  
Burned remains of Stump S. 40° E. 4.6 ft.  
Stump Hole N. 80° W. 23.8 ft. - No scribe at these points.  
Measured west from CC. of Secs. 35 & 36, T22-9W 732.1 ft. (Record 736.6 ft.)  
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W S 2 | S 1  
Office, 1968 T23S  
New BT's: 18" D. Fir S.75°E. 7.5 ft. mkd. T23S R9W S1 CS BT.  
10" D. Fir S.28°W. 19.2 ft. mkd. T23S R9W S2 CS BT.  
16" D. Fir West 9.0 ft. mkd. T23S R9W S2 CS BT. 2/8/68

43

Closing Corner to Sections 35 and 36 only, T22-9W.  
Found - Unrecorded  $1\frac{1}{2}$ " I.P. at corner, nearly flush with ground.  
Orig. 24" Fir, now 36" Stump, N.44°E. 38.3 ft., shows scar. Do not open.  
Orig. 36", Fir, now 42" Stump, S.33°E. 17.8 ft., burned. Open &  
find "2S" scribe and reverse.  
Orig. 36" Fir, now 44" Stump, N.58°W. 29.7 ft., Open & find scribe "S".  
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R9W S 35 | S 36 CC  
(Deposit I.P. alongside) Office, 1968 T23S  
New BT's: 9" D. Fir N.43 $\frac{1}{2}$ °E. 27.1 ft. mkd. T22S R9W S36 CCCS BT.  
9" D. Fir N.50°W. 74.9 ft. mkd. T22S R9W S 35 CC CS BT.  
Note - This corner lies on steep, south slope in old logged area.  
2/7/68

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
December & January, 1968  
C. S. File No. 54/60