

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 2 - 3 - 10 - 11.

Found - Old, squared Post, partially buried, See Ren. #8, 1899.

Orig. 5", now 13" Maple, Alive, N. 75° W. 15.8 ft., 3 trees on one stump.

Orig. 4", now 12" Maple, Alive, S. 89° W. 19.2 ft., open & find scribe.

Orig. 10", now 22" Maple, Alive, N. 89° E. 29.0 ft., 2 trees on one stump.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W
Office S 3 | S 2
1969 S 10 | S 11

New BT's: 18" D. Fir S. 25° W. 22.0 ft. mkd: "T23S R9W S10 CS BT".

12" Hemlock S. 88° E. 8.2 ft. mkd: "T23S R9W S11 CS BT".

8" Hemlock N. 31° W. 44.6 ft. mkd: "T23SR9W S 3 CS BT".

No trees suitable to Northeast.

This corner lies about 330 ft. north of top of spur, sloping N.W.

11/24/69

55

Vernon "Ray" Tracy
J. Heritage-V. Perron
Nov. 1969 C.S. File 54/60

B.C.
6/1/84
E. White
11/9/76

1/4 Corner Sections 14 and 23.

Found - Orig. 10" Maple S. 40° E. 5.3 ft., down and badly decayed,
frag. scribe on edges of blaze.

Orig. 16" Cedar N. 69 1/2° W. 29.7 ft. Only decayed stump 8"
high, log mostly decayed away, no scribe found.

Spur ridges call to E. fits record. dist.

Set - Brass cap at cor. mkd. County Surveyor's T23S 1/4 S14 R9W
Office 1969 S23

New BT's: 8" Hemlock N. 72° W. 28.6 ft. mkd: 1/4 S14 CS BT.

24" Douglas Fir S. 75° E. 22.6 ft. mkd: 1/4 S. 23 CS BT.

Note- This cor. lies on SW. slope 80 ft. W. of top of spur.

Jan. 12, 1970

56

Section Corner to Sections 27 - 28 - 33 - 34.

Found - Orig. 30" Fir N. 52 1/2° E. 41.6 ft., now only small part of shattered
stump remains, no scribe found.

Orig. 10", now 28" Hemlock, 12 ft. high snag, S. 82° E. 25.1 ft.,
reverse scribe visible through hole on backside.

No trace other Orig. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W
Office S 28 | S 27
1970 S 33 | S 34

New BT's: 7" Hemlock S. 20° W. 27.2 ft. mkd: "T23S R9W S33 CS BT".

20" Hemlock S. 44° E. 45.0 ft. mkd: "T23S R9W S34 CS BT".

7" Hemlock N. 76° W. 38.1 ft. mkd: "T23S R9W S28 CS BT".

7" D. Fir N. 40° E. 21.4 ft. mkd: "T23S R9W S27 CS BT".

June 1970

57

Vernon "Ray" Tracy
V. Perron C.S. File No. 54/60

Section Corner to Sections 9 - 10 - 15 - 16.

Found - Orig. 40" Fir, now stump, N. 5° E. 30.4 ft., no scribe, found bark gone.

Orig. 36", now 40" Fir Stump, N. 24° W. 41.6 ft., old axe blaze,
possible fragmentary scribe on bark.

Orig. 60", now 64" Fir Stump, out of place, S. 72° E. 71.3 ft.,
fragmentary bark scribe.

Orig. BT. to S. W. gone.

Calls E. - W. & S. to ridge tops fit old field notes good.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W
Office S 9 | S 10
1970 S 16 | S 15

Remark O. BT's.: 40" Fir Stump N. 24° W. 41.6 ft. mkd: T23SR9W S 9 CS BT.

40" Fir Stump N. 5° E. 30.4 ft. mkd: T23S R9WS10 CS BT.

No live trees available. - Line Tag on road to S. of cor.

Set - 3/4" Iron Rod S. 61° E. 20.0 ft. & 3/4" I. Rod S. 74° W. 15.0 ft.

June, 1970

1/4 Corner to Sections 9 and 16.

Found - 1" I. Pipe at corner, unrecorded, set from Orig. BT. Stumps.

Orig. 50" Fir, now 60" Stump, N. 17° E. 38.9 ft., no bark or scribe found.

Orig. 60" Fir, now 64" Stump, S. 66° W. 19.8 ft., old bark blaze, no
scribe, blaze in poor condition. Creek call to W. fits this location.

DO NOT SET BRASS CAP, as Pipe is in good condition.

New BT's: 5" D. Fir N. 32° W. 16.4 ft. mkd: "1/4 S 9 CS BT".

6" Alder S. 26° E. 6.4 ft. mkd: "1/4 S16 CS BT".

This corner lies on bench in large clear-cut area, now covered with
dense brush and reproduction.

59