

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

60

1/4 Corner to Sections 30 and 31.  
Found - Orig. 10", now 16" Fir Snag, N. 28° E. 7.9 ft., "1/4" scribe visible  
on open blaze. No trace of other Orig. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W  
Office S 30  
1970 S 31  
New BT's: 8" Chinquapin N. 85° E. 7.6 ft. mkd: "1/4 S30 CS BT"  
(No other suitable tree in Section 30)  
32" D. Fir S. 42° W. 22.9 ft. mkd: "1/4 S31 CS BT".  
This corner lies on top of spur, sloping N.W. & in extremely dense brush.  
No beat way to go to this corner at this time.

FNO ok 5/91  
M113-34748

61

1/4 Corner to Sections 27 and 34.  
Found - 1/2" Steel Tube and Orig. BT's., See Ren. #32.  
Orig. 24", now 26" Fir, down, badly decayed. N. 53° W. 16.5 ft., no scribe found  
Orig. 20", now 29" Fir, alive, S. 32° W. 17.8 ft., open & find "S34" scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W  
(Reset Tube Alongside) Office S 27  
1970 S 34  
New BT's: 19" D. Fir S. 51° W. 27.3 ft. mkd: "1/4 S34 CS BT".  
30" D. Fir N. 61° E. 25.4 ft. mkd: "1/4 S27 CS BT".  
This corner lies on nearly flat bench on easterly slope of Mt.  
Found - Weyerhaeuser BT. 30" Fir N. 53° W. 36.2 ft., "W" & plate.

62

Section Corner to Sections 8 - 9 - 16 - 17.  
Found - Orig. 30" Fir, now 40" sawed Stump, N. 9° W. 52.8 ft., partial axe  
blaze on bark, chopped open by someone, no scribe. Also has  
old yellow tag dated 1945 & numerous brag marks.  
Orig. 26", now 36" Fir, badly decayed & burned, S. 54° E. 33.7 ft.,  
no scribe found.  
Orig. 40", now 48" Fir, badly decayed & burned, N. 89° E. 47.5 ft.,  
no scribe found.  
No trace of Orig. BT to S.W., Call of 2 ch. to E. was on trail,  
I assume trail was on ridge top. The approx. 60 ft. elevation below top  
of ridge also looks O.K. Call on creek to S. fits O.K., by pacing.  
This position has been recognized as corner point for at least 25 years.  
Also find remains of very old & badly decayed sq. post.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 9 W  
Office S 8 | S 9  
1970 S 17 | S 16  
New BT's: 10" D. Fir S. 19° W. 10.0 ft. mkd: "T23S R9W S17 CS BT".  
16" D. Fir S. 76° E. 12.5 ft. mkd: "T23S R9W S16 CS BT".  
18" D. Fir N. 31° W. 23.0 ft. mkd: "T23S R9W S 8 CS BT".  
11" D. Fir N. 26° E. 40.3 ft. mkd: "T23S R9W S 9 CS BT".  
This corner lies on steep westerly slope in dense brush.

MARCH 71

6/8/70

63

1/4 Corner to Sec. 19, T23-9 and Sec. 24, T23-10. #89  
Set - 1 1/2" x 36" galv. Iron Pipe with 3" Bronze Cap mkd: Ore. St. Bd.  
of Forestry, 36" in ground.  
16" Hemlock S. 57° E. 42.6 ft., YMLP (RS359)  
14" Hemlock N. 22° W. 30.9 ft.  
4 1/2" x 72" White Painted Cedar Post N. 84° E. 4.0 ft.  
6/29/72

RE-RENEWED CORNER NO. #89

64

1/4 corner Sections 29 & 30.  
Found - 2" iron pipe 23" above ground.  
36" stump, bears N. 30° E., (rec. N. 20° E) 12.8 ft.  
(rec. 12.54 ft.) scribed "1/4 S 29 BT"  
Other BT, a stump out of ground, badly burned & rotted,  
lies almost directly over corner.  
Set - Brass cap at corner inside iron pipe mkd: # 103  
COUNTY SURVEYORS T 23 S R 9 W  
OFFICE 1/4  
1973 S 30 | S 29  
New BT's - 6" D. Fir, bears N. 3 1/2° E., 18.8 ft. scribed  
S29 CS BT.  
8" Fir, bears S. 49° W., 54.5 ft. scribed T23S R9W  
S30 CS BT.  
10/26/73

FNO ok  
5/91 M113-34748

RE-RENEWED CORNER NO. #103

Vernon "Ray" Tracy  
C. S. File No. 54/60  
V. Perron

L. E. Monrean  
Pete Earle  
C.S. 56/39  
10/26/73

JAN 1972