

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 9 R.W.W.M.

WORE-CHAPMAN CO. EUGENE, ORE. 21881

72

1/4 Corner for Secs. 28 and 33.

Found - Orig. NE bearing tree, a 20" D. Fir, now a 30" snag, which we open and find good scribing "BT".

The orig. NW bearing is down and downhill from its orig. position.

We find good scribing "1/4" on a previously opened blaze.

At the corner point, we find a 5/8" x 60" I. Rod extending 2.3 ft. above ground. Ren. #19.

Set - At the corner point, we set a 1" x 30" Iron pipe with brass cap attached marked:

COUNTY SURVEYORS	T 23 S
OFFICE	1/4 S 28
1975	S 33
	R 9 W

and place iron rod alongside brass cap,

From which:

An orig. 20" Fir, now a 30" snag bears N.15°E., 31.0 ft. We open and find good scribing "BT".

We note the following bearing objects:

A bridge spike driven in the top of a 48" Fir stump, directly above the center of its root collar bears N.52°E., 23.8 ft.

A bridge spike driven in the top of a 38" Fir stump, directly above its root collar bears N.29°W., 72.6 ft.

We place a steel fencepost with survey marker sign attached approx. one foot east of the corner.

Note - This corner lies in a clear cut unit in dense brush and logging debris on a northwest facing slope and approx. 100 ft. south east of a small stream. Compass declination setting: 20° east.

2/12/75

73

West 1/4 corner of Sec. 31 only, T23 R8

Found: Rotted Hemlock stump with scribed BT legible. Bears S 38°E., 4.6 ft. (scribe is on NE face of stump)

70' Fir with scar bears N62°E., 46.2 ft. (call N.2°E., 46.2 ft.)

New: I intersect call distances and match bearing to SE BT (no sign of any other possible 70" Fir) and

Set: Brass cap on 1 1/2 Iron pipe stamped

DOUGLAS CO. SURVEYOR
1975

T 23 S

R		R
9		8
W		W

W 1/4 S 31

A 8" hemlock scribed T 23S R8W S 31 CS BT in a Double blaze
Bears S 63°E., 14.7 Ft. Compass Declination 20°

1/4 Corner of Sec. 23 & 24

Found: 60" Fir stumped and rotted on south side possible N.W. B.T. Chop into S.E. face and find no sign of scribe. Diligent search finds no sign of stone or S.W. BT. May have stood although ground is rocky and soil loose. No definite sign of any hole where S.W. BT may have stood.

I do not monument at this time. NOTE: This appears to be the accepted location for this corner and matches all calls.

74

Clell Goodwin
Lenora Ladig
6/17/75
C.S. 57/30

106

1/4 Corner for Secs. 23 and 26

Found - Metal fence post set by BLM.

Set - 5/8" Iron along side post.

From which:

Orig. D. Fir, 44" now dead with face partially chopped out, N.38°E., 17 lks. (record, N.38°W.)

Orig. D. Fir, 29", face partially chopped out, S.5°E., 23.8 ft. (36 lks.)

I mark 37" D. Fir, N.16°W., 16.2 ft.

75

Ronald E. Stuntzner
For: International
Paper Co.
June 7, 1976
M 60 - 41

76

Center 1/4 Corner for Sec. 26.

Set - 5/8" Iron rod with yellow cap

From which I scribe:

48" D. Fir, N.51°W., 29.7 ft.

6" Hemlock, S.57 1/2°W., 10.0 ft.

48" D. Fir, S.72°30'E., 52.2 ft.

Gary L. Langlitz, County Surveyors office
Peter L. Earle
Feb. 12, 1975
C.S. 57/17