

Douglas County Surveyor's Record of
Government Corners Renewed

T 23

T. S.

R 9

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21001

95

cont. from prev. page (1/4 Cor. Secs. 3 and 10)

Doug. Co. Surveyor
Office
R.W. Smith and S.J.
Flause - Dec. 10, 1985
C.S. 62/29

New BTs - 8" D. fir double blazed and scribed "1/4 S10 CS BT" bears
S.32°W., 11.6 ft.
8" D. fir double blazed and scribed "1/4 S10 CS BT" bears
S.81 1/4°W., 13.0 ft.
7" D. fir double blazed and scribed "1/4 S3 CS BT" bears
N.25 1/2°E., 35.9 ft.
7" D. fir double blazed and scribed "1/4 S3 CS BT" bears
N.49°E., 28.5 ft.

Corner lies on a NW slope.

12/10/85

Carey Weatherly
For: International
Paper Co.
1986
C.S. 63/55

Section corner for sections 2, 3, 10 and 11

Found - 1969 Douglas County brass cap/iron pipe burried 60"
deep in road sidecast. Ren. #55
8" Hemlock stump, face visible, 2 Doug. Co. tags, N.31°W., 44.6 ft
(Other BTs either not found, or root wad dug out and rolled
downslope during road construction.

Set - 2" brass cap marked "T23S - R9W 3 | 2 1986 LS 1667" on 36" x 1 1/4"
10 | 11

I.P. 60" above Doug. Co. Brass cap.

New BTs - "X" marked on 24" Douglas fir bears S.78 1/2°W., 73.1 ft. to nail
in tree, IPCo. tag.

54" Douglas fir stump with IPCo. tag bears S.36°E., 46.4 ft.

1986

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
April 21, 1987
C.S. 62/45

Section corner for Sections 2, 3, 10, and 11.

Found - 1986 2 1/2" brass cap on a 1 1/2" dia. I.P. protruding 8" above
ground. Ren. #96

1969 DCSO brass cap not looked for. Buried 60" per Ren. #96.

10" maple now root wad, no blazes or scribing found, bears
N.89°E., 29.4 ft. (Rec. N.89°E, 29.0 ft. Orig. BT)

(no other original BTs found.)

5" maple now a stump thats pushed out of position, loose and
slid down hill (rec. N.75°W., 15.8 ft.) Per Ren. #8

(No other BTs per Ren. #8 found.)

8" now 8" dia. 5 ft. high hemlock stump with a partially healed
double blaze and illegible scribing visible bears N.31°W.,

44.0 ft. (Rec. N.31°W, 44.6 ft. per Ren. #55)

(No other BTs per Ren. #55 found.)

24" now 29" dia. D. fir blazed with "X" and a small blaze with
line tag below bears S.78 1/2°W., 73.1 ft. Ren. #96

54" dia. 4 ft. high D. fir stump bears S.36°E., 46.4 ft. Ren. #96.

New BTs - 54" dia. 4 ft. high D. fir stump (per Ren. #96), we set a boat
spike stamped "BO 1" through BT tag on top, bears S.36°E.,
46.4 ft.

8" hemlock double blazed and scribed "T23S R9W S3 CS BT" bears
N.76 1/2°W., 79.0 ft.

Corner lies on a steep east slope approx. 15 ft. east of the east edge
of a dirt logging road.

4/21/

Closing Corner for Sections 24 and 25.

Found - 1" iron post with 2 1/2" brass cap. Doug. Co. Ren. #91
The monument was tipped down hill (SE ±2 ft. and under debris
from logging operation.

±70" D. fir, 36.0 ft. bark scribing visible.

13" hemlock, 17.7 ft. two small faces, not yet healed scribing
visible.

? " maple in group of 3 or 4 has broken off at ground level - no
attempt made to measure.

±30" W.R. Cedar now a snag 25 ft. tall, it has slipped down the
hill ±20 ft. (it is still upright but leaning to SW), it will
probably slide farther down the hill and wipe out the monument
sometime in the future. No measure taken.

Set - We reset the County monument upright, the bottom had not moved. No
attempt was made to find the chiseled + in bedrock.

Set 6 ft. steel post with USFS attention sign 1.2 ft. west of mon.

The corner is on a very steep (±85%) SE slope. It is ±70 ft. from creek
bottom and on the edge of a recent BLM clearcut, (Unit #2 Old Camp Timber
Sale).

Steven P. Ness
L.S. #811
Dec. 28, 1989
C.S. 63/104

98