

Douglas County Surveyor's Record of
Government Corners Renewed

23

T. S.

10

R. W. W. M.

1/4 Corner between Sections 25 & 30, R9W. & R10W.

I find that in the construction of the BLM. road, the 2 original BTs had been destroyed. The 3/4 inch iron pipe had been bent over, but still in place. I straightened out the pipe & added the "cattle guard" as a B.O. as follows:

A B.O., the S.W. corner of the concrete cattle guard base bears, N.47 1/2°E., 8.8 ft.
Set - 3/4 inch iron pipe from 2 original Gov't BTs. as follows:
A Fir snag bears N.80°E., 9.5 ft. (scribing visible).

New Bearing Trees:

A Fir 12" in diam. bears N.78 1/2°E., 61.2 ft. BLM tag on face also scribed.
A Fir 16" in diam. bears N.56°W., 44.2 feet.

*FD OK 5/11
M 113-34 AFB
FOOK 4/14
M 126-31
T. HOS*

Clifford A. Stephens
Survey for Coos Head Timber
Sept. 12, 1957
C. S. File No. 42/299

8

Section Corner common to Sections 9, 10, 15, & 16.

Original: Post (found, down and rotted, scribed 9,10,15,23S and portion of T, 16 R10W visible), from which a:

6" Fir bears N. 20°E. 34 lks.; now 18" dead tree, scribes S10 visible. Also (not orig.) scribed 2 10 R BT visible above original face.
10" Fir bears S. 39°W. 30 lks.; now 35", face unexposed.
8" Fir bears S. 52°E. 32 lks.; now 24", face unexposed.
6" Fir bears N. 28°W. 23 lks.; now 27", exposed by unknown parties,
Scribes T23 visible.

Restored: Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T23S R10W S9 S10 S15 S16 1957 RS 359, 33 inches in ground, in mound of stone, & from which a: 26" Fir bears N. 69°E. 31.3 ft.; scribed T23S R10W S10 BT.
27" Fir bears N. 6°E. 26.4 ft.; scribed RS 359.
Oregon State Board of Forestry metal location poster on 27" Fir N. 6°E. 26.4 feet.

Elbert Driver, Engineering Aide
Ore. State Bd. of Forestry
Witnesses: Bob Banks, Derald Timmons, & Dick Rugh
Sept. 13, 1957
C. S. File No. 42/314

9

Section Corner common to Sections 11, 12, 13, & 14.

Found - Rotted base of stump that checks bearing & distance for Orig. S. E. BT. Also find all BT's. scribed by State 1933-1934.

The S. W. BT. now 36" Stump only shows good scribing.
Find 30" now 36" Fir N.78°W. (State N.48°W.) 21.7 ft., shows good scar. I do not open.

Find 30" now 36" Fir N.65°E. 5.0 ft., shows good scar, part of face open, scribing visible.

Also find 4" x 4" scribed stake at Corner.

Set Brass Cap at corner marked: S11/S12 T.23S., R.10W., County Surveyor's Office, 1958
S14/S13

New BTs.: 18" Fir bears S.44 1/2°W. 73.5 ft. scribed S14 T23S R10W CS BT.
18" Maple " S.71°E. 10.0 ft. scribed S13 T23S R10W CS BT.

RE-RENEWED SEE CORNER NO. #115

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blom
Feb. 11, 1958
C. S. File No. 49/63

10

1/4 Section Corner to Sections 14 & 13.

Found - 4" x 4" Sq. & scribed Stake at Corner and both BTs. as scribed by State. No trace of original BTs. can be found.

This Corner proportioned in by State.

Find State's 15" now 30" Hemlock, open face shows good scribing., bears S.65°E. 22.0 ft. (State S.25°E. 22.0 ft.)

10" now 18" Alder Snag, checks State's bearing & distance.

Set Brass Cap alongside Sq. Stake marked County Surveyor's Office, 1958, 1/4 S14/S13 T23S R10W.

I reblaze & rescribe 30" Hemlock S.65°E. 22.0 ft. 1/4 S 13 CS BT.

I blaze & Scribe 10" Hemlock N.24°W. 21.0 ft. 1/4 S14/S13 CS BT.

*FD OK 9/83
G. MILLER
M 95-55*

Ore. State Bd. of Forestry
By Elbert Driver
Wit: Bob Banks & Ron Witha
Sept. 9, 1957
C. S. File No. 42/331

11

Section corner common to Secs. 1 & 2.

Orig.: Post (now missing) from which a:

8" Fir bears S.25°E. 28 lks., now 29", exposed portion of scribe S, (bearing is S.38°E.)

24" Fir bears S.88°W. 46 lks., now 40", bark scribes T23S R10W S2 BT visible.

Retracement by Levi Walker, 1906, Post (found, rotted & down, scribed T23S R10W S1 & 2 visible)

Restored: Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T22S R10W S36 T23S R10W S1 S2 1957 RS 359," 33 in. in ground, & from which a:

*FD OK PER BAKER
APRIL-87 M104-9*

12

(cont. next page)