

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 10 R. W. W. M.

KOYE-CHAPMAN CO., EUGENE, ORE. 21881

57

1/4 Corner to Sections 12 & 13.

Found - Ref. Hub-also tack in stake nailed to 60" Fir-as marked on reference notes. (Ren. # 30)
Measured out on line 109.51 ft. (51.35 - 19° 37' =48.37 to Hub Set) 64.03-25°07'=57.98 to tack in road) & 3.16 Lev. to corner. Both S.E. trees now gone. Original S.W. tree now gone. Stump of original N.W. tree found, but no scribing.

Set - Brass Cap mkd: "County Surveyor's Office 1964 T 23 SR 10 W
1 S12"
4 S13

Cap set level with present ground surface, approx. 3 ft. N.W. of N.W. edge of traveled portion of County Road, as it exists at present.

In excavating for setting cap found iron rod set by Frear 28" below present ground surface-set cap over iron rod.

New BTS: 11" Doug. Fir S 76° W. 61.4 ft. Mkd: "1/4 S 13 CS BT"
12" Maple N. 77 1/2° W 25.0 ft. Mkd: "1/4 S 12 CS BT".

RE-RENEWED CORNER NO. #62

58

1/4 Corner to Section 26 & 35.

Found - Doug. Fir (now 42" diam.) N. 65° E. 44.0 ft. Scribing visible (Ren. # 20)
Doug. Fir (now 32" Diam.) N. 39° E 39.0 ft. Face open, but Pitched over.

Set - Brass cap mkd: "County Surveyor's Office 1964 T 23 SR 10 W
1 S26"
4 S35

New BT: 6" Hemlock S 26° W 24.7 Ft. Mkd: "1/4 S 35 CS BT"

Note: Found old, rotted cedar stump scribed "1/4 S" on E. face S 33 1/2° W 28.2 ft., which I believe to be an original BT.-does not face right for call in government notes for BT.-No other old tree found to match it, even if bearing given is in wrong quadrant.

Corner as renewed by me, is rerenewal of corner as set by Oregon State Board of Forestry only.-not renewal of original corner.

Fd. OK
6-10/87
E. Miller
M 97-68

59

Corner to Sections 26, 27, 34 & 35. See also M 133-14

Found - At corner badly rotted wooden stake-scribed. (Ren. # 19)
Hemlock (now 24" diam) S. 51° W 31.0 Ft. scribing visible on open face "3 23 RLOW"- face starting to decay.
Doug. Fir (now 42" diam.) N. 8 1/2° E 33.0 ft.-very plain scars visible.
Red Cedar (now 27" diam.) N. 4° W (not N. 23°W) 5.0 ft.-scribing visible in not completely covered scar.

Set - Brass Cap mkd: "C.S. 1964 23-10 27/26"
34/35

New BTS: 24" Red Cedar S 10° E 22.4 ft. Mkd: "T 23 SR 10 W S 35 CS BT"
24" Hemlock S 37° W. 33.9 ft. Mkd: "T 23 SR 10 W S 34 CS BT"
Corner lies on very steep N.W. slope approx. 300 ft. South of Creek.

60

Section Corner to Sections 25, 26, 35, & 36.

Found - At corner C. S. Brass Cap set in 1957. (Ren # 21-#26)
3 of the original BTS are still alive & in good condition. Viz:
60" Doug. Fir N. 25° E 20.5 ft.
50" Doug. Fir S. 50° E 19.8 ft.
48" Doug. Fir S. 89° W 17.8 ft.

Distances all to face of tree. The N.W. tree is now down.

New BT: 8" Hemlock N 22° W 36.0 ft. Mkd: "S 26 CS BT"

Found - 1 3/4" x 1 3/4" angle iron driven in ground S 3° E 24.5 ft. from Brass Cap.

Milo Godfrey, Deputy
Wm. Stoffel, Mike Darby, Mike Stone
May & June, 1964
C. S. File No. 49/60