

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S. T. S. R. 10 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

1/4 Corner on South Side of Section 2.

61

Orig.- Fir Post (now missing, point falls in cat road) from which:  
16" Fir bears S.44°E. 21 lks.; now 27" stump, scribes 1/  
visible on exposed face.  
12" Fir bears N.34°E. 13 lks.; now 17" stump, pushed over  
in place, portion of scribes 1/4 visible.  
Set - 1 1/2" x 36" gal. iron pipe with 3" br. cap mkd: "Ore.St.Bd.  
of Forestry 1/4 S2 1957 RS359," 33" in ground, in mound of  
stone & from which a:  
40" Fir bears N.20°E. 46.7 ft.; scribed 1/4 S2 BT  
36" Fir bears N.65°W. 36.5 ft.; scribed RS359.

Ore.St.Bd.Forestry  
Arnold G. Gibson  
Elbert Driver  
January 1958  
C.S.File No. 42/331

1/4 Corner to Sections 12 and 13.

62

Found - Frear's Iron Rod 28" below surface of ground, See Ren. #30.  
BT's. as recorded in Ren.#57, as follows:  
11" D. Fir, Alive, S. 76° W. 61.4 ft., scribe visible on  
pitched blaze.  
12" Maple, Alive, N. 77 1/2° W. 25.0 ft., scribe visible on  
unhealed blaze.  
Reset - 1964 Brass Cap, Ren. #57, over Iron Rod, brass flush with  
surface of ground. Set Steel Fence Post alongside.  
Note - Corner lies 3 ft. N.W. of N.W. edge of asphalt on County Road.  
7/31/73 - Fo. O.K. Y.R.T. C.S. 56/35

Meander Corner Sections 11 and 12.

63

Found - Corner Tree & BT's. as recorded in Ren. #47, as follows:  
20" Laurel Corner Tree, alive & scribe "MC S12/11 CS" visible  
on unhealed blaze.  
36" Fir N. 40° W. 17.7 ft. Alive. Bark scribe visible.  
33" Fir Snag, decaying, N. 20° E. 15.2 ft., bark scribe  
visible below scar.  
Set - 3/4" Iron Rod under Corner Tree.  
New BT: 14" Laurel N. 3° E. 4.6 ft. mkd. MC S12 CS BT.  
Note - This corner lies near water's edge on steep, southerly slope.

Vernon "Ray" Tracy  
Jack Heritage & Elmer West  
December, 1966  
C. S. File No. 49/63

Meander Corner to Sections 11 and 12.

64

Found - 4"x4"x10" Fir Post, nearly rotted off at ground, &  
BT's. as recorded in Ren # 48, as follows:  
32", now 34" Fir, alive, S. 19° W. 39.0 ft., prev. opened,  
blaze well pitched over.  
16", now 18" Fir, Alive, N. 78° E. 28.5 ft., shows good scar.  
Do not open.  
Set - Brass Cap at Cor. Mkd: County Survey's T 23 S R 10 W  
Office M.C. S 11/S 12  
1966  
Note = This corner lies approx. 10 ft. south of water's edge  
on steep, N.W. slope.

South 1/4 Corner to Section 35.

65

Found - 5" fir mkd. 1/4 on N. face, now 6" Fir Snag, just a ring of bark.  
Scribe visible, but on south not north face.  
36" fir south 27 lks, now 40" fir--bark scribed--visible.  
15" fir N. 50° E. 11 lks., now 20" fir snag--bark scribed--vis.  
Removed shell of bark 1/2 ft. above ground and drove a 4' x 3/4" pipe  
in the ground at the center of bark shell for new corner  
and re-referenced with "W" nails and Weyerhaeuser tags:  
40" fir S. 1° W. 18.0 ft.  
22" fir N. 18° E. 12.0 ft.

Weyerhaeuser Co.  
By Donald L. Peel  
March, 1967  
C.S. File No. 55/30

Standard Corner common to Secs. 34 and 35, T23-10W.

Found - GLO Survey Record - Post -- Gone.  
36" fir N.15°E. 37 lks, now 30" fir stump--nothing visible  
probably bark scribed.  
20" fir S.58°E. 17 lks, markings destroyed in 1896--now 26" fir  
snag--face visible.  
20" fir S.61°W. 24 lks, markings destroyed in 1896--now 32" fir--  
face visible.

(continued next page)