

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T.S. 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy & Clete Putnam  
October 1961  
C. S. File No. 52/42

Section Corner to Sections 28 - 27 - 33 - 34. 13  
Found - Mound of Rocks - Also Fir Tree, now 24", N.68°E. 22.4 ft.,  
(instead of N.66°E.) 22.4 ft., shows good scars. Tree in good cond.  
Chinq., now 8", S.29°E. 5.3 ft. (instead of S.34°E.) 5.3 ft.  
face badly rotted but scribing "BT" visible.  
Pine Tree, instead of Fir, now 24", S.42°W. (instead of S.41°W.)  
17.8 ft., shows scars. Blaze & rescribe this tree "T24SRLWS33CSBT".  
N. W. BT. not found.

Set - Brass Cap Mkd: County Surveyor's Office, 1961  
T24S RLW S24 | S27 #158  
S33 | S34

New BT's: 17" D. Fir N.32°W. 24.3 ft. Mkd: T24S RLW S28 CS BT.  
13" D. Fir S.47°E. 26.3 ft. Mkd: T24S RLW S34 CS BT.

----- MAY 1970 - FOUND O.K. V.R.T C.S. 54/27

Section Corner to Section 18 - 17 - 19 - 20. 14  
Found - Rock as called for in Gov't notes, It has slid down hill  
approx. 2 ft. from corner.  
Fir Tree, now 26", N.47°W. 9.9 ft. Good scars. Has been partially  
chopped open, Scribing visible "S18".  
Fir Tree, now 24", S.63°E. 15.8 ft. Shows good scars-Did not chop opn.  
Fir Tree, now 20", N.70°E. 29.0 ft., shows good scars-Didn't chop opn.  
Dead Fir Snag S.45°W. 13.2 ft. scribing Visible "4S RLW S19".

Set - Brass Cap Mkd: County Surveyor's Office, 1961  
T24S RLW S18 | S17  
S19 | S20 Alongside.

New BT: 8" Hemlock S.49°W. 8.5 ft. Mkd: T24S RLW S19 CS BT.

Section Corner to Sections 7 - 8 - 18 - 17. 15  
Found - Rock as called for in Gov't notes, lying on top of ground,  
approximately 3 ft. from corner position.  
Fir Tree, now 33", S.76°W. 15.2 ft., shows good scar-Didn't chop opn.  
Fir Tree, now 30", N.31°W. 33.3 ft. (instead of 34.3 ft.) shows  
good scar. Did not chop open.  
Fir Tree, now 11", S.40°E. 5.9 ft., good scribing visible in open  
Remnant of Fir Stump N.65°E. 22.4 ft. scar.

Set - Brass Cap Mkd: County Surveyor's Office, 1961  
T24S RLW S7 | S8  
S18 | S17

Place Orig. Rock alongside, Built Rock Mound around corner.

New BT: 8" D. Fir N.73°E. 30.3 ft. Mkd: T24S RLW S 8 CS BT.

1/4 Corner Witness Corner to Sections 23 and 26. 16  
Found - 22" Fir tree N.35°W. 24.4 ft., cut open & fd. good scribing "S".  
17" Fir tree, S.55°E. 2.0 ft., uprooted & down. Cut open &  
found good scribing "4".

Note - Corner position & S.E. tree are right in edge of stream at  
Forks of Canton Creek. Impractical to set Brass Cap in  
this position.

Set Wit. Cor. to 1/4 Cor. 70 ft. South of Corner position. Set Iron  
Pipe with Brass Cap Mkd: "County Surveyor's Office, 1961  
T24S RLW WC 1/4 S23 Made Rock Mound.

New BT's: 16" Hemlock S.49°E. 21.5 ft. Mkd: S26S26 W.C./CS BT.  
The Orig. N.W. BT. bears N.9°W. 91.6 ft. Did not rescribe.

Section Corner to Sections 9 - 10 - 16 - 15. 17  
Found - Rock set in ground Mkd: as called for in Gov't notes.  
Cedar tree, now 40", S.40°E. 6.6 ft. scribing visible on  
rotting face "4R1". Reblaze & scribe this tree.  
W. Fir, now 30", S.38°W. 42.9 ft., shows 2 good scars.  
Tree in good condition. Did not rescribe.  
Cedar, now 16", portions of scribing visible in nearly closed  
scar. Tree nearly dead, N.32°W. 27.1 ft.

Set Brass Cap Mkd: County Surveyor's Office, 1961  
T24S RLW S9 | S10 Made Rock  
S16 | S15 Mound

New BT's: 20" Cedar North 19.8 ft, Mkd: T24S RLW S10 CS BT.  
7" Yew N.35°W. 5.8 ft. Mkd: T24S RLW S 9 CS BT.

FD. OK - T. S. H. E. U. M.  
11/20 M BT-55