

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 1 W. R. W. W. M.

ROSE-CHAPMAN CO. EUGENE, ORE. 97801

4/24/73
 See Report By
 S. Anderson in
 C.S. File 54/27
 For possible
 Discrepancies
 4/24/73

Vernon "Ray" Tracy
 V. Perron C. S. File No. 54/27

Section Corner to Secs. 25 & 36, T24-1W. & Secs. 30 & 31, T24-1E. 90

Found - Orig. 6", now 14" Fir, alive, S. 34° E. 14.5 ft., shows good scar. We Rescribe "T24S R1E S31 CS BT".

Orig. 12" Cedar, now 20" Hemlock Stump, S. 77° W. 23.8 ft., shows good scar.

Orig. 24", now 30" Cedar, alive, N. 40° W. 42.9 ft., scribe marks visible on nearly healed blaze. Rescribe "T24S R1W S25 CS BT".

Orig. BT. to N. E., down, shws. scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970

R	T 24 S	R
1	S 25 S 30	1
W	S 36 S 31	E

New BT's: 15" Hemlock N. 82° E. 39.9 ft. mkd: "T24S R1E S30 CS BT".

9" Cedar S. 8° W. 23.3 ft. mkd: T24S R1W S36 CS BT".

This corner lies near bottom of N. slope, approx. 40 ft. from flat bench to N. 4/12/70

1/4 Corner to Sections 15 and 22. 91

Found - 1962 C.S. Brass Cap & pipe, tipped over with rootwad of

Orig. N.W. BT. and Orig. S.W. BT., face. down. Ren. #25.

7", now 8" W. Fir, alive, N. 5° E. 31.2 ft., split with about 1/2 of upper blaze hanging loose with scribe marks, lower scar healed over.

RESET BRASS CAP IN PROPER PLACE.

New BT's: 6" W. Fir S. 25° E. 55.1 ft. mkd: "1/4 S22 CS BT".

10" D. Fir N. 73° E. 38.6 ft. mkd: "1/4 S15 CS BT".

This corner lies moderate S.W. slope approx. 100 ft. S. of ridge top, course S. E. 4/13/70

1/4 Corner to Sections 22 and 23. 92

Found - Corner Stone, in place, mkd: "1/4".

Orig. 24", now 30" D. Fir, alive, S. 84° E. 49.5 ft., shows good axe scar, tggd.

Orig. 42", now 46" D. Fir, alive, N. 53° W. 43.6 ft., shows good axe scar, we tag.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1970

T 24 S	R 1 W
1/4 S 22	S 23

(Set old Corner Stone Alongside)

New BT's: 8" Hemlock S. 35° W. 27.9 ft. mkd: "1/4 S22 CS BT".

14" D. Fir S. 81° E. 24.8 ft. mkd: "1/4 S23 CS BT".

This corner lies on moderate S. slope near foot of very steep, ascent to N. 4/13/70

1/4 Corner to Sections 22 and 27. 93

Found - Corner Stone, mkd: "1/4" at 1/4 Corner.

Orig. 6", now 7" Fir, 10 ft. high Snag, N. 27° E. 5.3 ft., prev. opened & shows "BT" scribe. We open higher & find "1/4 S" scribe.

Orig. BT. to S. E. gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970

T 24 S	R 1 W
1/4 S 22	S 27

(Reset Stone alongside)

New BT's: 10" D. Fir S. 45° W. 14.5 ft. mkd: "1/4 S27 CS BT".

8" Cedar N. 55° W. 8.1 ft. mkd: "1/4 S22 CS BT".

This corner lies on steep, east slope about 50 ft. from creek, course N.E. 4/14/70

Section Corner to Sections 26 - 27 - 34 - 35. 94

Found - Orig. 36", now 38" Fir, alive, N. 38° E. 25.1 ft., shows good scar, Wetag.

Orig. 48", now 54" Fir, alive, S. 68° E. 31.7 ft., shows good scar, we tag.

Orig. 10", now 15" Cedar, alive, S. 62° W. 32.3 ft., broken top, we open and find "S" scribe & reverse.

No trace of N. W. Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970

T 24 S	R 1 W
S 27	S 26
S 34	S 35

New BT's: 8" Hemlock S. 51° W. 35.5 ft. mkd: T24S R1W S34 CS BT.

20" Hemlock N. 89° W. 18.0 ft. mkd: T24S R1W S27 CS BT.

This corner lies on very steep, westerly slope, apprx. 75 ft. E. of creek. 4/14/70