

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

119

Center 1/4 Corner for Sec. 8
Set - 3/4" x 30" I. P.
A 40" S. Pine, N.15°E., 18.0 ft. to a R.R. spike.
A 24" D. Fir, S. 5°W., 50.3 ft. to a R.R. spike.

Nick Juliano
(Triangle Engineering)
For: Weyerhaeuser Co.
Oct. 1976
M 62 - 35

120

1/16 Corner for Sec. 33 and Sec. 4 of T25-1
Found - 3/4" x 36" steel tube with alum. cap stamped "USPC property
cor." T25S R1W $\frac{33}{4}$ E 1/16 RE 4287
Steel tube is bent, cap is 16" above ground. Area disturbed by logging.
An 8" Red Cedar, now a stump, bears S.71°W., 14.2 ft. (Rec.
S.70°W., 9.7 ft.) Stump scribed "BT"
NE BT not found.

Renewal:

Due to the condition of the monument (bent & loose) and the tie
to the SW BT, I determine that the monument has been disturbed.
I remove the corner monument and place in the position where I
found it, an I.R. 3/4" x 30" long, 27" in the ground.

I set - monument, marked as noted at corner as determined by T.E.
Shrum Jr., M 32 - 62,

From Which: 8" Red Cedar stump bears S.70°W., 9.7 ft.
3/4" I.R. bears N.80°E., 4.3 ft.

New BT: Set 3/8" x 12" star drill 10" deep at center of a 48" Hemlock
stump. Marker bears S.41 1/2°W., 31.9 ft. Stump blazed and
scribed "1/16 S4 CS BT" Note: Star drill used is a 1/2" drill,
shank portion measures 3/8".

12/9/76

Larry E. Monrean &
P. L. Earle
Do. Co. Surveyors
Office
Dec. 9, 1976
C.S. 59/26

121

1/4 Corner for Secs. 19 and 20
Set - 5/8" x 40" Iron rod and alum. cap.
BT's - 42" Fir, N.28 1/2°E., 19.8 ft. OBT
44" Fir, S.56°W., 36.3 ft. OBT

Howard W. Johnstone
For: Roseburg Lumber
March 31, 1977
M 65 - 15

122

1/4 Corner for Secs. 20 and 29
Set - 5/8" x 40" Iron rod and Alum Cap
BT's - 12" Cedar bears N.3°W., 19.1 ft. OBT
27" Fir bears S.65°E., 9.9 ft. OBT

3/31/77

123

1/4 Corner for Secs. 30 and 31
Found - 2" square wood post at 1/4 corner. Post not orig. monument.
Orig. 16" now 24" Cedar bears N.22°E., 9.2 ft. (rec. N.27°E. hits
edge of tree near face.) Blaze previously chopped out, rotted.
No scribing found.
A 8" now 12" Hemlock, is dead and partially uprooted. Tree bears
S.86 1/2°E., 8.6 ft. Blaze previously partially opened scribed
"1/4", we open more blaze and find scribed "S".
Set - 1" x 30" Iron pipe with brass cap attached stamped :
"Douglas County Surveyor" T 24 S R 1 W
1977 $\frac{1}{4}$ S 30
S 31
New BT's- A 7" Hemlock bears S.53°W., 24.0 ft. Tree blazed and scribed
"1/4 S31 CS BT".
A 11" Hemlock bears N.25°W., 30.6 ft. Tree double blazed and
scribed "1/4 S30 CS BT".

5/4/77

124

1/4 Corner for Secs. 19 and 30.
Found - Orig. Basalt stone at 1/4 corner. Stone is 16" x 14" x 12" firmly
set and marked "1/4" on northerly face.
BT's- Orig. 12" Fir now an uprooted snag bears S.52°E., 3.3 ft. Tree
has healed scar with the face rotted out, no scribing found.
Orig. 12" now 30" Fir and uprooted bears N.19°W., 26.4 ft. Tree
has well healed blaze. We do not open for scribing.
Set - 1" x 30" Iron pipe with brass cap attached marked:
"Douglas County Surveyor" T 24 S R 1 W
1977 $\frac{1}{4}$ S 19
S 30

Larry E. Monrean, Doug. Co. Surveyors Office
R. B. Kimberling
S. J. Flouse - P. L. Earle
May 4-5, 1977
C.S. 59/34

Set original stone along north edge of cap.