

Douglas County Surveyor's Record of  
Government Corners Renewed

T 24 T. S. R 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

146

1/4 Corner for Secs. 31 and 32

Found - Iron pipe with 1970 County brass cap, properly mkd., protruding 18" above ground. Ren. #102

DID NOT find original basalt corner stone.

Orig. 10" fir, now 26" dia., bears N.52°W., 11.2 ft. Partially healed blaze with scribing visible.

42" fir stump bears N.11°E., 55.8 ft. (Rec. 57.1 ft.) No scribing visible. Ren. #102

Set - Monument was protruding 18" above ground on steep rocky hillside. We made a mound of rocks approx. 5 ft. x 4 ft. around monument to protect it.

New Accessories:

Set a 8" x 1/2" spike in a 42" fir stump, bears N.11°E., 55.0 ft. Spike set through a "Doug. Co. Surveyors Off." bearing tree tag in pitch ring of stump. (Stump is a BT from Ren. #102)

A chiseled "X" in face of rock bluff, bears S.48°W., 14.5 ft.

Note: Corner lies on steep east slope approx. 300 ft. east of BLM Rd. #25-1-5.4. Corner lies in cutting line. A clear cut is to the east of corner.

10/18/83

Southwest corner of Section 31.

Found - 27" fir, N.64 1/4°E., 44.2 ft. OBT.

17" fir, N.18 1/4°E., 27.1 ft. (1951 Cadastral resurvey)

8" chinquapin, S.13 1/4°E., 13.2 ft. OBT

Landing construction eliminated these BTs after the corner was referenced out. Monument and BTs were in the middle of a proposed landing to be constructed in a logging clear cut unit. I referenced out the B.C. and after the landing was built and the unit logged:

I re-set - the Brass Cap from my references and scribed 2 BTs to the west which is the only area with remaining timber.

Brass cap marked: U.S. General Land Office Survey"

(Cap was reset in large mound of rocks.)

T24S  
R1W  
S 31

T25S R2W  
S 1

1951 191

New BTs - 9" D. Fir, S.45°W., 102.3 ft. scribed S1 L 28 T25S R2W BT.

26" S. Pine, S.80°W., 105.9 ft. scribed S1 L28 T25S R2W BT.

Note: Corner sets on a step landing at end of spur road and at base of cut slope for landing. Bts are at toe of road fill slope.

9/24/85

1/4 Corner for Sections 12; and Sec. 7 of T.24-1E.

Found - A 24" x 16" x 10" basalt stone marked "1/4" on west face.

Stone is tipped out of position 1.5 ft. North. (Orig.)

30" now 30" dia. D. fir snag with a single fully healed blaze bears S.70°E., 9.9 ft. (agrees with record).

20" now 24" dia. 1 ft. high rooted D. fir stump, No blaze, or scribing found, bears S.64°W., 43.9 ft. (Rec. S.64°W., 44.9 ft. is a slope measurement.)

Set - Orig. plumb position of orig. stone referenced, stone is removed and a 2 3/8" brass cap on a 1 1/4" x 32" I.P. is set in its place protruding 1" above a 2 ft. dia. 1 ft. tall mound of stone set along South edge of I.P. with "1/4" mark facing West. Cap mkd. "Douglas County Surveyors T24S 1/4 R1W S12 S7 R1E 1986 Office".

New BTs - 8" D. Fir double blazed and scribed "1/4 S7 CS BT" bears N.69°E., 14.8 ft.

4" I. Cedar double blazed and scribed "X BT" bears S.22 1/2°E., 7.0 ft

11" D. Fir double blazed and scribed "1/4 S12 CS BT" bears S.45 1/2°W., 32.5 ft.

11" D. Fir double blazed and scribed "1/4 S12 CS BT" bears N.09 1/4°W., 9.0 ft.

Corner lies approx. 250 ft. North of the NW corner of a new steep Westerly facing clear cut approx. 2 miles along USFS Rd. 2300-600.

148

Larry E. Monrean  
Deputy, Doug. Co.  
Surveyors Office  
Randall Smith  
Oct. 18, 1983  
C.S. 62/7

Howard Johnstone  
For: Roseburg Lbr.  
Company  
Sept. 24, 1985  
C.S. 63/26

Doug. Co.  
Surveyors Office  
Randall Smith  
Stephen Flause  
July 2, 1986  
C.S. 62/37