

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 97501

27

Sec. Cor. Common to Sections 13 & 24 only, T24-2W.

Set - Square Post from which a:

12" D.Fir Snag, Orig. BT. with bark scribes visible, bears N.31°W. 6.6 feet. 34

24" D.Fir, Orig. BT. with a bark scribe visible, now a blowdown tree, bears S.46°W. 27.0 ft.

New BT's: 20" D.Fir, I scribed "T24S R2W S24 BT" bears N.88°W. 36.7 ft.

36" D.Fir, I scribed "T24S R2W S24 BT" bears N.7°E. 11.3 ft.

15" D.Fir, I scribed "T24S R2W S13 BT" bears N.15°W. 30.1 ft.

28

East $\frac{1}{4}$ Corner of Section 24, T24-2W.

Set - Square Stake from which a:

20" D.Fir, Orig. BT. with scribes visible, bears S.30°W. 12.5 ft.

16" Hemlock, Orig. BT. with old face, bears N.20°E. 9.2 ft.

New BT's: 60" D.Fir, I scribed "T24S S24 BT" bears S.78°W. 56.0 ft.

28" D.Fir, I scribed "T24S S24 BT", bears S.50°W. 72.6 ft. 37

Note - This corner is approximately 30 ft. west of 1191+65 on proposed BLM access road.

29

Section Corner to Sections 24 and 25 only, T24-2W.

Set - Square Post, from which a:

60" D.Fir, Orig. BT. with old face, but bark scribes, now missing, I newly scribed "T24S R2W S25 BT", bears S.59°W. 22.0 ft.

16" D.Fir, Orig. BT. set by McQuinn in 1883 with bark scribes visible, bears N.21°E. 24.2 ft. (Chapman & Nicklin in 1896 said this tree did not fit . . .)

12" Hemlock BT. set by C. & N., now missing.

38" D.Fir, I scribed "T24S R2W S24 BT" bears N.8°W., 37.7 ft.

30

$\frac{1}{4}$ Corner to Sections 7 and 8.

Found - 6" Cedar Snag S. 84° E. 24.4 ft., scribing visible.

7" Hemlock, snag on ground & 10' downhill from call distance, N. 52° W. 17.2 ft.

Set from bearing & distance of 6" Cedar Snag.

BT's: 16" Hemlock N. 69° E. 63.4 ft. "W" Nail & Plate.

18" Cedar S. 64 $\frac{1}{2}$ °E. 73.2 ft. "W" Nail & Plate.

Dec. 10, 1965

31

Sec. Cor. to Secs. 18 & 19, T24-2W. & Secs. 13 & 24, T24-3W.

Found - 30" Cedar, now 44", S.29°W. 24.8 ft., face part grown over, no scribing.

10" Hemlock, now 13", N.45°W. 6.6 ft. face open, part rotten, scribing visible.

20" Cedar, now 42", N.82°E. 15.2 ft., face part grown over, no scribing.

20" Hemlock, now 32", S.70°E. 23.1 ft., tree windthrown, face closed.

Set 1" x 30" Aluminum Pipe, from which:

Orig. 42" Cedar N.83°E. 13.6 ft., "W" Nail & Plate.

Orig. 44" Cedar S.29°W. 24.0 ft., "W" Nail & Plate.

36" Hemlock N. 88° W. 25.3 ft. "W" Nail & Plate.

68" Fir N. 28° E. 35.9 ft. "W" Nail & Plate.

Oct. 8, 1965

32

Sec. Cor. to Secs. 7 & 18, T24-2W. and Secs. 12 & 13, T24-3W.

Found - 38" Fir N.40°W. 24.4 ft., slide, no evidence.

14" Maple N.15°E. 27.2 ft., Stub 5' high "W" Nail but no scribing.

52" Fir S.77°E. 47.5 ft. windthrow root wad & dist., no reference.

34" Fir S.59°W. 33.0 ft., slide, no evidence.

Set - 1 $\frac{1}{2}$ " x 42" Iron Pipe, from which:

14" Maple Stub N. 15° E. 27.2 ft. (Orig. BT) "W" Nail & Plate.

36" Fir Stump N. 56° W. 37.2 ft. "W" Nail & Plate.

NOT ENOUGH EVIDENCE TO RENEW - ~~MAR 1968~~ V.R.T. 5/127 Dec. 2, 1965

Bruce A. Shaner
For Evans Products Co.
April - May 1965
Map File M 29 - 65

C.S.
File
No.
53/110

Weyerhaeuser Company
Donald H. Jordan, Surveyor
March 1966
C. S. File No. 53/111