

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 2 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

66

$\frac{1}{4}$ Corner to Sections 21 and 22.
Found - Mound of Stones, apparent Corner Stone, broken, no marks found.
Orig. 12", now 18" Cedar, alive, N. 22 $\frac{1}{2}$ ° E. 7.9 ft., now healed blaze.
We Rescribe " $\frac{1}{4}$ S 22 CS BT".
Orig. 18", now 24" Fir, alive, N. 25° W. 19.8 ft., shows good scars.
We Rescribe " $\frac{1}{4}$ S 21 CS BT".
Set - Brass Cap 12" in ground & built mound of stone around Pipe & Mkd:
County Surveyor's Office, 1969
T24S $\frac{1}{4}$ S 21 | S 22 R2W
New BT: 7" Yew S. 81° W. 27.3 ft. mkd: " $\frac{1}{4}$ S 21 CS BT".
Weyerhaeuser Ref: 36" Fir Stump S. 78° E. 3.0 ft. to "W" Nail.
This corner lies on very steep south slope approx. 420 ft. N. of creek.

67

Section Corner to Sections 29 - 30 - 31 - 32.
Found - 1951 Cad. Brass Cap, in place as determined from remaining BT.
48" Fir sawed stump S. 74° E. 16.5 ft., fragmentary scribe on
burned blaze. Rescribed "T24S R2WS32CS BT".
New BT: 16" Hemlock S. 21° W. 105.2 ft. mkd: T24S R2W S31 CS BT.
Found Weyerhaeuser BT: 48" Fir Stump S. 77° W. 42.9 ft. This also Orig.
Bearing Tree, no scribe found, badly burned.
This corner lies on bench in dense fir reproduction, greasewood &
vinemaple brush.

68

$\frac{1}{4}$ Corner to Sections 30 and 29.
Found - Orig. 12", now 15" Hemlock Stump, S. 75° E. 34.3 ft., scribe marks
visible.
Hole where N. W. Orig. Bearing Tree should have been.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 2 W
(6' steel fence post alngsd) Office, 1969 $\frac{1}{4}$ S 30 | S 29
New BT: 40" D. Fir N. 45° W. 151.6 ft. mkd: " $\frac{1}{4}$ S 30 CSBT".
There being no trees in sec. 29, we set $\frac{3}{4}$ " I.R. N. 70° E. 15.0 ft.
This corner lies on moderate, changing to steep, northerly slope.

69

$\frac{1}{4}$ Corner to Sections 29 and 32.
Found - 1951 Cad. Brass Cap, firmly set and in place.
Orig. 40" Fir (Snag) S. 11° E. 23.1 ft., bark scribe still visible.
56" Fir Stump S. 42° 45' E. 24.4 ft., scribe visible.
Set - 6.0 ft. steel fence post alongside Brass Cap.
There being no trees close, we set: $\frac{3}{4}$ " I.R. North 20.0 ft.
 $\frac{3}{4}$ " I.R. West 5.0 ft. from $\frac{1}{4}$ Cor.
This corner lies on N. E. slope in old logged area.

8/21/69

70

Sec. Cor. to Secs. 12 & 13, T24-2W and Secs. 7 & 18, T24-1W.
Found - Orig. 24", now 30" Fir, dead, N. 75° E. 17.2 ft., bark scribe
visible, poor condition.
Orig. 30", now 34" Fir, dead, S. 81° E. 19.8 ft., frag. bark scribe visible.
Orig. 32", now 36" Hemlock, alive, S. 75° W. 30.4 ft., scribe visible on
unhealed blaze. We Rescribe: "T24S R2W S13 CS BT".
Orig. 20", now 24" Fir Snag, N. 61° W. 36.3 ft. (Rec. 33') bark scribe vis.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 24 S R
Office 2 S 12 | S 7 1
1969 W S 13 | S 18 W
New BT: 16" Hemlock N. 46° E. 30.0 ft. mkd: T24S R1W S 7 CSB T.
10" Hemlock N. 6° W. 22.3 ft. mkd: "T24S R2W S12 CS BT".
22" Hemlock S. 43° E. 59.5 ft. mkd: T24S R1W S18 CS BT.
This corner lies on steep northerly slope 90 ft. S. of creek, course E.

71

$\frac{1}{4}$ Corner to Sections 15 and 22.
Found - Orig. 6", now 7" Vinemaple, dead, N. 5° E. 23.8 ft., bark scribe vis.
Do not find I.P. called for in Ren. #7 due to logging.
12", now 13" Hemlock, alive, N. $\frac{1}{2}$ ° W. 24.2 ft., good condition,
scribe visible on nearly healed blaze.
24", now 24" Hemlock, alive, S. 85 $\frac{1}{2}$ ° E. 65.2 ft., scribe visible.
Set - Brass Cap in Cat Fire Trail Mkd: County Surveyor's T24S R2W
Office $\frac{1}{4}$ S 15
1969 S 22

8/27/69

Vernon "Ray" Tracy
Jack Heritage & V. Perron
August, 1969 C.S. File No. 54/27

RE-RENEWED, #117

FD. OK. 3/17/92
B.L.M.
C.S. 63/140