

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 24 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97301

104

C O N T - - - -
Glen Mc Chesney, for:
Weyerhaeuser Co.
June 10, 1977 (filed 12/80)

Accessories added this date:
54" Fir, N.40°E., 7.5 ft. (orig. BT) with "W" nail and plate.
40" Fir, S.6 1/2°W., 25.5 ft. with "W" nail & plate.
6/10/77

105

L. Wilson - R. Rice
For: Weyerhaeuser Co.
April 18, 1977
Filed 12/80)
C.S. 58/8

1/4 Corner for Secs. 28 and 29
Found - No trace of 1883 cedar post.
Orig. 24" now 38" Hemlock, scribing visible, bears N. 44 1/2°E.,
10.7 ft. from 1951 GLO brass cap. to center of BT.
Orig. 18" now 32" Fir, scribing visible, bears N. 53 1/2°W.,
21.1 ft. from 1951 GLO brass cap to center of BT.
1951 brass cap, in place.
Drove 2" fir post alongside brass cap.
Added "W" nails and Weyerhaeuser plates to BTs.
4/18/77

106

Glen Mc Chesney
For: Weyerhaeuser Co.
Jan. 21, 1980
C.S. 58/8

Section corner for Sec. 19, 20, ~~29~~¹⁷ and ~~30~~¹⁸.
Found - No trace of 1883 Yew post.
Orig. 12" now 30" Fir, healed over faces, bears N.60°E., 11.2 ft.
(Rec. N.50°E.)
Orig. 10" now 18" Fir, healed over faces. bears S.05°E., 23.1 ft.
face measurement. (Rec. S.40°E.)
Orig. 18" now 26" down fir, rotted. Axe work and one scribe mark.
bears S.56°W., 36.3 ft. to root hole (Rec. S.35°W.)
Orig. 36" now 38" Fir stump, rotted but evidence of old face
bears N.03°W., 9.9 ft. face measurement. (Rec. N.05°W.)
Bearings and distances are to a 1" x 30" Monel pipe set by GLO.

Accessories added this date:
30" Fir, N.59°E., 10.5 ft. (1883 BT) with "W" nail and plate.
38" Fir, bears S.86°E., 29.8 ft. with "W" nail and plate
18" Fir, S.06°E., 23.0 ft. (1883 BT) with "WR nail and plate.
12" Yew, bears N.80°W., 18.6 ft. with "W" nail and plate.
1/21/80

107

Glen Mc Chesney
For: Weyerhaeuser
July 13, 1976
(Filed 12/80)
C.S. 58/8

North 1/4 Corner for Sec. 4 of T.25-2.
Found - 1951-63 GLO brass cap.
42" Hemlock, (1951) scribing visible. This tree will be removed
by current road construction. Tree bears N.11 1/4°W., 27.4 ft.
14" Red Cedar, (1963), scribing visible bears S.35°W., 52.6 ft.
Tree is at westerly edge of R/W but should survive road
construction.

BRASS CAP TO BE RESET AFTER ROAD CONSTRUCTION.
Accessories added this date:
48" Fir, S.49°E., 71.2 ft. with W nail and plate.
40" Fir, S.71°W., 69.0 ft. with W nail and plate.
38" Fir, N.36°W., 72.9 ft. with W nail and plate.

7/13/76
108

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
Debbie Stewart
Aug. 12, 1981
C.S. 61/27

Closing Corner for Secs. 19 and 30 only, T.24-1
Found - DCSO brass cap properly marked from 1966 Ren. #35. The marks
AM were added at a later date than the other marks.
An unrecorded BLM brass cap, 1981, bears N.89°W., 5.8 ft.
Orig. 12" now 34" Fir with opened blaze showing 19/30 BT bears
N.19°E., 8.0 ft. (Rec. N.29°E., 7.92 ft.) from DCSO BC.
60" now 56" Fir with healed over blaze bears S.10°E., 71.8 ft.,
from DCSO brass cap.
The orig. 12" now 34" fir with opened blaze showing 19/30 BT bears
N.47°E., 11.4 ft. from BLM cap.
60" now 56" Fir with healed over blaze bears S.15°E., 74.1 ft.
from BLM cap.
Unrecorded 38" fir recently scribed T24S R1W S19 BT bears N.30°E.,
73.6 ft. This tree is blocked from DCSO cap by Orig. BT.

8/12/81