

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Weyerhaeuser Company
 By Lester E. Calder
 April 1964
 C. S. File No. 51/31
 C.S. 53/111

Section Cor. common to Secs. 21 - 22 - 27 - 28. #108
 W. Co. Survey Record 1953 - Ref. by R. Ehm (Plates & "W" nails only)
 Set - 1 1/2" iron pipe from ref. made by L. E. Calder, 1942. Sometime
 after 1942, the area shifted in a northerly direction several
 feet. Calder's reference trees were outside of this area. The
 C. S. trees marked in 1939, see Ren. #5, were in the slide area.
 The Cedar is dead and down, the yew is standing, but at new location,
 scribing visible.
 50" Fir Stp. S.41°E. 32.5 ft. Found FOUND CORNER O.K.
8-29-67 V.R.T.
 50" Fir Stp. S.53°W. 57.0 ft. Found
 20" R. Cedar N.69°W. 57.2 ft. Found.

37

1/4 Corner common to Secs. 21 and 22.
 GLO Survey Record 1871 - Post, Gone.
 5" Fir S.60°W. 10 lks. Gone
 6" Fir N.25°E. 11 lks. Gone
 Set - 1" aluminum pipe for corner by single proportionate method.
 Ref. by Glen McChesney (Weyerhaeuser method with disc. #2149, Decl. 20°)
 22" Fir N. 87° E. 22.0 ft.
 16" Fir N. 52° W. 41.6 ft.

38

N. E. Corner Section 1 only.
 Found - 60" Fir S.70°E. 37.0 ft., now blown down.
 18" Yew; now 20" Yew S.24°W. 39.0 ft., O. K.
 62" Fir N.30°W. 8.6 ft., O. K.
 Set - 1/2" G. I. Pipe, W. Co., 1954.
 BT. - 64" Fir East 42.8 ft. "W" Nail & Plate.

39

Section Corner to Secs. 2 - 3 - 10 - 11.
 All Original BT's. gone.
 W. Co., 1958 - 54" Fir N.68°E. 13.9 ft., now stump, added a plate.
 60" Fir N.13°W. 14.1 ft., now stump, 1958 error, dist.
 should be 15.1, changed plate to 15.1.
 27" Fir S.17°E. 38.6 ft., now stump.
 48" Fir S.17°W. 49.7 ft., now a windfall.
 Set - 1" x 30" Aluminum Pipe, 1963 - 1" x 6" Marker Pipe.
 BT: - 54" Fir Stump N. 68°E. 13.9 ft., "W" Nail & Plate.
FOUND O.K. OCT. 1967 C.S. 54/16

40

1/4 Corner to Sections 10 and 11.
 Found - 72" Fir East 15 lks., scribing on bark mostly gone, Br. Tag O.K.
 8" Cedar N.50°W. 29 lks., not chopped out, some face showing
 but no scribing, some scribing might be inverted on part that
 is blown over. Brass Tag marked S.50°W. changed to S.50°E.
 Cedar Stake & left it for Corner.
 BT's: - 36" Fir S.66°W. 23.6 ft. "W" Nail & Plate.
 56" Fir N.53°W. 35.6 ft. "W" Nail & Plate.

41

North 1/4 Corner to Section 4.
 Found - 1882, 5" Hemlock, mkd. 1/4 S North Face, chopped out & found
 scribing on lower face on North side of 12" Hemlock.
 14" Cedar S. 6.6 ft., scribing visible on 26" Cedar, (Orig.)
 14" Hemlock E. 13.2 ft., no trace.
 BT's - 26" Cedar S.13°W. 8.9 ft. "W" Nail & Plate.
 10" Hemlock N.2°E. 28.6 ft. "W" Nail & Plate.

42

1/4 Corner to Sections 14 and 15.
 Found - WTCO. 1948, Calder survey by K. Bergeson.
 2" Cedar Stake, rotten at bottom.
 22" Cedar N.27°W. 49.5 ft., "W" Nail, good, plate about grown out.
 36" Cedar S.1°W. 70.2 ft., "W" Nail good, " " "
 Set - 1" x 33 1/2" Monel Pipe, Nov. 1957

43

WEYERHAEUSER CO.
 1957 - 1963
 C. S. File No. 53/111