

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

55

1/4 Corner to Sections 10 and 15.

Found - Stumps of Orig. BT's. as found by Forest App., 1952.

Orig. 40", now 43" Fir Stump, N. 50° W. 9.9 ft., bark gone, no scribe, forest app. tag mkd. to be on N.W. BT.

Orig. 30", now 33" Fir Stump, S. 32° W. 15.2 ft., bark gone, no scribe found. (face measure)

Find old blazes west of corner.

Set - Brass Cap at Cor. Mkd: County Surveyors T 24 S R 3 W
(Set Steel Fence Post Office 1/4 S 10
6' long, 2' E. of Cor.) 1967 S 15

New BT's: 22" Maple N. 81° E. 111.4 ft. mkd. "1/4 S10 CS BT.

(Note - BT. is live stub.)

6" D. Fir S. 58 1/2° E. 114.4 ft. mkd. "1/4 S15 CS BT."

Note - This corner lies in logged-off area on gentle southerly slope.

56

1/4 Corner to Sections 9 and 16.

Found - 1950 G.L.O. Brass Cap, firmly set, & properly marked.

10", now 11" maple, N. 16 1/2° E. 5.3 ft., tipped over, alive, shows scribe "1/4 S9" on unhealed blaze.

60" Fir Stump S. 62° E. 38.9 ft., shows healed blaze.

Set - 6.0 ft. steel fence post 2.0 ft. East of Corner, from which:

New BT: 16" Hemlock Stump S. 66° W. 14.4 ft. mkd. "1/4 S16 CS BT".

(6 ft. high stump)

Note - This corner lies on gentle S. W. slope in logged-off unit.

57

1/4 Corner to Sections 9 and 10.

Found - Org. 7", now 9" Yew, alive, N. 20° E. 10.6 ft., bent over & blaze rotted away, no scribe found.

Orig. 24", now 37" Hemlock, alive, N. 80° W. 7.9 ft., open & find scribe & reverse. We use face measurements on O. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyors T 24 S R 3 W
Office, 1967 1/4 S 9 | S 10

New BT's: 6" Hemlock S. 58° W. 22.6 ft. mkd. 1/4 S 9 CS BT.

14" Hemlock S. 64° E. 25.1 ft. mkd. 1/4 S10 CS BT.

Note - This corner lies westerly slope in small stand of old-growth timber.

Vernon "Ray" Tracy
Jack Heritage & E. West
September, 1967
C. S. File No. 54/27

58

Section Corner to Sections 9 - 10 - 15 - 16.

Found - 1950 G. L. O. Brass Cap, properly mkd., bent over & buried.

Orig. 40" Fir, now only decayed remains of stump with fragmentary bark scribe visible on old axe blaze, N. 13 1/2° E. 11.9'.

No trace of any other BT's. found because of logging.

Reset - Brass Cap in proper position and Mkd. new BT's:

15" Yew S. 28 1/2° E. 37.0 ft. mkd. T24S R3W S15 CS BT.

7" Hemlock S. 51° W. 37.4 ft. mkd. S16 CS BT.

11" Hemlock N. 7 1/2° W. 82.5 ft. mkd. T24S R3W S9 CS BT.

12" Hemlock N. 14° E. 73.7 ft. mkd. T24S R3W S10 CS BT.

59

1/4 Corner to Sections 4 and 9.

Found - 1950 G. L. O. Brass Cap, buried.

26" Fir, now stump, N. 41 3/4° E. 14.3 ft., moved by logging, should be 17.9 ft., scribe visible

18" Hemlock, now stump, S. 29 1/2° W. 50.8 ft., scribe showing, This BT. under logging debris.

Set - 6 ft. steel fence post alongside Brass Cap.

New BT: 58" Fir Stump S. 53° E. 33.1 ft. mkd. 1/4 S9 CS BT.

Note - Also Weyerhaeuser "W" nail at base of new BT.

This corner lies on steep, S. W. slope 70 ft. E. of Creek, 3 ft. wide, course S. in clear cut unit.