

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 3 W. R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21881

60

Section Corner to Sections 4 - 5 - 8 - 9.
Found - 1950 G. L. O. Brass Cap, firmly set, & properly marked.
8" Yew, alive, N. 66 3/4° E. 21.8 ft., scribe visible on
unhealed blaze.
All other BT's. down.
New BT: 26" Hemlock N. 29° W. 86.7 ft. mkd. T24S R3W S5 CS BT.
5" Yew S. 76° W. 43.1 ft. mkd. S 8 CS BT.
No other trees available.
Note - This corner lies on gentle N.E. slope in cut-off unit approx.
100 ft. S. of E. - W. cutting line.

61

1/4 Corner to Sections 30 and 31.
Found - 1958 Cadastral Brass Cap, properly mkd., buried under limbs & dirt.
18" Hemlock, alive, N. 35 1/2° W. 32.6 ft., scribe visible on
unhealed blaze.
S. E. Bearing Tree, now stump.
New BT: 7" Cedar S. 4° E. 35.5 ft. mkd. "1/4 S31 CS BT".
Note - This corner lies on steep N. E. slope, approx. 85 ft. W. of
Jeffers Creek.

62

1/4 Corner to Sections 16 and 21.
Found - 1950 G. L. O. Brass Cap, properly marked, in pile of logging
debris, out of position approx. 15.0 ft.
Straighten Pipe & Reset from Stumps of BT, as follows:
26", now 28" Fir, 5 ft. high stump, N. 7 1/2° W. 35.0 ft., open
& find "1/4 S16 BT" scribe.
S.E. BT., down & out of position.
New BT's: 16" Hemlock N. 5° W. 40.8 ft. mkd. 1/4 S16 CS BT.
18" Maple S. 11° W. 63.2 ft. mkd. 1/4 S21 CS BT.
Note - This corner lies in old cat. skid road on bench.

63

1/4 Corner to Sections 5 and 4.
Found - No trace of Brass Cap, 1950, called for, however, it may be
much deeper in dirt from large root wad.
9" Hemlock, now 14" Stump, N. 75 1/4° E. 50.2 ft., blaze buried, Open
& find scribe marks "1/4".
No trace S.W. BT.
Set - Brass Cap at Cor. Mkd: County Surveyors T 24 S R 3 W
Office, 1967 1/4 S 5/ S 4
With steel fence post 6.0 ft. long set alongside.
New BT's: 20" Hemlock Stump S. 29° E. 32.9 ft. mkd. 1/4 S 5 CS BT.
10" Hemlock S. 27° W. 46.3 ft. mkd. 1/4 S 4 CS BT.
Note - This corner lies on gentle easterly slope 100 ft. west of
old logging access road.

64

1/4 Corner to Sections 16 and 15.
Found - No trace of any Orig. BT's. in this area.
4"x4" scribed corner post, badly decayed, See Ren. #7.
40", now 42" Cedar, S. 82° W. 22.5 ft., scribe visible on
partially unhealed blaze.
N.E. BT. destroyed by logging several years ago.
Set - Brass Cap at Cor. Mkd: County Surveyors T 24 S R 3 W
Office, 1967 1/4 S 16 | S 15
New BT's: 12" D. Fir N. 4° W. 10.6 ft. mkd. 1/4 S16 CS BT.
12" Cedar S. 89° E. 26.4 ft. mkd. 1/4 S15 CS BT.
Note - This corner lies on flat bench land & in timber left from thinning.

65

1/4 Corner to Sections 10 and 11.
Found - 2"x20" Steel Pipe, bent & burned, See Ren. #41.
Orig. 72" Fir, now burned stump, East 9.9 ft., no scribe, we Rescribe:
"1/4 S11 CS BT"
Orig. 8", now 14" Cedar, stump, N. 50° W. 19.1 ft., burned, Open & find "1/4"
reverse, Weyerhaeuser method BT.
56" Fir, now stump, N. 53° W. 35.6 ft., "W" nail & tag S.W. "W", BT. destroyed.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 3 W
Office, 1967 1/4 S 10 | S 11
Set in place of old pipe with 6' steel fence post alongside. No other
suitable trees or stumps available. This area was clear cut & burned this yr.

12-1-67

Vernon "Ray" Tracy
Jack Heritage & E. West
September, 1967
C. S. File No. 54/27

nothing but 0216 notes
SEE AFO C.S. 16/16
MFO 1-29-04 SC

RE-NEWED CORNER NO. #62
RE-NEWED CORNER NO. #78
RE-NEWED CORNER NO. #79