

Douglas County Surveyor's Record of  
Government Corners Renewed

T 24 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C.S. File  
No.  
54/27

Section Corner to Sections 23 - 24 - 25 - 26. #111  
Found - Orig. 48" Fir, now shattered snag, N. 35° E. 28.4 ft., any scribe  
or scar would be approx. 5 ft. below logging debris.  
Orig. 40", now 44" Fir Stump, S. 40° W. 37.6 ft., shows scar.  
Orig. 24" Hemlock, now 28" Stump, S. 55° E. 25.7 ft., Open & find "B".  
No trace of NW BT at corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 3 W  
Office, 1968 S 23 S 24  
New BT: 35" Fir Stump N. 53° W. 31.4 ft. mkd. T24S S 26 S 25  
46" Fir Stump S. 52° E. 43.2 ft. mkd. T24S R3W S25 CS BT.  
No live trees available. This corner lies on very steep, NE. slope.  
3/18/68

Southeast Corner of Section 36, T23-3W.  
Found - 1/2" I. Pipe, "W" method., See C.S. File No. 53/107.  
Orig. 26" Fir, now 42" Stump, N. 45° W. 8.6 ft., old bark scribe  
visible in poor condition. Also "W" Nail.  
40" Fir Stump N. 47° E. 13.7 ft., "W" Nail & Tag. R R  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S 3 S 36 2  
Office, 1968 T23S W W  
(Reset I.P. alongside)  
New BT: 60" Fir Stump N. 47° W. 26.1 ft. mkd. T23S R3W S36 CS BT.  
Note - This corner lies on SE. slope on top of cut bank of  
cat road in logged-off area. NOT RE-RENEWED

Closing Corner to Sec. 31, T23-2W. & Sec. 6, T24-2W.  
Found - 1/2" Tubing at cor. & 1/2" I.P. for marker with Orig. BT's:, and  
"W" method BT., see Ren. #3, T23-2W., C.S. 53/106.  
Orig. 16" Cedar, now 24" Stump 5 ft. high, N. 10° E. 27.7 ft.,  
scribing visible on nearly healed blaze.  
Orig. 60" Fir, now 64" Stump, 2 ft. high, S. 57° E. 25.1 ft., top  
of blaze visible on top of stump.  
26" Hemlock Stump S. 50° W. 18.1 ft., "W" Nail & Tag.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R3 C S 31 R2  
Office, 1968 T24S W C S 6 W  
(Reset 1/2" Tube alongside)  
New BT: 9" Cedar Snag N. 44° E. 28.9 ft. mkd. T23S R2W S31 CC CS BT.  
Note - This corner lies on E. side of spur, ridge sloping south  
about 50 ft. E. of top.

Closing Corner to Sec. 1, T24-3W. & Sec. 6, T24-2W.  
Found - 1/2" I. Pipe at corner & "W" BT's., see Ren. #39, T24-3W.  
Orig. 18", now 20" Yew, alive, S. 30° W. 39.0 ft., scribe marks  
visible on old blaze. Rescribe: "T24S R3W S1 CC CS BT".  
Orig. 60" Fir, now 62" Stump, slightly out of position, S. 70° E. 37.0 ft.,  
shows good scar. No trace of N.W. Original BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R C C R  
Office, 1968 T24S 3W S 1 S 6 2W  
(Reset I.P. alongside)  
New BT: 14" Yew S. 50° E. 54.8 ft. mkd. T24S R2W S6 CC CS BT.  
Note - All "W" BT's., now stumps. No other trees suitable for BT's.  
This corner lies on bench sloping S.W. in logged-off area.  
4/1/68

1/4 Corner to Section 29 and 20. #121  
Found - 1950 G.L.O. Brass Cap, properly mkd., & 1 1/2" Iron Bar, See Ren. #4.  
12" Fir, now high stump, S. 46° W. 15.2 ft., shows scar, badly burned.  
All other BT's. gone, completely.  
New BT: 5" Cedar S. 24° E. 75.7 ft. mkd. T24S S 29 CS BT.  
No other trees available.  
Note - Corner lies at end of old E-W fence, running E. to 80. Rd. about  
550 ft. E. edge of red brick chimney on house N. 21 1/2° E. 300 ft.  
Put Line Tag on N. end of bridge #19/15.3 west side of Co. Road.  
4/3/68

FO. OK 6/91  
D. PEEL M 113-43  
FD OK 10/89  
L. DOLAN M109-1  
SEPT. 68

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
April, 1968  
C. S. File No. 54/27