

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

1/4 Corner for Sections 8 & 17.
Original Brass Cap found.
Found - 36" D. Fir
20" Maple (dead)

76

New BT's - 20" Cedar, bears N.29°E., 21.1 ft. distance, mkd. N 1/4 S8 BT.
8" D. Fir, bears S.52°30'W., 22.75ft distance, Mkd. N 1/4 S17 BT.
Note - The corner is situated on a SW slope, approx. 120 ft. above a medium size creek that courses SE. Medium undergrowth of salal, fern & Oregon grape. Trees of D. Fir and scattered Cedar.

Baugman Surveying Service
Eugene A. Bloom
M 47 - 61 C.S. File 55/280
February, 1973

Center 1/4 Corner Sec. 17.
Set - 1" x 36" I.P., 6" above ground, with brass cap mkd. T24S R3W WM
1973 C 1/4 S 17 OLS 492.

77

New BT's - 20" Cedar, bears N.74°E., 16.4 ft. dist. mkd. C 1/4 S17 BT.
22" D. Fir, bears N.40°W., 17.4 ft. dist. mkd. C 1/4 S17 BT.
Note - The corner is situated on an east slope, approx 75' down the east side of Timothy Ridge, which bears approx. N-S. Medium undergrowth of salal & Oregon grape. Large D. firs & Cedar. Some small vine maple. See also Ren. #19

February 1973

SEE ALSO WEYERHAEUSER NOTES IN C.S. 59/11

1/4 Corner for Secs. 4 and 5.

78

Found - 1950 U.S.G.L.O. brass cap on iron pipe leaning & sticking loosely in dirt almost out of ground. This brass cap obviously out of position.
Upon digging at position established from 2 BT's, I find a 1967 Co. Surveyors Brass cap, buried & on its side, in good condition. This cap apparently moved out of position & recovered with loose dirt. Ren. No. 63

Re-Set - and remarked 1967 County Surveyors Brass cap T 24 S R 3 W
with a steel fence post alongside, 1/4 S 5 | S 4
1974
1967

from which - 12" Hemlock stump bears N.75 1/4°E., 50.2 ft. previously opened blaze and scribing visible. (Rec. N.75 1/4°E., 50.2 ft.)
10" Hemlock stump bears S.28 1/4°W., 49.3 ft. (Rec. S.27°W., 46.3 ft.) scribing "1/4 S5 CS BT visible.

1/18/74

Gary Langlitz, Surveyors Office
P. Earle
Jan. 18, 1974
C.S. 56/43

3/27
JAN 75

1/4 Corner for Secs. ¹⁵ and 16.

79

Found - Rotted remains of scribed Fir post. Ren. #7
40" now 42" Cedar (stump) bears S.83°W., (rec. S.78°W.) 24.0 ft. scribing visible. (Rec. 22.5 ft.)

NE BT destroyed by old logging.

1967 Brass cap at corner. Ren. #64

12" Cedar bears S.89°E., 26.4 ft. scribing visible BT tag. to center of tree.

12" now 14" D. Fir bears N.4°W., 10.6 ft. to center of tree scribing visible BT tag.

New BT's- 18" D. Fir bears S.41°W., 22.1 ft. with "W" nail and plate
48" Fir stump bears N.13°W., 74.0 ft. with "W" nail and plate.

5/6/76

Frank O. Williams by Glen McChesney
For: Weyerhaeuser Co.
April 7, 1976
C.S. 58/8

1/4 Corner for Sec. 6 only. West boundary.

80

Found - 1950 GLO brass cap in place.
30" now 40" Fir bears N.55°E., (rec. N.58°07'E) 227.0 ft. scribing visible on partly healed face, with BLM BT tag.

33" now 42" Incense Cedar bears S.7°E. (Rec. S.9°E.,) 419.8 ft. faces healed over with BLM BT tag.

New BT's- 12" Fir bears N.30°E., 52.3 ft. with "W" nail and plate
8" Fir bears S.49°E., 22.0 ft. with "W" nail and plate.

4/7/76

JAN 78