

Douglas County Surveyor's Record of  
Government Corners Renewed

Lwp. 24 S. T. S. R. 4 W. R. W. W. M.

✓ 1/4 COR. BET. SECS. 36 & 31. F.B. No. 7 Page 2  
Madrone 10" Dia. Brs. N. 72° W. 10 Lks.  
Cedar 48" Dia. brs. S. 59° E. 31 Lks. **SEE CORNER NO. 24** 9  
May 1903  
C. E. Roberts  
Co. Surveyor.  
F.B. 7P. 19

✓ S. E. COR. OF S. M. DRIVER D. L. C. No. 41 ( F.B. NO. 9 Pg 1)  
Fir 18" Dia. Brs. S. 75° E 12 Lks. **SEE COR. #95** 10  
Fir 12" Dia. Brs. S. 77° W. 24 Lks. Aug. 1904.  
C. E. Roberts  
Co. Surveyor.  
F.B. 9, P. 1

✓ N. W. COR. OF S. M. DRIVER D. L. C. No. 41  
N. W. COR. OF S. M. DRIVER D. L. C. No. 41  
W. Oak 6" Dia. brs. N. 45° W. 37 Lks. **78-1711**  
W. Oak 5" Dia. Brs. S. 87° W. 33 Lks.

1/4 SEC. CORNER BET. SECS. 7 & 18. { Oak stake destroyed—a 3/4" x 4" reinforcement  
bar set by F. C. Frear in 9-29-54. Trees Good.  
Set a 2" x 2" x 3' Oak stake for corner from Feb. 12, 1941  
the 12" Black Oak, S. 50° E. 195 Lks. which was cut C.S. 34/46A  
out and scribe marks found and from rotten stump of H. L. Eppstein  
18" W. Oak N. 18° W. 124 Lks. Marked New Bearing Co. Surveyor.  
Trees as follows: WIT:  
14" W. Oak, brs. N. 35° E. 10.8 feet. 12 Romie Howard  
Marked 1/4 S. 7 C. S. B. T. N. E. Richardson  
12" Oak, Brs. S. 42° W. 10.1 feet. Harvey Eppstein  
Marked 1/4 S. 18 C. S. B. T. Jr.

✓ SECTION CORNER COMMON TO SECS. 7, 18, 12 & 13 T. 24 S. R 4 & 5 W  
Set a 5" x 5" x 5' Oak post for corner from the old  
Bearing Trees, Namely B. Oak brs. S. 32° W. 92 Lks, Cut  
out and scribe marks found; B. Oak brs. N. 47° W. 110 Lks.  
cut out and found old ax marks, No scribe marks; B. Oak  
brs. N. 54° E. 83 Lks. Down and rotten; B. Oak brs.  
S. 52° E. 107 Lks. alive. Marked New Bearing Trees 13 C.S. 34/46A  
as follows: M3-53  
12" W. Oak Bears N. 64° E. 36.5 feet  
Marked S. 7, T. 24 S. R. 4 W. C. S. B.T. 41  
15" B. Oak Bears S. 19 1/2° E. 91.5 feet,  
Marked S. 18 T. 24 S., R. 4 W. C. S. B.T.  
12" W. Oak, Bears S. 32° W. 20.4 feet,  
Marked S. 13, T. 24 S. R. 5 W. C. S. B. T.  
10" W. Oak, Bears N. 71 1/2° W. 59.0 feet,  
Marked S. 12, T. 24 S. R. 5 W. C. S. B.T.

✓ South East CORNER OF ELIZABETH JOHNSON'S D. L. C. NO. 45  
Set a 2" x 36" I.P. #111 14  
12" old stump with B.T. N32 E. - 290 links.  
Marked New Bearing Tree- 7" B.Oak S, 30° 30'E 89.0 ft.

✓ SECTION CORNER COMMON TO SECS. 21, 22, 27, & 28.  
Set a 2" x 36" I.P. 100 15  
3 old bearing trees still standing. 20" W. Oak S. 72° E. 278 lks.  
10" W. Oak N. 29° W. 58 lks. 10" W. Oak N. 39° E. 73 lks.

✓ SOUTHWEST CORNER OF SAMUEL M. DRIVER'S D. L. C. NO. 41  
Set a 2" x 36" I.P. 16  
Set from old B.T. 18" Oak N. 48° W. 91.0 lks.  
Marked the following new bearing trees.  
15" W. Oak N. 4° 05' E. 164.3 ft.  
7" W. Oak S. 40° 20' W. 102.4 ft.

✓ NORTHWEST CORNER OF SAMUEL M. DRIVER'S D. L. C. NO. 41  
Set a 2" x 30" I.P. 17  
Reset from 2 old bearing trees. Ren #1  
Marked the following new bearing tree. 78  
10" W. Oak S. 67° 30' E. 31.6 ft.

✓ 1/2 CORNER BET. SECTIONS 22 & 23. F.D. OK 12/95 BY CHRISTENSEN  
Set a 2" x 48" I.P. M 123-21 18  
Marked the following new bearing tree.  
14" W. Oak S. 3° 30' W. 10.7 ft.

This corner visited by M.E.G. & Cuy 3-8-63 & FOUND IN GOOD CONDITION.  
SEE NOTE IN C. & FILE No. 53/9

Rest by Gene Richardson and  
Edwin Woodford 1945.