

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy & Mike Stone
February and March 1963
C. S. File No. 53/9

69

Section Corner to Sections 8 - 9 - 16 - 17.
Found - Oak S.10°E. 93.1 ft., down & badly rotted, stump hole plain.
Found good reverse scribing "S16 T24S R4W BT".
Rotten Oak Stump N.40°W. 29.7 ft. Trunk of tree pushed out of position.
Good reverse scribing visible on trunk of tree.
Upper portion of rotted Oak Tree S.59°W. 18.5 ft. No stump hole found.
Could not find where tree had stood. No marks found.
No trace of N.E. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W

S 8	S 9
S17	S16

Office, 1963
New BT's: 36" E.Cedar N.30°W. 14.0 ft. Mkd: T24S R4W S 8 CS BT.
9" D.Fir S.51°W. 20.6 ft. Mkd: T24SR4W S17 CS BT.
7" D.Fir S. 8° E. 16.9 ft. mkd: T24S R4W S16 CS BT.
7" W.Fir N.45°E. 24.3 ft. Mkd: T24S R4W S9 CS BT.
A N. & S. Fence line bears East 8 ft. from Corner.

70

Section Corner to Sections 10 - 11 - 14 - 15
Found - Brass Cap set by Grant in 1958. - SEE COR.# 32
High cut Fir Stump, now ~~24~~ 26", S.58°W. 34.3 ft., chopped open
& found good scribing "S". No trace of any other Orig. BT's.
New BT's: 6" Hemlock N.26°E. 84.7 ft. Mkd: S11 CS BT.
40" Red Cedar S.20½°E. 266.5 ft. Mkd: T24S R4W S14 CS BT.
9" Red Cedar S.66°W. 198.0 ft. Mkd: T24S R4W S15 CS BT.
No suitable trees near to N. W.
Corner lies approximately 35 feet North of small stream running S. E.

71

¼ Corner to Sections 10 and 15.
Found - Haines' "T" Iron at Corner. - SEE COR.# 38
30" Fir Stump S.62°E. 15.2 ft., scribing visible on partially opnd. face
30" Fir Stump N.63½°E. 8.6 ft, shows very plain axe scar.
18" Fir S.23°W. 34.5 ft., bark scribing visible, also Haines' metal
disc nailed to tree.
DID NOT SET BRASS CAP. - Corner lies on top of mall spur at top of steep N. slope
New BT: 7" Hemlock N.46°W. 32.1 ft. Mkd: ¼ S10 CS BT. slope.

72

Witness Corner to ¼ Corner Sections 10 and 11.
Found - Recently broken Fir Snag, now 24", N.56°E. 12.5 ft., good scrbing.
22" Fir, uprooted, not recent, S.64°W. 10.4 ft., shows good scar.
Position for Corner falls in creek. Set Wit. Cor. 40 ft. North.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W W C ¼ S10/S11
Office, 1963 Corner 40 ft. S.
New BT's: 13" D.Fir S.74°E. 39.6 ft. Mkd: WC ¼ S11 CS BT.
21" D.Fir S.32°E. 26.3 ft. Mkd: WC ¼ S11 CS BT.
(No trees available except in S.E. quad.)

73

¼ Corner to Sections 13 and 24.
Found - 28" D.Fir N.23½°W. 26.4 ft. Has been opened previously, good scribing.
36" Fir, old uproot, dead, S.85½°W. 13.2 ft, face down, no scribing vis.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W ¼

S13
S24

Office, 1963
New BT: 54" D.Fir S.46°W. 66.5 ft. Mkd: ¼ S24 CS BT.
Rescribe - 28" D.Fir N.23½°W. 26.4 ft. Mkd: ¼ S13 CS BT.
Corner lies approximately 35 ft. S.E. of old logging road running NE. & SW.

74

Fd P 90
M 112 - 11

Section Corner to Sections 15 - 16 - 21 - 22.
Found - ¾" Galv. Iron Pipe (not 1½" Pipe), top about 8" above ground.
24" Bl. Oak N.2½°W. 918.1 ft. Opened 18 yrs. ago. Good reverse
scribing on loose slab, "16 T24S R4W". - SEE COR.# 19
36" W.Oak S.8¼°E. 300.3 ft., opened previously & face rotted.
Fragments of scribing visible on edges of old face.
Did not find N.E. or S.W. Bearing Trees.
DID NOT SET BRASS CAP.
New BT's: 14" Ash N.49°E. 63.5 ft. Mkd: T24S R4W S15 CS BT.
6" Ash N.7°W. 155.0 ft. Mkd: S16 CS BT.
12" W.Oak S.32°E. 169.6 ft. Mkd: T24S R4W S22 CS BT.
12" W.Oak S.10°W. 325.3 ft. Mkd: T24S R4W S21 CS BT.