

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 S. T. S. R 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

106

N. W. Corner D. L. C. No. 43.
Found - Hollow Dead Oak Snag N.30°E. 9.2 ft. Cut open & fd. reverse face.
Stump Hole & Rotten Oak Log S.60°E. 17.8 ft. Didn't look for scrbing.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W NW DLC 43
Office, 1963
New BT's: 11" D.Fir S.10°E. 13.0 ft. Mkd: NW DLC 43 CS BT.
21" D.Fir N.43°E. 12.0 ft. Mkd: NW DLC 43 CS BT.
Corner lies on South slope approx. 200 ft. South of ridge top.
A North & South Fence Line is 24 feet East of Corner.

107

S. W. Corner D. L. C. No. 43.
Found - Old Oak, down several years, N.48°E. 538.6 ft. Cut open & fd. good scr
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W SW DLC 43
Office, 1963
New BT's: 8" W.Oak S.69°E. 55.6 ft. Mkd: SW DLC 43 CS BT.
26" D.Fir S.26°W. 77.7 ft. Mkd: SW DLC 43 CS BT.
Corner lies on open NE slope, near top of small ridge.

108

N. W. Corner D.L.C. No. 44.
Found - Remains of old Oak Stump N.21°W. 314.2 ft. No scribing found,
but a portion of badly rotted overgrowth of old face found.
This stump fits location of calculated position from old BT.
for S.W. corner of DLC No. 43.
No trace of other Original Bearing Trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W NW DLC 44
Office, 1963
New BT's: 6" W.Oak N.73°E. 27.6 ft. Mkd: NW DLC 44 CS BT.
9" W.Oak S.38°W. 67.5 ft. Mkd: NW DLC 44 CS BT.
Corner lies in nearly level, open pasture land, at foot of north
slope of small hill.

109

Interior "L" Corner D. L. C. No. 45.
Found - 26" W.Oak N.70°E. 19.8 ft. Cut open & fd. good scribing "C4".
32" W.Oak S.63°E. 117.2 ft. (not S.70°E.) 122.1 ft. Opened & found
good scribing, part of "B".
Couldn't find any location at which both bearings & one dist., or
both dist. & one bearing from found trees would fit gov't field
notes, set corner from closest tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W Int. "L" Cor. D.L.C. 45
New BT's: 11" W.Oak N.24°W. 5.0 ft. Mkd: Int. L DLC 45 CS BT.
10" W.Oak S.29°E. 19.5 ft. Mkd: Int. L DLC 45 CS BT.
Corner lies approx. 15 ft. West of small stream flowing N.W.

110

S. W. Corner D.L.C. No. 45.
Found - 44" W. Oak S.14°W. 203.3 ft., opened & fd. reverse scribing on
overgrowth of old face "4W", Tree hollow, face had apparently
rotted badly before growing over.
27" W.Oak N.89½°E. 295.0 ft. No scars visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W SW Cor. D. L. C. 45
New BT's: 7" D.Fir S.2°W. 73.0 ft. Mkd: SW DLC 45 CS BT.
D.Fir N.38°E. 109.0 ft. Mkd: SW DLC 45 CS BT.
Corner lies in open pasture land approximately 600 ft. south of
Driver Valley Road

111

Mst. Southerly S. E. Corner D. L. C. No. 45.
Found - ¾" Iron Pipe set by Woodford & Richardson in 1945. REN #14
12" Bl. Oak S.30½°E. 89.0 ft., shows good scars. Did not open.
Old Rotten Oak Stump N.3°E. 191.4 ft. Good rev. scrbing. Orig. BT.
DID NOT SET BRASS CAP.
New BT's: 9" D.Fir S.56°E. 6.4 ft. Mkd: S SE DLC 45 CS BT.
7" D.Fir N.79°W. 11.6 ft. Mkd: S SE DLC 45 CS BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
May 1963
C. S. File No. 53/9