

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

118

$\frac{1}{4}$ Corner to Sections 29 and 30.
Found - Both BT's. mkd. in 1960, but Brass Cap is gone; falls in Cat. Road.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W $\frac{1}{4}$ S30/S29
Trees Mkd. in 1960 as follows: - *SEE Cor. # 43*
7" Bl. Oak N.66°W. 20.1 ft. scribing still visible " $\frac{1}{4}$ S30 CS BT".
9" D.Fir S.72°E. 62.5 ft., scribing still visible " $\frac{1}{4}$ S29 CS BT".
New BT: 9" D.Fir N.12°W. 44.7 ft. Mkd: $\frac{1}{4}$ S30 CS BT.
Note - Corner lies just west of power line, Fir BT. in Section 29 in
Power Line R/" will probably have to be cut before limbs reach wires.
FD OK 1/23/96 H. CHRISTENSEN M123-36

119

Section Corner to Secs. 29 - 30 - 32 - 31.
Found - Rock set by Frear, "X" cut in top, Rock firmly set. - *SEE Cor. # 5*
Rotten remnant of Fir Stump S.65 $\frac{1}{2}$ °E. 7.0 ft. Not enough left
to find any marks.
No trace of Frear's other BT. or any of the originals.
Corner is nearly in center of power line R/W. Location fits
call on ridge top in Orig. gov't notes.
DID NOT SET BRASS CAP.

New BT's: 8" Madrone S.81°E. 105.4 ft. Mkd: T24S R4W S32 CS BT.
8" D.Fir N.59°E. 160.0 ft. Mkd: T24S R4W S29 CS BT.
9" D.Fir N.73°W. 82.6 ft. Mkd: T24S R4W S30 CS BT.
10" D.Fir S.72°W. 98.2 ft. Mkd: T24S R4W S31 CS BT.
Note - Corner is in E. & W. fence line, 7 ft. west of fence corner,
fences East, West and North.

120

$\frac{1}{4}$ Corner to Sections 31 and 32.
Found - Rock set by Frear, "X" cut in top. - *SEE Cor. # 4*
25" W.Oak S.24°W. 216.5 ft., shows good scar. Appears to have
been opened previously, Did not open.
No trace of S. E. BT.
DID NOT SET BRASS CAP.

New BT's: 21" W.Oak S.55°W. 114.0 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
14" Ash N.81°E. 144.8 ft. Mkd: $\frac{1}{4}$ S32 CS BT.
Note - Corner lies incultivated field approx. 140 ft. North of
small stream flowing Southeast.

*FD Stone & BT's
W. Barnes
M 60-70
1/176*

121

$\frac{1}{4}$ Corner to Sections 29 and 32.
Found - Rock set by Frear, "X" cut in top. - *SEE Cor. # 3*
20" Fir Stump N.65 $\frac{3}{4}$ °E. 3.3 ft., bottom of axe face only, no scrbing.
Stump Hole & rotten Oak Log S.30°E. 59.4 ft. Opened & found good
reverse scribing "B". Upper face rotted away (Orig. BT.)
Stump Hole only N.16°E. 19.8 ft.
Set - Brass Cap alongside Rock Mkd: County Surveyor's T24S R4W $\frac{1}{4}$ S29
Office, 1963 *S30 S32*
New BT's: 10" W.Oak S.40°E. 50.8 ft. Mkd: $\frac{1}{4}$ S32 CS BT.
6" W.Oak N.75°E. 51.3 ft. Mkd: $\frac{1}{4}$ S29 CS BT.
Note - Corner lies on East slope, approx. 100 ft. W. of small stream
flowing south.

FD OK 1/23/96 CHRISTENSEN M123-36

122

Witness Corner to $\frac{1}{4}$ Corner to Sec. 32, T24-4W. & Sec. 5, T25-4W.
Found - W.Oak, recently uprooted & down, now 36", N.3 $\frac{1}{2}$ °E. 83.8 ft., opened
& found good scribing "S BT". Ring count shows this to be Frear's.
SEE COR. # 1 Rotten remnants of Oak Log S.81°W. 140 ft. Too far gone to find mks.
Did not find rock set by Frear, Cor. Location falls in gravel road.
Set - Wit. Cor. 14 ft. W. of $\frac{1}{4}$ Cor. Brass Cap Mkd:
County Surveyor's Office, 1963 T24S R4W WC to $\frac{1}{4}$ S32
14 ft. E. to Corner. T25S R4W S 5
New BT's: 5" W.Oak N.82°E. 69.9 ft. Mkd: W. C. $\frac{1}{4}$ S32 CS BT.
6" W.Oak S.78°W. 38.2 ft. Mkd: W.C. $\frac{1}{4}$ S 5 CS BT.
Brass Cap set in fence line along S.W. side of Road to Manning's place.

RE-RENEWED, SEE CORNER NO. #178

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
May 1963
C. S. File No. 53/9