

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 24 T. S. R 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Donald Bentz
For: Knight Ranch
Nov. 1980
Map filed Jan. 1982
M 91 - 2

166

Interior "L" corner for DLC #46
Set - 5/8" iron rod from which:
BT - an 18" oak bears N.88°E., 26.1 ft. scribed D.L.C. Corner
T24S R4W B.T.
Fence corner bears N.69°E., 20.0 ft. fence runs east and south.

L. W. Barber For:
Bureau of Land Man-
agement
May 15, 1974 (Filed
Nov. 1984)
M 97 - 62

167

Most easterly southeast corner for DLC #46
Set - 5/8" iron rod 2 ft. west of fence line from which:
BT - An 18" snag in fence corner bears south 9.0 ft. (fence runs
north and west)
Corner is 30 ft. east of ridge top and 18 ft. east of north-south
skid road.

168

Center 1/4 Corner for Section 35
Set - Rebar, 1/2" x 18"
BTs - 14" cedar, S.75°E., 7.5 ft.
18" cedar, S.36°30'W., 19.3 ft.

169

1/4 Corner for Section 35; and Sec. 2 of T.25-4
Set - Rebar, 1/2" x 18" (SEE ALSO REN.#32 IN T. 25-4)
BTs - 14" fir, N.17°E., 59.5 ft.
48" cedar, S.75°E., 55.5 ft.
18" fir, S.23°30'E., 38.6 ft.

Ronald Geisler
For: Champion
International Co.
Oct. 9, 1985
C.S. 63/22

170

West 1/4 Corner for Sec. 18 only of T.24-3.
Found - 1950 BLM brass cap on a 1" I.P. extends 14" above ground.
28" rotted fir stump bears N.43 1/4°E., 76.3 ft. (Rec. 72.6 ft.)
scribing visible (1950)
34" Fir bears S.19°E., 38.28 ft. closed face.
New BT - 17" W. fir bears N.52°E., 26.9 ft. scribed 1/4 S18 BT. This
tree had a 1963 BLM tag (BT) on it but no face. REN.#140
Located along N/S wire fence.

Ronald Geisler
L.S. #1988
For: International
Paper Co.
Oct. 25, 1985
C.S. 63/22

171

Section corner for Secs. 7 and 18 only of T.24-3
Found - 1950 BLM 2 1/2" brass cap on a 2" I.P. extending 14" above
ground. And See Ren. #124
22" cedar snag bears S.82°E., 62.22 ft. (Rec. S.85°E., 61.38 ft.)
scribing partially visible.
New BTs - 16" fir bears S.38°E., 69.2 ft. scribed T24S R3W S18 BT.
14" fir bears N.59°E., 77.2 ft. scribed T24S R3W S7 BT.

Douglas County
Surveyors Office
L.E.Monrean
Terrie Frannsen
Coleen Bliss
August 1, 1986
C.S. 62/37

172

Section corner for Secs. 30 and 31; and 25 & 36 of T.24-5
Found - 1" x 36" gal. I.P. with brass cap, 1958 County, out of
ground. Was able to identify location for corner by
depression in ground & location of broken flanged base of
monument under surface. Renewals 94 and 132
W. Oak now a 26" dia. stump with blaze visible in growth ring
pattern, bears N.59°W., 39.8 ft.
12" W. Oak bears N.32°E., 59.5 ft. has been cut down.
14" W. Oak now a 16" dia. snag with well healed blaze bears
S.79°W., 32.0 ft.
16" W. Oak now a 22" dia. stump bears S.25°E., 60.8 ft. (stump
located on easterly edge of creek bed.)
Orig. 16" maple, N.61 1/2°E., 46.2 ft. not found. (this position
falls at westerly edge of creek bed.)
14" B. oak now 18" dia. and cut down bears N.37 1/2°W., 13.2 ft.
(Rec. N.38°W., 13.0 ft.)
Set - We reset monument with cap protruding approx 1 foot above ground.
We add the words "RESET 1986".

New Accessories:
10" B. Oak blazed and scribed "T24S R4W S31 CS BT" bears
S.62 1/2°E., 15.7 ft.
8" W. oak blazed and scribed "T24S R4W S30 CS BT" bears N.47 1/2°E.,
52.6 ft.
Set 1/2"x8" spike in 18" stump of down bearing tree. Spike bears
N.37 1/2°W., 13.2 ft. and stamped "BO". All BTs tagged with DCSO

*Fd. 9/15/88
B. SHANER
C.S. 63/85*

5827