

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 5 R. W. W. M.

Section Corner to Secs. 25 & 36, T24S.R5W., & Secs. 30 & 31 T24S.R4W.
Found - All Four BT's. as recorded except N.59°W. 39.8 ft. BT.
which is W. Oak recorded as Bl. Oak. I open this BT
& find good scribing "5" (SEE COR. #1 for BT's) #109
Find Orig. 16", now 40" Maple, shows good scar, center
rotted, N.61½°E. 46.2 ft. R5W R4W
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958

S25	S30	T24S
S36	S31	

New BT: 14" B. Oak bears N.38°W. 13.0 ft. scribed S25 T24S R5W CS BT.

RE-RENEWED SEE CORNER NO. #109

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
December 1958
C. S. File No. 49/124

Renew Township Corner Twp. 24 & 25S. R's. 4 & 5 W. 23
Found - Laurel Tree, now 30" diam. standing but dead, chopped open
& found good scribing "BT" (N.41°E. 13.2 ft.)
Laurel Tree, standing & alive but rotted out inside, now
40" diam. N.74°W. 207.9 ft.
Stump Hole S.22°E. 25.7 ft.
Oak tree (dead & down), now 16" Diam. S.22°W., instead of
S29½°W. 82.5 ft. Chopped out upper blaze & found reverse
of scribing "R5W T25S & S".
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958

S36	S31	R4W
S1	S6	

T24S
T25S

Blaze & Scribe the following trees:
8" W. Oak S.52½°W. 24.4 ft. mkd. "T25S R5W S1 CS BT"
10" W. Oak S.44°E. 45.0 ft. mkd. "T25S R4W S6 CS BT"
8" W. Oak N.48°W. 15.6 ft. mkd. "T24S R5W S36 CS BT".
7" W. Oak N.15°E. 25.9 ft. mkd. "T24S R4W S31 CS BT".

FOOK
BY R. Ddan
7/94
M120-61

Section Corner to Sections 25, 26, 35, and 36. 24
Found - Stewart's 30", now 38" Maple N.48°E. 68.3 ft., shows
scar, I do not open. REN #9
30", now 32" Maple S.62½°W. 39.5 ft. I do not open.
No trace of S.E. BT.
30" Ash, now Snag N.17½°W. 136.0 ft., shows good
scribing.
Also Found 1" Iron Pipe at Corner. No Brass Cap Set.
New BT: 38" Forked Maple N.51°W. 35.5 ft. scribed T24S R5W S26 CS BT.

¼ Section Corner to Sections 25 & 26. 25
Found - Part of Rock Mound - rocks placed in a circle. REN #8
White Oak Tree, now 17", S.52°E. 95 ft. This tree showed
scars. Opened tree & found it had been opened about
60 yrs. ago. Center rotted out.
Ash Tree, now 28", N.65°W. 42.9 ft. This tree had been
reblazed. Scribe marks visible in still open upper &
lower faces approximately 3" inside present bark.
Probably Stewart's scribing. Through an opening in
the N.E. face I could see that the entire center of
the tree has rotted away.
At Corner Set Iron Pipe with Brass Cap Mkd: County Surveyor's
Office, 1959 T24S.R4W ¼ S26/S25.
Built Mound of Rocks around Corner.
Blaze & Scribe following Trees:
17" W. Oak N.48°E. 4.6 ft. Mkd. "¼ S25 CS BT."
10" W. Oak N.33°W. 29.3 ft. Mkd. "¼ S26 CS BT."
Fence Corner (Fence N. & E.) bears East 23.3 ft.
Corner is 9 feet West of Small Creek flowing S.15°E.

Section Corner to Sections 23, 24, 25, and 26. 26
Found - 2" x 15" x 8" Stone at Corner & Orig. 28" W. Oak, now
30" Snag., previously opened, center mostly rotted,
shows good scribing "BT". I find depression that checks
bearing & distance for Orig. S.E. BT.
No trace of other Orig. BT's. found.
Set Brass Cap alongside Corner Stone Mkd: County Surveyor's Office,
1959

T24S R5W	S23	S24
	S26	S25

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
April 3, 1959
C. S. File No. 49/124