

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

67

Township Corner $\frac{S36}{S1} | \frac{S31}{S6}$ T24S
R6W R5W T25S

Found - Remains of all 4 Orig. BT's.:

S. W. & N. E., now down. S.E. BT., now snag., outside rotted off.

N. W. BT. standing, center rotted., All check record, no scribing found.

Set Brass Cap at Corner Mkd: $\frac{S36}{S1} | \frac{S31}{S6}$ T24S County Surveyor's Office, 1960

New BT's: 13" Laurel bears S.59°W. 51.6 ft. scribed S 1 T25S R6W CS BT.
6" B.Oak bears S.64°E. 18.9 ft. scribed S 6 T25S R5W CS BT.
14" Laurel bears N.19°E. 20.1 ft. scribed S31 T24S R5W CS BT.
26" W.Oak(Orig.) N.69°W. 50.8 ft. scribed S36 T24S R6W CS BT.

Note - See signed statement by Harry Bainbridge in file.

James W. Byron
Milo Godfrey
Clete Putnam
March 17, 1960
C. S. File No. 49/124

68

$\frac{1}{4}$ Section Corner to Sec. 31, T24S R5W. & Sec. 36, T24S R6W.

Found - Orig. 14", now down & partly rotted Oak. Shows good reverse scribing on chip of old face "BT".

Orig. N. E. BT., now down, face down.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ S36/S31 T24S

New BT's: 12" W.Oak bears N.57°W. 6.5 ft. scribed $\frac{1}{4}$ S36 CS BT.
11" W.Oak bears S.83°E. 12.9 ft. scribed $\frac{1}{4}$ S31 CS BT.

69

$\frac{1}{4}$ Section Corner to Sections 30 and 31.

Found - Orig. 11", now 26" B. O. N.14°W. 57.4 ft. I open & find good scribing "T".

Orig. 10", now 30" B.O. S.4 $\frac{1}{2}$ °E. 46.9 ft., previously opened, center rotted. I do not open.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ S30 T24S R5W

New BT's: 8" W.Oak bears N.7 $\frac{1}{2}$ °W. 8.2 ft. scribed $\frac{1}{4}$ S30 CS BT.
7" W.Oak bears S.30°E. 3.7 ft. scribed $\frac{1}{4}$ S31 CS BT.

Note - Corner under E. W. Fence.

Milo E. Godfrey, Deputy
Vernon Tracy
August 8, 1963
C. S. File No. 49/123

70

Township Corner T24S R6W $\frac{S36}{S1} | \frac{S31}{S6}$ R5W
T25S

Found - Brass Cap out of ground and leaning against corner post of fence.

All 4 BT's. mkd. in 1960 are alive & standing, vis:

13" Laurel S.59°W. 51.6 ft. scribing visible.

14" Laurel N.19°E. 20.1 ft., scribing visible.

26" W.Oak(Orig.BT.) N.69°W. 50.8 ft., renewal scribing visible.

6" Bl.Oak S.64°E. 18.9 ft. scribing visible, tree standing and alive, but top broken out.

Reset- Brass Cap at Corner - Top flush with surface of ground.

New BT: 19" D.Fir S.11°E. 49.2 ft. Mkd: T25S R5W S6 CS BT.

Sec. Cor. to Secs. 34 & 35, T24-5W. & Secs. 3 & 2, T25-5W.

Found - Co. Surv. Brass Cap, See Ren. No. 19.

36" Maple N.11°E. 202 ft., uprooted & down, this tree is across main road from corner, all scribing visible.

24" W.Oak N.80 $\frac{1}{2}$ °W. 45.6 ft., standing but dead, scribing visible.

18" Ash S.1 $\frac{1}{2}$ °E. 36.6 ft., alive & standing, part of top broken out.

New BT's: 9" W.Oak S.60°E. 146.5 ft. Mkd: T25S R5W S2 CS BT.

12" W.Oak S.23 $\frac{1}{2}$ °W. 128.3 ft. Mkd: T25S R5W S3 CS BT.

No trees near in N.E. or N.W. quadrant.

Note - Corner is in lawn behind shed at rear of dwelling house.

December 13, 1963

71

*FD. OK 10/9/68
K. Reed - Dist.
Co. Surveyor's off.
C.S. 4/1/68*