

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

74

1/4 Section Corner to Sections 18 and 17.
Found - Orig. 24", now 30", down & partly rotted, Fir S.78°30"W.
7.3 ft. Find good scribing "1/4".
Orig. 18", now 40" Fir N.75°30'E., shows good scar,
I do not open.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
S18/S17 T24S R6W
New BT's: 6" R.Fir bears S.71°E. 6.0 ft. scribed 1/4 S17 CS BT.
8" R.Fir bears N.69°W. 45.8 ft. scribed 1/4 S18 CS BT.

James W. Byron
Milo Godfrey
Clete Putnam
March 25, 1960
C.S. File No. 49/83

Section Corner to Secs. 33 & 34, T24-6W, & Secs. 3 & 4, T25-6W 75
Reset from one O. B. T., others down.

Set 1 1/4" Iron Pipe, Remarkd:
14" Fir N.14°E., 16.8 feet
16" Fir N.16°W., 9.2 feet
36" Fir S.37°E., 136.2 feet
4" Fir S.48°W. 46.8 feet

G.G. Stewart
For Leatherwood
3/24/22
Recorded in
Vol. 3,
Page 112

1/4 Corner to Sections 3 and 10. 76
Found - Rotten Fir Snag N.12 1/4°W. 21.8 ft., good reverse scribing "1/4 S"
on small piece of wood lying at base of snag.
20" D.Fir S.70°E. 2.0 ft. Tree alive & in good condition.
Set - Brass Cap at cor. Mkd: County Surveyor's Office, T24SR6W 1/4 S 3
1962 S10
Reblz. & Scribe 20" D.Fir S.70°E. 2.0 ft. Mkd: 1/4 S10 CS BT.
New BT's: 27" D.Fir N.23°W. 44.1 ft. Mkd: 1/4 S 3 CS BT.
Corner lies on very steep East slope.

Section Corner to Sections 23 - 24 - 25 - 26. 77
Found - Sandstone Rock set in former renewal of Corner. Ren. #9
Oak, dead & down, S.10 1/4°E. 511.5 ft. Had been opened years ago.
Nearly all rotted away inside. fd. fragment of wood inside
with reverse scribing "W" & "S" still legible.
Oak, dead & down, S.50°W. 464.0 ft. Has not been opened. No
scar visible, bark gone.
Set - Brass Cap alongside Rock Mkd: County Surveyor's T24S R6W S23|S24
Office, 1962 S26|S25
New BT's: 6" W.Oak N.75 1/2°W. 50.7 ft. Mkd: S23 CS BT.
16" W.Oak N.58°E. 96.4 ft. Mkd: T24S R6W S24 CS BT.
7" W.Oak S.83°E. 167.2 ft. Mkd: T24S R6W S25 CS BT.
8" W.Oak S.32 1/2°W. 317.1 ft. Mkd: T24S R6W S26 CS BT.
A fence corner, fences East, West, & South, bears N.20°E. 10.0 ft.
Corner lies on S. slope of hill, near the top, top of hill nearly bare.

Milo E. Godfrey, Deputy
Mike Stone
October 23, 1962
C.S. File No. 49/83

Sec. Cor. to Secs. 33 & 34, T24-6W. & Secs. 4 & 3, T25-6W. 78
Found - 1 1/4" Iron Pipe set by Stewart in 1922. Ren. #75
26" Fir N.16°W. 9.2 ft. (to face) scribing visible on pitched
over face.
Stump Hole & Portions of Fir Roots N.14°E. 16.8 ft.
Rotten Fir Stump S.37°E. 136.2 ft., bark gone, no scribing found.
Rotten Fir Stump S.48°W. 46.8 ft., opened & fd. good scribing.
Stump Hole & fragments of Laurel Roots N.39°W. 72.6 ft. (Orig.)
Stump Hole with Bl. Oak growing out of one side, N. 1/4°E. 39.6 ft. (Orig.)
No trace of other Original Bearing Trees.
DID NOT SET BRASS CAP AT CORNER.
New BT's: 12" W.Oak S.74°W. 63.5 ft. Mkd: "T25S R6W S4 CS BT".
11" D.Fir N.28°E. 35.4 ft. Mkd: "T24S R6W S34 CS BT".
7" W.Oak S.32°E. 9.5 ft. Mkd: "T25S R6W S3 CS BT".
Corner lies in a N. & S. Fence Line.

Milo Godfrey & Crew.
C.S. File No. 49/123

Nov. 16, 1962

FD. B.C. M89-12
By R. WARE 1981
FD. B.C. 7/92
M. HELMOLD
M 112-50

FD. OK
6-94 By DeLaur
M 119-34