

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T.S. 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

cont.

A 16" Fir bears S71 1/2°E., 66.2 ft. scribed T24S R5W.,  
S6 CS BT

Dist. 67.50 @ -13° =

A 10" Fir bears S.57°W., 27.1 ft. scribed T24S R6W S1  
CS Bt.

Corner lies in wooded area (Madrone & Fir) is located  
at intersection of fences running southerly, easterly  
and Westerly. 4/22/75

L.B. Monrean  
A.V. Cangie  
4/22/75  
C.S. 57/21

Center 1/4 corner for Section 34. (See Also - Vol 3 PG 115) 112

Set - Brass cap

BT's - 8" D. Fir, bears S.7°W., 14.3 ft. scribed C 1/4 S34 BT.  
22" Madrone, bears N.82°E., 34.9 ft. scribed C 1/4 S34 BT.

Glenn Baughman  
For: Frederick  
Harrington  
May 1975  
M 56 - 16

SW Corner DLC #41

Set - Brass Cap

BT's - 8" White Fir, bears N.37°E., 6.3 ft. scribed SW DLC 41 BT.  
5" Madrone, bears S.11°W., 29.9 ft. scribed SW DLC 41 BT.

113

Section Corner for Secs. 7 and 18; and Secs. 12 and 13, T24-7 114

Found - 1/2" I.P. renewal by Grant. Ren. # 30

12" W. Fir bears N.38°E., 18.0 ft.

17" Madrone, N.36°W., 50.5 ft. now short snag.

2 Fir BT's down.

New BT - 12" Fir bears S.74°30'E., 59.4 ft. scribed S18 BT.

8/66

Don E. Garrett  
For: Resort Propertie  
Aug. 2, 1966  
M 33 - 8

1/4 Corner for Sec. 18 and Sec. 13 of T.24-7. F.O.K 12-92 115

Set - 5/8" Iron Rod. R. Dolan M116-38

BT - 10" White Oak bears N.3°15'W., 60.0 ft. scribed 1/4 S13 BT.

8/66

Township corner for Sec. 6; and Sec. 1 of T24-7; Sec. 31 of T23-6; 116  
and Sec. 36 of T23-7.

Found - All evidence of the orig. corner is gone.

Found a BLM brass cap reset by unknown party approx. 0.5 ft.  
from proper location. This corner was referenced by Doug.

Co. Surveyors Office in 1972 for road construction per notes  
attached to field notes this renewal.

Found a 5/8" I. Rod and PK nail in stump established as ref-  
erences for this corner, N.84 1/2°E.

The SE references have been destroyed.

We RESET the BLM brass cap at the proper location as determined by transit  
and chain from the County Surveyors references.

Found - From the 1957 dependent resurvey, a 22" now 23" G. Fir with well  
healed blaze bears N.74 1/2°W., 113.6 ft. (Rec. N.74 1/2°W., 116.8 ft.)

The NE bearing tree has been destroyed.

From the 1964 BLM resurvey correcting the 1957 dependent resurvey:

An 8" now 12" D. Fir alive with well healed single blaze  
bears N.63°E., 73.3 ft.

and a 15" now 17" I. Cedar with scribing "S R6W S6" visible on  
partially healed single blaze bears S.85°E., 107.6 ft.

RESET the BLM iron post with brass cap attached marked as described  
in the official record, flush in the shoulder of a dirt  
logging road. We add the markings "Reset 1977" to the brass cap.

No new accessories. We place steel fence post with survey marker witness  
sign attached approx. one foot west of brass cap.

8/29/77

117

Center 1/4 Corner for Sec. 19

Found - 1962 BLM brass cap properly marked set 4" above ground.

A 12" now 17" D. Fir bears N.16°E., 157.3 ft. (Rec. 160.4 ft.) with  
a single well healed blaze.

A 17" Maple is down, (rotted off at ground), bears approx. S.55°E. P. L. Earle

48.8 ft. with visible scribing in partly healed blaze. Doug. Co. Surveyors

New accessories:

A 2" + in center concrete bridge pier, 6" from top, bears S.58°W., 164.1 ft. Office

Note: Corner is at base of hill, 1.5 ft. west of fence which bears N.40°E. C.S. 59/42

and S.40°W., approx. 5 ft. south of cross fence, in drainage ditch. 11/14/77

Gary L. Langlitz, Doug. Co. Surveyors Office  
R. B. Kimberling - M. W. Cline  
Aug. 29, 1977  
C.S. 59/38

RENEWED CORNER NO. 136

JAN 96 1-79