

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 24 S. T.S. R. 6 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97101

129

Sec. Corner common to Secs. 4, 5, 8, & 9.
Found - 1958 County BCIP. REN. #43
BTs - 12" cedar snag bears N.26-1/2°W., 9.9-ft. Orig.
27" fir stump bears S.18°W., 37.0-ft., scribed "BT". Orig.
BTs fd. scribed & tagged - not of record:
6" fir N.53°W., 9.9-ft.
4" fir S.24°W., 3.3-ft.
4" fir S.32°E., 9.9-ft.
5" fir N.23-1/2°E., 6.3-ft. - - - 5/6/82

130

Center 1/4 Corner of Sec. 4.
Set - 5/8" x 36" I.R. & aluminum cap marked "LS 498".
New BTs- 9" maple S.36°E., 13.0-ft.
19" maple S.76°W., 7.8-ft. 5/6/82

131

Center 1/4 Corner for Section 2
Found - Bed rock marked X Ren. #34
C 1/4
Carved "B x O" in bedrock bears N.35°W., 17.5 ft. to marks.
30" fir with bark scribed "C 1/4 S2 BT" bears N.61°E., 81.3 ft.
Set - I drive "PK" nail 1/2" into center of carved "X" in bedrock.
New BTs - 9" fir scribed "C 1/4 S2 CS BT" in double blaze bears
S.13°W., 7.9 ft.
8" fir scribed "X CS BT" in double blaze bears S.63°W., 26.5 ft.
DCSO BT tags on all trees.

10/27/82

132

1/4 Corner for Sections 15 and 22
Found - 1973 BLM 3 1/4" dia. brass cap on a 2 1/2" O.D. I.P. firmly set and protruding 6" above ground.
(A search was made for orig. BTs in area. No evidence found.)
From the BLM 1973 resurvey:
23" dia. now a 25" dia. 1 foot tall Oak stump with a partially healed blaze, illegible scribing visible, bears N.30°E., 199.0' (Rec. N.30°E., 200.0 ft.)
A White Oak, 15" dia. now a 4 foot high double trunked (above base) Oak stump (with the easterly scribed trunk being 15" dia.) with a partially healed blaze, illegible scribing visible, bears S.78°W., 121.8 ft. (as per record)
Set - Monument position is perpetuated as found. Distance error to northeast BT could be a possible slope distance reduction problem
New BT - A 13" DBH B. Oak scribed "1/4 S22 CS BT" on a double blaze bears S.84 3/4°E., 288.7 ft.
New BT tags are nailed on found BT stumps.
Location in wide hollow between southerly and easterly facing ridges and approx. 150 ft. lower than ridgetop. Area is cleared for grazing. New BT is in large remaining wood lot easterly from monuments.

5/2/88

133

Section Corner for Sections 13 and 24; and 18 and 19 of T.24-5
Found - A 2 1/4" dia. brass cap, properly mkd., on a 1 3/8" O.D. iron pipe is firmly set with top bent 6" south of plumb position. Ren.#61
No evidence of previous monuments not found.
No evidence of original BTs is found.
A 12" B. Oak now a 14" DBH B. Oak with a possible healed blaze (center of tree burned out bears S.44°E., 42.9 ft. distant. (Rec. is S.41°E., 42.9 ft. Ren. #8)
Evidence of roots and roothole are found bearing approx S.41°W., 44.2 ft. distant. Ren. #61
Due to land clearing and cat work in area, no evidence of other BTs is found. Old fences run south and west from corner position
Set - Described found corner monument is to be covered by unstable fill slope and will not be easily occupied in future, therefore WE ESTABLISH a reference monument,; a 2 3/8" dia. brass cap mkd. "Douglas County Surveyors T24S Ref. Point R6W S13 S24 R5W S18 S19 N.45°W 60 ft. 1989 Office".
New BTs - (New accessories are tied to reference monument only)
A 20" DBH W. Oak scribed "T24S R5W S18 CS BT" on a double blaze bears N.49°E., 52.1 ft. distant.

Howard Johnstone, L.S. 498
For: Rsbg.Lmbr. Company
May 6, 1982
M 92 - 17

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
Karen Reed
Terrie Frannsen
(Plouff)
C.S. 62/1
Oct. 27, 1982

Douglas County
Surveyors Office
Stephen Flause
R. W. Smith
Deputies
May 2, 1988
C.S. 62/52

Douglas County
Surveyors Office
R. W. Smith
S. J. Flause
June 10, 1989
C. S. 62/63