

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97401

133

(CONT. from Prev. Pg.

Douglas County
Surveyors Office
R.W. Smith
S.J. Flause
June 10, 1989

A 20" DBH southeasterly trunk of a triple trunk W. Oak is scribed T24S R6W S24 CS BT on a double blaze. The center of the root crown of the triple trunk W. Oak bears S.74½°W., 12.1 ft. dist.
A 21" DBH D. fir scribed T24S R6W S13 CS BT on a double blaze bears N.66½°W., 144.6 ft. distant.
Monument lies on gradual SW slope on shoulder of ridge running from Northwest to Southeast.

C.S. 62/63

6/10/89

CORNER REPORT ONLY

Shaner Engineering
For: Western Timber
Company
July 1989
C.S. 63/96
RM 3 - 72

1/4 Corner for Section 31; and Section 6 of T.25-6
Found - 2½" iron pipe with a 3½" brass cap properly marked. (BLM)
18" D. fir face overgrown bears N.14 3/4°W., 72.6 ft.
30" D. fir face overgrown bears S.32°W., 29.2 ft. (Rec. 31.7)
The corner is North approx. 80 ft. from the top of a spur ridge that slopes down to SE. Many mistakenly blazed property lines and BTs in the area South of corner approx. 100 ft.

RE-REVIEWED SEE CORNER NO. #140 134

135

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Aug. 29, 1989
C.S. 64/1

1/4 Corner for Sections 7 and 8
Found - 1970 Doug. Co. 2½" dia. brass cap on a 1¼" O.D. x 30" long I.P. out of ground, up against base of orig. NE BT. Ren. #100
Fractured stone, largest piece measures 15"x9"x5" at position of corner, no marks found. (Orig. stone was 20"x12"x6", 15" in ground marked ¼ on west face)
45" now 46" dia. D. fir with a fully healed blaze, bears N.8¼°E., 11.9 ft. (agrees with rec.) Orig. BT.
18" now 36" dia. 4 ft. high D. fir stump with a metal cap on top. All bark gone from stump. A partially healed single blaze with scribing visible "4" (rescribed in Ren. #100) bears N.35°W., 31.7 ft. Orig. BT.
Set - Position of corner determined from bearings and distances to orig. bearing trees. 1970 DCSO BC/IP is set at referenced position and now protrudes 2" above ground, a mound of stone is set along northerly side of brass cap. The marks "RESET 1989" are added.
New BTs - 6" dia. D. fir, double blazed and scribed "¼ S7 CS BT" bears N.51°W., 51.0 ft.
8" dia. D. fir, double blazed and scribed "¼ S8 CS BT" bears S.01°E., 17.0 ft.
Corner lies on a steep North slope on a North-South cut line, new clear cut is to the West. Corner is approx. 150 ft. Northeast of landing at end of Road.

136

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Feb. 7, 1992
C.S. File 64/23

Tsp. Corner - NW Corner Section 6
Found - 3½" dia. BLM brass cap on iron pipe is flush with ground. (1957 BLM - reset 1977) Ren. No. 116
22" now 35" dia. Grand Fir with a fully healed single blaze, bears N.74½°W., 115.6 ft. (agrees w/ren. No. 116)
8" now 15" dia. D.Fir with a fully healed single blaze, bears N.63°E., 73.3 ft. (agrees w/rec.) 1964 BLM
15" now 22" dia. I.Cedar with a fully healed single blaze, bears S.85°E., 107.6 ft. (agrees w/rec. 1964 BLM)
New BT - 8" dia. D.Fir double blazed and scribed "T24S R7W S1 CS BT" bears S.45°W., 19.3 ft.

2/7/92

137

Mark Heimburger
AA Surveying
For: W.D. Henry
July 6, 1992
M 112-50

1/4 Corner for Sections 26 and 35
Set - A 2½" x 30" Alum. Pipe, 28" in the ground with a 3½" alum. cap marked:
T24S R6W
¼ S26
S35
RLS 2287
1992
from which a
11" B.Oak bears N.7°W., 133.8 ft. scribed "¼ S26 BT"
8" D.Fir bears S.87°E., 82.1 ft. scribed "¼ S35 BT"
Old fence corner bears S.75°W., 27.5 ft.

7/6/92