

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97126

SOUTH 1/4 SEC. 15 ONLY

1/4 sec. corner to secs. 15 and 22. *SEE ALSO M 71-69 #140*
Corner reset using erroneous corner to 15 and 22 (supposedly destroyed) which was set in 1893. Found 54 inch Fir stump, S.49°W., 18 lks, chopped out B T scribing. Found 48 inch Fir stump, N.51°E., 31 lks. with old face rotted out. *At 2.54 ch east*
Corner was reset 2.65 chs. east of old corner. (See orig. notes). I found Mad. stump bearing S.27°W., 25 lks. (O.B.T.) and stump hole of Fir bears N.87°W., 20 lks. (O.B.T.)
At corner point I set a 3/8 x 30 inch iron bolt from which
40 inch Fir bears N.40°15'E., 58.7 feet, mkd. 1/4 S 15 RE 3561 BT.
No other trees available.

Gene E. Johnson,
R.E. 3561,
May, 1956.
C. S. File No. 42/151.

RE-RENEWED, SEE CORNER NO. #17

~~1/4 corner to section 19, T24S, R7W., and section 24, T24S, R8W.~~
~~Found O. B. T. Fir snag, S.78E., 141 lks.~~
~~Set 3 inch x 3 inch x 48 inch D. Fir post for corner.~~
~~Blaze and scribe New B. T.s:~~
~~24 inch D. Fir, N.20°W., 7.0 feet mkd 1/4 S - 24 - R.E. 2741 - B.T.~~
~~12 inch Hemlock, N.68°E., 11.0 feet mkd. 1/4 S - 19 - R. E. 2741 - B.T.~~
SEE COR. #17 T24-RW.
NOT COMMON CORNER - E. 1/4 COR. SEC. 24 - T24-RW

Arthur R. Evans
For Martin Bros.
Box Co.
April 3, 1956.
C. S. File No. 42/198.

1/4 corner to secs. 10 and 11.
Found:
No evidence of corner post.
14 inch Yew-N.80°E., 91 lks. - badly rotted.
36 inch Cedar - N.64°W., 102 lks. - down.
Set:
12 inch x 12 inch x 14 inch stone with a "+" on top for the corner,
From which:
12 inch Cedar bears N.65°W., 6.4 feet, mkd. 1/4 S 10, B. T.
14 inch Hemlock bears S.57°30'E., 30.5 feet mkd. 1/4 S 11, B. T. (This tree forks at about 30 feet).
Note: All faces were painted with orange paint.
FD OK 4/96 des Roberts M123-73 + 1994 BLM BC.

G. Robert Lecklider
Feb. 28, 1957
C. S. File No. 42/232.

Section corner to secs. 21, 22, 27 and 28.
Found original 24 inch Fir (now 40 inches), S.15°E., 89.1 feet bark scribed T 24 S, R 7 W., S 27., in good condition. Found rotted stump (36 inches) S.15°E., 62.7 feet-shows old face but no scribing visible. Also found 5 foot snag, N.75°W., 29 feet with bark & face rotted - no scribing visible. The orig. SW. BT not found.
Set an iron pipe with brass cap at corner point mkd. Sec. cor. 21 22 28 27
T24S, R7W, County Surveyor's Office, 1957.
From which:
A 7 inch R. Fir, bears N.56°W., 12.0 feet, scribed S 21 CS BT.
A 22 inch R. Fir bears S.33°W., 54.4 feet, scribed S 28 T24S, R7W., CS BT.
A 24 inch R. Fir bears N.78°E., 78.2 feet scribed S 22 T24S, R7W., CS BT.

James W. Byron, Dep. County
Surveyor.
April 3, 1957.
C. S. File No. 47/172.

RE-RENEWED, SEE CORNER NO. 102

Section corner to secs. 24 & 25, T24S, R7W., and secs. 19 & 30, T24S, R6W.
Location for corner determined by proportional measurement.
Set a 4 inch x 4 inch fir post at corner point, from which:
16 inch DF bears S.41°20'W., 43.6 feet.
5 inch DF bears N.64°00'E., 24.5 feet.
24 inch DF bears S.16°00'E., 36.0 feet.
24 inch DF bears S.29°50'E., 45.3 feet.
(each marked RE 3937 BT.)

Clifford M. Bryden
February, 1956.
C. S. File No. 42/157.

1/4 Section Corner to sections 9 & 10.
Found - Original 16" now 40" Fir N.23°E., 10.6 ft. I open near base & find good scribing "S".
I find stump hole only for original S.W. BT.
Set Brass Cap at corner marked 1/4 S9/S10 T24S R7W County Surveyor's Office, 1957.
New BTs: 8" Hemlock bears S.70°E. 32.8 ft. scribed 1/4 S10 CS BT.
10" R. Fir bears S.20°W. 56.9 ft. scribed 1/4 S9 CS BT.

James W. Byron
M. Godfrey
S. Elow
Nov. 29, 1957
C. S. File No. 49/41

RE-RENEWED, SEE CORNER NO. #175

FD OK 4/96 L Roberts M123-73