

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Dep. County Surveyor  
M. Godfrey  
S. Bilow  
Nov. 29, 1957  
C. S. File No. 49/41

Section Corner to Sections 3, 4, 9, & 10. 30  
Found - 30"X16"X10" Sandstone at corner 18" out of ground. Checks  
record for size but I cannot find any notches I am sure of.  
Original 8" now 12" Fir rotted stump S.47°E. 60.7 ft. No Scbg. Fd.  
Orig. 14" now 24" Fir, down. I open & fd. scribe mks. S60°W. 13.2 ft.  
Orig. 40" now 50" Fir, shows good scar. I do not open. N34°W. 34.3'.  
Orig. 16" now 26" Fir N.55°E. 14.5 ft. shows good scar, I do not open.

Note - All check record dist. & bearing.  
Set Brass Cap at corner marked  $\frac{S4}{S9} \frac{S3}{S10}$  T24S R7W County Surveyor's Office, 1957.  
New BTs: 12" R. Fir bears S.30°W. 28.2 ft. scribed S9 T24S R7W CS BT.  
4" Hemlock " S75°E. 26.0 ft. scribed S10 T24S R7W CS BT.  
The original N.E. & N.W. BTs. alive & in good condition.

----- FD OK 4/9/6 L. Roberts M123-73

$\frac{1}{4}$  Section Corner to Sections 4 & 9. 31  
Found - Both orig. BTs. The 30" now 40" Cedar South 31.7 ft. has  
open face good scribing  $\frac{1}{4}$ S".  
Original 14" now 24" (Record Fir should be Hemlock) N.62°E. 15.2 ft.  
Shows good face, I do not open.

Set Brass Cap at corner marked  $\frac{1}{4} \frac{S4}{S9}$  T24S R7W County Surveyor's Office, 1957  
I Reblaze & rescribe the original South BT  $\frac{1}{4}$  S9 CS BT. Distance should be 33.2 ft. FD OK  
2/80 - L.  
ROBERTS  
M84-57

James W. Byron, Dep. County Surveyor  
M. Godfrey  
S. Bilow  
Dec. 3, 1957  
C. S. File No. 49/41

Section Corner to Section 7, 8, 17, & 18. 32  
Found - Original 10" now 18" W. Fir snag N.40°E. 28.4 ft. Has open  
face, good scribing.  
The S.E. & S.W. orig. BTs. would be in Log Road. I can find no  
trace of Original N.W. BT.

Set Brass Cap at corner marked  $\frac{S7}{S18} \frac{S8}{S17}$  T24S R7W County Surveyor's Office, 1957  
Note: Corner falls on cut slope at North Side of Log Road.  
New BTs: 13" W. Fir bears S.49 $\frac{1}{2}$ °E. 48.3 ft. scribed S17 T24S R7W CS BT.  
48" R. Fir bears N.62 $\frac{1}{2}$ °W. 27.0 ft. bark " S 7 T24S R7W CS BT.  
16" W. Fir bears N.41°E. 58.1 ft. scribed S 8 T24S R7W CS BT.  
6" W. Fir bears S.59 $\frac{1}{2}$ °W. 119.7 ft. scribed S18 T24S R7W CS BT.

Section Corner to Sections 8, 9, 16, & 17. 33  
Found - Orig. 12" now 24" Oak. This BT. is down. Sections have been cut  
& I find chips with reverse scribing "S 1", S.3°W. 204.6 ft.  
I can find no trace of the Orig. S.E. & N.W. BTs.  
Fence Corner bears East 3.0 ft.

Set Brass Cap marked  $\frac{S8}{S17} \frac{S9}{S16}$  T24S R7W County Surveyor's Office, 1957.  
New BTs: 13" R. Fir bears S.16 $\frac{1}{2}$ °W. 22.8 ft. scribed S17 T24S R7W CS BT.  
14" R. Fir bears S.76°E. 8.4 ft. scribed S16 T24S R7W CS BT.  
14" W. Oak bears N.53 $\frac{1}{2}$ °E. 23.0 ft. scribed S 9 T24S R7W CS BT.  
10" R. Fir bears N.26°W. 36.2 ft. scribed S 8 T24S R7W CS BT.

Section Corner to Sections 1, 2, 11, & 12. 34  
Found - All Original BT's. FD B.C. By Charles Gault  
7/80 M79-52  
The S. E. BT. now snag - Shell Only.  
The N. W. BT. alive & good condition, open face shows good scribing.  
The S. W. & N. E. BT's alive. I do not open.

All check bearings & distances.  
Set Brass Cap marked  $\frac{S2}{S11} \frac{S1}{S12}$  T24S R7W County Surveyor's Office, 1958  
New BT's: 14" Forked B. Oak bears N.11°E. 6.5 ft. scribed T24S R7W S1 CS BT.  
48" B. Oak bears S.3°W. 47.7 ft. scribed T24S R7W S11 CS BT.  
7" W. Oak bears S.55 $\frac{1}{2}$ °E. 31.8 ft. scribed T24S R7W S12 CS BT.  
15" W. Oak bears N.81°W. 109.0 ft. scribed T24S R7W S2 CS BT.

James W. Byron, Deputy  
M. Godfrey  
S. Bilow  
April 10, 1958  
C. S. File No. 49/41

RE-RENEWED CORNER NO. #159