

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

75

C.S. 49/41

$\frac{1}{4}$  Section Corner to Sections 5 and 6.  
Found - Orig. 20", now 30" R. Fir N.62°E. 3.3 ft. I open & find good scribing "BT".  
Orig. N. W. BT., now down & mostly rotted, checks bearing & distance to stump section.  
Also find  $\frac{1}{2}$ " Iron Pipe 1.0 ft. South.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
New BT's: Rescribe, now 30" R. Fir N.62°E. 4.1 ft.  $\frac{1}{4}$  S5 CS BT.  
8" W. Fir bears S.48°W. 9.3 ft. scribed  $\frac{1}{4}$  S 6 CS BT.

RE-RENEWED, SEE CORNER NO. #183

76

Renew 

S 1	T24S
R8W S12	R7W

  
Found - Orig. 20", now 20" R. Fir N.39°W. 51.5 ft. I open & find good scribing "S". This BT was 8" when scribed.  
I find down Firs that check record for S. E. & S. W. BT's.  
No trace of Orig. N. E. BT.  
Set - Brass Cap at Corner Mkd: 

S1	T24S
R8W S12	R7W

 County Surveyor's Office, 1959  
New BT's: Rescribe Orig. 20" R. Fir N.39°W. 51.5 ft. S1 T24S R8W CS BT.  
10" R. Fir bears S.69°W. 12.7 ft. scribed S12 T24S R8W CS BT.

East  $\frac{1}{4}$  Corner to Section 12, T24S R8W.  
Found - Orig. 30", now 45" Fir Stump N.80°E. 18.5 ft. I open & find good scribing "BT".  
Orig. 24", now 52" Fir Stump, shows good bark scribing "BT" S.22°W. 11.9 ft.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1959  
New BT's: 8" W. Fir bears S.60 $\frac{1}{2}$ °W. 32.1 ft. scribed  $\frac{1}{4}$  S12 CS BT.  
8" Cedar bears N.69°W. 36.3 ft. scribed  $\frac{1}{4}$  S12 CS BT.

Closing Corner Sections 6 and 7.  
Found - Orig. 50" Fir, now 55", previously opened, shows good scribing "24SW".  
Orig. 40", now 48" Fir S. 2°E. 23.1 ft.  
Orig. 24", now 48" Fir S. 64°W. 22.4 ft.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
New BT's: 12" R. Fir bears S.82°E. 34.2 ft. scribed S7 T24S R7W CS BT.  
6" R. Fir bears N.70°E. 28.4 ft. scribed S6 T24S R7W CS BT.

Renew 

T23S	R7W
R8W S1 / S6	R7W
T24S	

  
Found - Orig. 36", now 48" Fir N.38°W. 56.1 ft. Old face dest. by fire.  
Orig. 36", now 42" Fir S.57°E. 54.8 ft. Old face dest. by fire.  
Orig. 48", now 65" Fir S.10°W. (Record S.57°E) 79.2 ft., now stump shows rotted face.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
New BT's: 4" R. Fir bears S.13°W. 15.4 ft. scribed S1 CS BT.  
Rescribe, now 42" R. Fir S.57°E. 54.8 ft. CC S6 T24S R7W CS BT.  
SEE NEW BT'S - REN. NO. 98

$\frac{1}{4}$  Section Corner to Sections 17 and 18.  
Found - Orig. 20", now 44" Cedar, We open & find good scribing " $\frac{1}{2}$ S", N. 9°W. 7.3 ft.  
Orig. 12", now down Yewwood, partly rotted, no scribing found, S.54°E. 16.5 ft.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
New BT's: 11" R. Fir bears S.65°E. 24.5 ft. scribed  $\frac{1}{4}$  S17 CS BT.  
Rescribe Orig., now 44" Cedar N.9°W. 7.3 ft.  $\frac{1}{4}$  S18 CS BT.

June 5, 1961

James W. Byron, Deputy  
For Martin Box Co.  
Wit: M. Godfrey  
C. Putnam  
Dec. 21, 1959  
C. S. File No. 52/6

James W. Byron  
Milo Godfrey  
Clete Putnam  
September 1960  
C. S. File No. 49/41

4/6/96  
NOTE:  
B.C. DESTROYED  
BY FALLING TREE.  
B.L.A. REPLACED  
WITH THEIR CAP.  
PER JAKE JELLEY.  
B.L.A. CHASTEN  
ENG. by

RE-RENEWED, SEE CORNER NO. #104

RE-RENEWED, SEE CORNER NO. #98

78

79

80