

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

**92**  
 $\frac{1}{4}$  Corner to Sections 8 and 17.  
 Found - 44" White Oak N.10°W. 21.1 ft., opened scar and found good scribing "S". Tree rotten in center, appears to be dying.  
 Uprooted Oak, near location for S. E. Tree, S.85°E. 39.6 ft. Cannot determine exactly where tree stood. Found good reverse scribing " $\frac{1}{4}$ S".  
 Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R7W  $\frac{1}{4}$  S 8 Office, 1963 S17  
 New BT's: 10" D. Fir N.47°W. 36.2 ft. Mkd:  $\frac{1}{4}$  S 8 CS BT.  
 10" D. Fir S. 45°E. 17.0 ft. Mkd:  $\frac{1}{4}$  S17 CS BT.  
 Corner lies in fence corner, fences South & East from corner. Also fence Posts continuing North from corner.

Milo E.  
Godfrey & Crew  
May, 1963  
C. S.  
File  
No. 49/41

**93**  
 Closing Corner to Sec. 36, T24-7W. & Secs. 1, T25-7W.  
 Found - 50" D. Fir S.59 $\frac{1}{2}$ °W. 42.9 ft. Old bark scribing visible. Faces Corner  
 60" D. Fir N.49°W. 37.0 ft. Bark shows evidence of having been flattened off with axé. Bark badly burned & flaked off. No scribe marks found.  
 Did not find S.E. tree called for in notes.  
 Rotten Fir Snag S.10°W. 14.3 ft. with portion of old face, showing fragments of scribe marks. At time it was faced off tree would have been 12" to 15". Face & scribing faces approx. N.40°W., not toward cor. as set from 2 BT's.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R7W CC S36 S1 R6W T25S S1  
 New BT's: 13" D. Fir N.30°W. 111.0 ft. Mkd: T24S R7W CC S36 CS BT.  
 28" I. Cedar N.31°E. 99.2 ft. Mkd: CC T24S & 25S R7W CS BT.  
 No trees available to S.W. except old, overripe & half dead D. Firs. Did not mark new SW. tree. Cor. lies approx. 10' W. of logging road, nearly at south end of road.

Milo E. Godfrey, Deputy County  
Vernon Tracy & Mike Stone  
July and August 1963  
C. S. File No. 49/123

~~$\frac{1}{4}$  Section Corner to Sections 24 and 25. - S.B. in T25-7W.  
 Found - 1" Iron Rod (buried), set by B.B. Irving, 1932.  
 40" Bl. Oak N.82 $\frac{1}{2}$ °W. 77.2 ft., has been previously opened and face entirely rotted away.  
 18" W. Oak S.3 $\frac{3}{4}$ °W. 92.4 ft., shows faint scars. Did not open.  
 Set - Alongside I. Rod at Cor. Brass Cap Mkd: T25S R7W  $\frac{1}{4}$  S24 County Surveyor's Office, 1963 S25  
 Blaze & Rescribe 18" W. Oak S.3 $\frac{3}{4}$ °W. 92.4 ft. Mkd:  $\frac{1}{4}$  S25 CS BT.  
 New BT: 13" W. Oak N.18 $\frac{1}{2}$ °W. 125.1 ft. Mkd:  $\frac{1}{4}$  S24 CS BT.  
 Note - Found Stump Hole & Young Bl. Oak at location of Orig. N.W. BT., N.51°W. 124 ft. Location for Orig. SW. BT. is now out in river.~~

**94**  
 Closing Corner for Sections 1 and 12, T24-8W.  
 Found - 10" D. Fir S.69°W. 12.7 ft. (renewed BT., now a stump)  
 20" D. Fir N.39°W. 51.5 ft. (Orig. BT., now 26" stump)  
 Scribed: 8" W. Fir S. 5° W. 48.5 feet  
 7" W. Fir N. 61° W. 41.1 feet.  
 Note - Corner falls in west lane of logging road therefore, no iron pipe was set.

By Howard W.  
Johnstone  
For Rsbrg. Lbr.  
Wit: Henrickson  
& Clark  
C. S. File  
No. 51/163

**95**  
 Closing Corner on S. Line Sec. 13. S13 S 23/S 24  
 Found - 1" Steel Shaft alongside Rock at Corner, buried in mud from roots of uprooted BT.  
 50" Fir N.80°E. 22.4 ft., scribing still visible in open scar, scribing still visible in nearly all pitched over.  
 The 36" Fir S.39°W. 17.8 ft. is uprooted & down.  
 New BT: 20" D. Fir S.26°W. 41.8 ft., Mkd: T24S R7W CC S23 CS BT.  
 Note - Found O.K. Cor. Secs. S14/S13 T24S R7W, Brass Cap & both BT's. mkd. in 1958 S23 still in good condition.

Milo E. Godfrey  
& Crew  
Jan. 13, 1964  
C.S. File  
No. 49/41

RE-NEWED NO. #105  
 APR 24 1964 M121-64 DLAN SEE REN # 40  
 APR 10 1965 M123-6 Berty