

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 7 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

96

Sec. Corner to Sections 22 - 23 - 26 - 27  
Found - Orig. 20", now 44" Fir S. 71° W. 19.8 ft., shows very old bark scribe, mostly fragmentary, "S or 2".  
Laurel Remnants & Stump Hole N. 30° E. 19.1 ft., no scribe found & stump holes for other 2 Orig. BT's., gone completely.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  $T24S \frac{S \ 22}{S \ 27} | \frac{S \ 23}{S \ 26} R7W$   
New BT's: 24" D. Fir N. 47° E. 43.3 ft. Mkd: T24S R7W S23 CS BT.  
6" W. Fir S. 58° E. 28.4 ft. Mkd: S 26 CS BT.  
9" W. Fir N. 36° W. 7.5 ft. Mkd: T24S R7W S22 CS BT.  
11" D. Fir S. 44° W. 58.1 ft. Mkd: T24S R7W S27 CS BT.  
Feb. 2, 1966

Vernon "Ray" Tracy  
Mike Stone & J. Layne  
B. Bright & T. Watts, BLM  
February 1966  
C. S. File No. 49/47

$\frac{1}{4}$  Corner to Sections 27 and 26.  
Found - Orig. 18", now 34" Fir S. 60° W. 21.8 ft., prev. opened & shows "1/4 S" scribe. Alive.  
Orig. 30", now 48", Fir N. 24° E. 39.6 ft. Down & out of place, several cruiser's marks on bottom side.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  $T24S \ S \ 27/S \ 26 \ R7W$   
New BT's: 17" D. Fir N. 23° E. 61.6 ft. Mkd:  $\frac{1}{4}$  S26 CS BT.  
16" W. Fir S. 32° W. 18.3 ft. Mkd:  $\frac{1}{4}$  S27 CS BT.  
Note - Corner is approximately 50 ft. North of small creek, course West.  
Feb. 2, 1966

Closing Corner to Sections 1 & 6, T24S., R's. 7&8 W.  
Found - County Brass Cap, properly mkd. as recorded in Ren. #79,  
 $T \ 23 \ S$   
 $R8W \ S \ 1/S \ 6 \ R7W \ T24S$   
All BT's. down & dead or gone completely.  
New BT's: 8" W. Fir East 32.8 ft. Mkd: "CC T24S R7W S 6 CS BT."  
6" D. Fir S. 55° W. 74.2 ft. Mkd: "CC S 1 CS BT".  
Note - This corner lies 30 ft. south of old logging road.  
April 18, 1966

$\frac{1}{4}$  Corner to Sec. 4, T25-7W, only.  
Found - BT. as recorded in Ren. #62, as follows:  
34" Fir N. 52° E. 30.5 ft., turned out, shows "CS BT" scribe on unhealed face.  
Possible Orig. 12" Fir N. 37° E. 15.8 ft., shattered stump, No scribe found.  
Orig. S.E. BT., now turned out stump, out of position.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966  $T24S \ R7W \ \frac{1}{4} \ \frac{S \ 23}{S \ 4}$   
New BT's: 5" D. Fir S. 63° E. 92.2 ft. mkd:  $\frac{1}{4}$  S 4 CS BT.  
14" W. Fir N. 8° E. 64.8 ft. Mkd:  $\frac{1}{4}$  S 4 CS BT.

V. "Ray"  
Tracy & Crew  
May 2, 1966  
C. S. File  
No. 54/10

$\frac{1}{4}$  Corner to Sections 1 and 12.  
Set - 1" x 1" x 36" T. Iron  
No Bearing Tree.

July 14, 1965

Wilford N.  
Haines  
Map File  
M 30 - 15

$\frac{1}{4}$  Corner to Sections 12 and 13.  
 $\frac{1}{4}$  Corner set by Single Proportionate Measurement.  
SET - 5/8" Iron Rod  
No Witness trees available.  
August, 1966

Don E.  
Garrett  
M 33 - 8

RE-RENEWED, SEE CORNER NO. #133

RE-RENEWED, SEE CORNER NO. #153

97

98

99

100

101