

Douglas County Surveyor's Record of  
Government Corners Renewed

T.24 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

102

Section Corner to Sections 21 - 22 - 27 - 28.

Found - C.S. Brass Cap set & mkd. in 1957, See Ren. #27.  
7", now 10" D. Fir N. 56° W. 12.0 ft., nearly healed blaze.  
Fir Bearing Tree to S.W., now Stump.  
N.E. BT., gone. Orig. BT's, gone.

New BT's: 5" D. Fir S. 60° E. 34.9 ft. mkd. S 27 CS BT.  
5" D. Fir N. 85° E. 53.2 ft. mkd. S22 CS BT.

Note - Very recent logging around this corner would account for  
BT's. being destroyed. Corner lies on N. slope approx. 400 ft.  
west of new logging road.

Nov. 23, 1966

Vernon "Ray"  
Tracy &  
Crew  
11/23/66  
C. S.  
File  
No. 49/41

E. 1/16th Corner to Sections 21 and 28.  
Set - 5/8" Iron Rod

103

May, 1967

D. Garrett  
May, 1967  
M 34 - 32

Cl. Corner to Sections 6 and 7 only.

Found - C.S. Brass Cap, firmly set, See Ren. #78. SEE ALSO RENEWAL #134

Orig. 55" Fir ( Snag) to N. E. shows scribe marks.  
Orig. 24", now 48" Fir, S. 64° W. 22.4 ft., alive, top of scar  
visible in logging road fill.

Orig. S.E. BT, turned out & slid downhill approx. 15 ft.

Re-New BT's: 12", now 14" D. Fir S. 82° E. 34.2 ft., alive, top broken  
out, healed blaze.

6" D. Fir, turned out, N. 70° E. 28.4 ft., scribe visible

New BT: 7" W. Fir N. 60° E. 22.4 ft. mkd. T24S R7W S 6 CC CS BT.

Note - This corner lies 50 ft. E. of old logging road, course N.W.  
on steep easterly slope. Oct. 10, 1967

104

105

Sec. Cor. to Sections 1 & 12 only, T24-8W, T.24-8

Found - BT's. as recorded in Ren. #13 & #94. T.24-7  
Orig. 20" D. Fir, now shattered Snag, N. 39° W. 51.5 ft., scribe vis.  
No trace of other Original Bearing Trees.

10" D. Fir, now 6' high stump, S. 69° W. 12.7 ft., scribe visible.

8", now 10" W. Fir, Alive, S. 5° W. 48.5 ft., scribe visible.

7", now 12" W. Fir, alive, N. 61° W. 41.1 ft., nearly healed blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S  
(Set 6' Steel Fence Office R 8 W S 1 R7W  
Post alongside Br. Cap) 1967 S 12

Note - This corner lies on left shoulder of old logging road, 5' E. ditch.  
Oct. 10, 1967

MICROFILM TO HERE 10/67

Vernon "Ray" Tracy  
Jack Heritage & V. Perron  
October, 1967  
C. S. File No. 54/55

106

1/4 Corner Sections 3 & 2

Found - 1955 C. S. Brass Cap in mound of stone on right bank of creek (Ren. #19)  
reset by O.S.H.D. See attached letter & sketch. BT's gone. Mkd. new  
BT's 15" D. Fir N. 43° W 128.7 Ft. Mkd. 1/4 53 CS BT  
7" D. Fir S. 55° E 173.0 ft. Mkd. 1/4 S2 CS BT  
Set steel fence post along side brass cap. Cor. lies 10ft. N. of Creek  
course N.W. 5-15-69

Witness Corner to Sec. Cor. 31 & 32, T24-7W & Secs. 6 & 5, T25-7.

Set - Brass Cap and Marked Bearing Trees:  
21" Cedar N. 47° W. 11.0 ft. scribed W.C. S32T24S R7W BT.  
12" Oak S. 60° W. 32.4 ft. scribed W.C. S 5 BT.  
12" Cedar N. 3° E. 5.3 ft. scribed W.C. X BT.

1/4 Corner to Sec. 32, T24-7W. and Sec. 5, T25-7W.

Set - Brass Cap and Marked Bearing Trees:  
11" Hemlock S. 73° E. 14.3 ft. scribed 1/4 S 5 T25S R7W BT.  
12" Cedar N. 31° E. 31.5 ft. scribed 1/4 S32 T24S R7W BT.  
See letter in C.S. File No. 55/140

March 9, 1970

108

Larry D. Bishop  
For Glanville  
3/9/70 Map M 33 - 68

RE-RENEWED SEE CORNER NO. #151