

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

116

Section Corner to Sections 29 - 30 - 31 - 32.

Found - 2"x2"x20" sq. Iron Pipe at Sec. Cor. O.K., Ren. #3.
14", now 20" B.Oak, N.41°W. (Rec. 41.5 ft.) 27.7 ft., shows good scars.
12", now 14" W.Oak, S.22°E. (Rec. 51.7 ft.) 33.7 ft., opened for scribe, "BT" reverse, face rotted.
15", now 18" W.Oak, S.52°W. (Rec. 63.0 ft.) 41.5 ft., shows good scars.

Note - These record distances must have been in links, as they check out for distance in feet. All bearing hit very good.

2"x2" Iron Pipe is flush with ground, 1.0 ft. south of fence corner, fence runs north and east.

New BT's: 8" D.Fir N.50°E. 8.3 ft. scribed "T24S R7W S28 CS BT".

9" D.Fir S.37°E. 14.8 ft. scribed "T24S R7W S33 CS BT".

Note - See Map File M 40 - 58.

John M. Powell & Crew
C. S. File No. 49/41
FOUR PER JOHNSON
M104-16 NBY-87
FOUR 1/91 M11-25
FOUR 3/95 M121-73

12/2/70

117

1/4 Corner to Sections 29 and 30.

Found - Orig. 18", now 28" W.Oak, S.32°E. 18.5 ft. (Rec. S26E),
alive, previously sawed open by D. Garrett & shows #158
"S" scribe, rings very fine & difficult to count.
Orig. 12", now 39" W.Oak, alive, S.76°W. 136.3 ft., shows
very faint scars. Reshd: "1/4 S30 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 7 W
Office, 1971 1/4 S 30 | S 29

New BT: 24" W.Oak N. 72°E. 59.2 ft. mkd: "1/4 S29 CS BT".

This corner lies on N. edge of bench in large field with scattered large oaks.

1/26/71

Vernon "Ray" Tracy
V. Perron
C.S. File No. 49/41

118

MARCH 71

Section Corner to Sections 14 & 15 and 22.

Found - 16" Chinquapin corner tree, stump, rotten center. In
center of corner tree I place a Brass cap* mkd.
County Surveyors Office T 24 S R 7 W Ren. #43
1958 S 15 S 14
S. 22

from which a:

- 32" D. Fir, original BT stump, scribing visible. Bears N.40°E., 22.4 ft. (Record 48" dia., N.45°E.)
- 12" D. Fir, Scribing visible. Bears N.48°E., 63.7 ft.
- 30" D. Fir, original BT, snag, burned and rotted. Bears S.68°W., 15.2 ft.
- 30" D. Fir, Face visible. Bears N.50°W., 20.7 ft.
- 12" Dogwood, original BT, now rotted stump. Bears N.72°W. 9.9 ft.
- Rotted Douglas fir root stump, possible original BT. Bears N.79°W., 33.0 ft.

*Brass cap did bear N.76°W., 1.4 ft. from corner tree.

1/8/73

U.S. Bureau of Land Mgt.
Bruce Shaner Engineering
M 49 - 6
January 8, 1973

119

Section Corner for Secs. 33 and 34 only T24-7.

Found - 3/4" x 18" Iron rod.
18" Orig. D. Fir snag, face vis. bears N.20°W., 24.4 ft.
(to face)
32" D. Fir, scribing vis. bears N.21°E., 58.0 ft.
28" Orig. D. Fir snag, face vis. bears N.61°E., 42.2 ft.

Set - Brass cap mkd. T24S, R7W, WM S33, S34, CC 1972.

Note - Tie to Sections 3 and 4, T25-7, S89°01'E., 204.61 ft.
(3.10 chains). (Record East, 207.24 ft. (3.14 chains))

120

CC Corner for Secs. 4 & 3 only, T25-7.

Found - Wooden stake at CC for 4 & 3. Ren. No. 63.
Orig. 20" D. Fir, snag, bears N.43°E., 14.5 ft.
14" Fir, down, burned, and rotted, bears S.66°E., 12.5 ft.
Stumphole with the burned remains of a cedar stump, bears S.65°W., 12.5 ft.

Set - Hub and Tack.

U.S. Bureau of Land Management
By Shaner Engineering
M 49 - 7
Dec. 11, 1972