

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 7 R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21881

North 1/4 Corner for Section 4
Set - 5/8" x 30" Rebar at corner
BT's - 32" Fir, S.12°E., 41.9 ft. "1/4 S4 BT".
6" Grand Fir, S.25°W., 24.2 ft. "1/4 S4 BT".

129

William Eimstadt
For: International
Paper Co.
July 1976
M 61 - 14

7/76

Section Corner for Secs. 12 and 13; and Secs. 7 and 18 of T24-6
Found - 1/2" I.P. renewal by Grant. Ren. #16
12" W. Fir bears N.38°E., 18.0 ft.
17" Madrone, N.36°W., 50.5 ft. now short snag.
2 Fir BT's down.

130

Don E. Garrett
For: Resort Properties
Aug. 2, 1966
M 33 - 8

New BT - 12" Fir bears S.74°30'E., 59.4 ft. scribed S18 BT.

8/66

1/4 Corner for Sec. 13 and Sec. 18 of T.24-6.
Set - 5/8" I. Rod
New BT - 10" White Oak bears N.3°15'W., 60.0 ft. scribed 1/4 S13 BT.

131

8/66

Township corner for Sec. 1; and Sec. 6 of T.24-6; Sec. 31 of T.23-6 and Sec. 36 of T23-7.

132

Found - All evidence of the orig. corner is gone.
Found a BLM brass cap reset by unknown party approx 0.5 ft. from proper location. This corner was referenced by Doug. Co. Surveyors Office in 1972 for road construction per notes attached to field notes this renewal.

Found a 5/8" I. Rod and PK nail in stump established as references for this corner, N.84 1/2°E.

The SE references have been destroyed.

We RESET the BLM brass cap at the proper location as determined by transit and chain from the County Surveyors references.

Found - From the 1957 dependent resurvey, A 22" now 23" G. Fir with well healed blaze bears N.74 1/2°W., 115.6 ft. (Rec. 116.8 ft.)

The NE bearing tree has been destroyed.

From the 1964 BLM resurvey correcting the 1957 dependent resurvey: an 8" now 12" D. Fir alive with well healed single blaze bears N.63°E., 73.3 ft.

and a 15" now 17" I. Cedar with scribing "S R6W S6" visible on partially healed single blaze bears S.85°E., 107.6 ft.

RESET the BLM iron post with brass cap attached marked as described in the official record, flush in the shoulder of a dirt logging road. We add the markings "Reset 1977" to the B.C.

No new accessories. We place steel fence post with survey marker witness sign attached approx. one foot west of brasscap.

8/29/77

132A

South 1/16 Corner for Secs. 8 and 9.
Found - 1" x 36" I. Pipe with 1960 brass cap mkd. "County Surveyors Office" T24S R7W
An orig. 24" Fir, now a 28" snag bears S.45°W., 19.2 ft. to face, WC 38.89 South 1/16 Cor. 1960
No visible scribing, snag burned and rotten. Ren. #70

A 12" R. Fir, now 18" bears N.62 1/2°W., 10.4 ft. with well healed double blaze.

A 16" R. Fir bears S.72°E., 7.0 ft. with well healed double blaze.

Renewal- x'd out W.C. on cap - stamped 1979 on it in addition to 1960.
Cap at appropriate brg. & dist. from original BT.

4/16/79

Karen Reed
P.L. Earle
Doug. Co. Surveyors Office
C.S. 60/24

133

Closing Cor. for Sec. 6; and Sec. 1 of T.24S. R.8W.

Set - 1 1/2" I. pipe and Brass Cap at true intersection.

BT's - 12" Fir bears S.62°W., 64.1 ft.

8" Fir bears S.55°E., 11.2 ft.

Note - Corner lies 2.28 ft. south of Cor. Renewal #98.

Les Roberts
Triangle Eng. Co.
For: International
Paper Co.
M 80 - 47
1979

RE-RENEWED, SEE CORNER NO. #155

3/77

Gary L. Langlitz, Doug. Co. Surveyors
Office
R. B. Kimber - M. W. Cline
Aug. 29, 1977
C. S. 59/38

JAN 78
1-79

RE-RENEWED, SEE CORNER NO. #138