

Douglas County Surveyor's Record of
Government Corners Renewed

24

T. S.

8

R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 97196

Arthur R. Evans
For Martin Bros.
Box Co.
April 3, 1956.
C. S. File No.
42/198.

~~CORNER NOT COMMON - SEE CORNER NO. 1617 LATER RENEWAL
DESTROYED B.T.s.
corner to section 24, T24S, R8W., and section 19, T24S, R7W.
Found O. B. T. Fir snag, S.78E., 141 lks.
Set a 3 inch x 3 inch x 48 inch D. Fir post for corner.
Blaze and scribe New B. T.s:
24 inch D. Fir, N.20°W., 7.0 feet mkd. $\frac{1}{4}$ S- 24 - R. E. 2741 B. T.
12 inch Hemlock, N.68°E., 11.0 feet mkd. $\frac{1}{4}$ S - 19 - R. E. 2741 B. T.~~

REFER TO C.S. File # 49/41

Arthur R. Evans
Work done for the Martin Bros. Box Co.
March 21, 1956.
C. S. File No. 42/206. (no map)

~~Closing corner to sections 33 and 34. (on South bdy. of Twp.)
Found O. B. T. for Sec. 3, T25S, R8W., a 60 inch D. Fir, S.89°E., 10 lks. -
scribe marks destroyed in 1911 survey - all other trees gone.
Set a 3 inch x 3 inch x 48 inch Fir stake at corner point.
Blaze and scribe 2 new B. T.s:
9 inch Hemlock, N.35°W., 29.7 feet (to centerline) mkd. T 24, R 8, S 33,
R. E. 2741 B. T.
36 inch D. Fir, N.45°E., 27.4 feet (to centerline) mkd. T 24, R 8, S 34,
R. E. 2741 B. T. (Bark scribe).
Yellow tag- "Grant and Evans" on N. E. B. T. Y. T.- (G.L.O.) on O. B. T.~~

SEE CORNER NO. 8
CORNER NOT COMMON
? See LATER
File 49/88
IN T 25/R8

~~Section corner to secs 34 and 35, T24S, R8W., and secs 2 and 3, T25S, R8W.
Found 2 O. B. T.s: (1911)
18 inch Fir, S. 5°E., 50 lks.
30 inch Cedar, (Inc.) S.28°W., 25 lks.
Set 4 inch x 4 inch x 36 inch Fir stake.
Rescribe O. B. T.s.
Blaze and scribe 2 new B. T.s:
20 inch D. Fir, N.31°W., 25.2 feet (to centerline) mkd. T24, R8, S 34,
RE 2741 - B. T.
14 inch D. Fir, N.36°E., 29.6 feet (to centerline) mkd. T24 - R8 - S 35,
RE 2741 - B. T.
Y. T. (G.L.O.) on N. W. B.T.
Plain yellow tag and G. L. O. warning sign on S. E. B.T.~~

Section Corner common to Secs. 23, 24, 25, & 26.
Found - All four of Chandler's BT's., All alive & in good condition.
The N.E. & N.W. BT's have open faces & good scribing.
All check bearings & distances. Chandler apparently used
slope distances.
Set Brass Cap at Corner Mkd: $\frac{S23}{S26} | \frac{S24}{S25}$ T24S R8W County Surveyor's
Office, 1958.
I use same BT's: Measurements horizontal & to Center of Tree:
22" Cedar N.9° W. 20.7 ft.
60" R.Fir N.35°E. 28.1 ft.
60" R.Fir S.40°E. 23.4 ft.
36" R.Fir S. 5°W. 30.2 ft.

JAMES W. BYRON, Deputy County Surveyor
M. Godfrey
S. Bilow
May 1, 1958
C. S. File No. 49/84

Section Corner common to Secs. 25, 26, 35, & 36.
Found - Orig. 18", now 32" R.Fir S.80°E. 27.7 ft. I open & find good
scribing "8".
Orig. 18", now 32" R.Fir N.85°E. 34.3 ft., shows good scars.
I do not open.
Rotted Base of Large Fir that checks bearing & dist. for Orig.
S.W. BT.
No trace of Orig. 6" Chinquapin Found.
Set Brass Cap at Corner Mkd.: T24S R8W County Surveyor's $\frac{S26}{S35} | \frac{S25}{S36}$
Office, 1958
New BT's: 10" Hemlock bears N.72°W. 27.2 ft. scribed S26 T24S R8W CS BT.
7" W. Fir bears S.51°E. 18.7 ft. scribed S36 T24S R8W CS BT.
4" R. Fir bears West 19.6 ft. scribed S35 CS BT.
16" Cedar bears N.75°E. 42.0 ft. scribed S25 T24S R8W CS BT.

~~$\frac{1}{4}$ Section Corner to Sections 23 & 24.
Found - Both Orig. BT's. Both alive & in good condition & both check for
bearings & distances. I open the N.E. BT. & find good scribing "S".
I do not open the S.W. BT., shows good scar.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S23/S24 T24S R8W County Surveyor's Off., 1958.
New BT's: I rescribe, now 35" R.Fir N.75 $\frac{1}{2}$ °E. 66.7 ft. $\frac{1}{4}$ S24 CS BT.
12" R. Fir S.47 $\frac{1}{2}$ °W. 40.2 ft. scribed $\frac{1}{4}$ S23 CS BT.~~

RE-RENEWED SEE CORNER NO. 107