

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 8 R. W. W. M.

Section Corner to Secs. 35 & 36, T24S, R8W, & Secs. 1 & 2, T25S, R8W. <sup>7</sup>  
Found - Orig. 40", now 40" Fir Snag S.5°W. 13.2 ft. Shows faint but  
clear bark scribing "S2 R8W BT".

Rotted Base of large Fir that checks bearing & distance for  
N. W. BT. ~~29~~

Orig. N.E. BT. down, checks for bearing & distance.

Set Brass Cap at Corner Mkd:  $\frac{S35}{S2} | \frac{S36}{S1}$  T24S R8W County Surveyor's  
T25S R8W Office, 1958.

New BT's: 30" Cedar bears N.38°W. 24.9 ft. scribed S35 T24S R8W CS BT.  
7" W.Fir bears S.67°W. 12.8 ft. scribed S 2 T25S R8W CS BT.  
11" R.Fir bears N.65½°E.53.3 ft. scribed S36 T24S R8W CS BT.  
24" R.Fir bears S.58½°E.63.0 ft. scribed S 1 T25S R8W CS BT.

James W. Byron, Deputy  
M. Godfrey  
S. Blilow  
May 6, 1958  
C.S. File No. 49/84

Section Corner to Sections 34 & 35, T24S, R8W, & Secs. 2 & 3, T25S, R8W. <sup>8</sup>  
Found - Evans renewed Corner, BT's of record. REN #3

The Original S.E. & Evans' N.E. BT's now dead.

Set Brass Cap at Corner Mkd:  $\frac{S34}{S 3} | \frac{S35}{S 2}$  T24S R8W County Surveyor's  
T25S R8W Office, 1958.

New BT's: 5" R.Fir bears S.82°E. 26.3 ft. scribed S2 CS BT.  
7" R.Fir bears N.69½°E.36.2 ft. scribed S35 CS BT T24S R8W.  
I find Evans' N.W. BT., should be N.34°W. 24.4 ft.,  
record N.31°W. 25.2 ft.

Section Corner to Sections 27, 28, 33, 34. <sup>9</sup>  
Found - Orig. 36", now 42" Fir Snag S.55°E. 11.2 ft., has open face,  
some scribing visible " S ".

Orig. N. E. BT., now down.

Orig. S. W. BT., standing, shows old face but rotted now. ~~#90~~

All check good for bearing & distance.

Note - Corner under 40" Log.

Set Brass Cap at Corner Mkd:  $\frac{S28}{S33} | \frac{S27}{S34}$  T24S R8W County Surveyor's  
Office, 1958

New BT's: 18" R.Fir bears S.68°W. 21.0 ft. scribed S33 T24S R8W CS BT.  
(This BT. scribed high, 5' above ground to top scribing.)  
5" W.Fir bears N.38°W. 28.7 ft. scribed S28 CS BT.  
12" W.Fir bears S.59°E. 15.0 ft. scribed S34 T24S R8W CS BT.  
10" Fir bears N.20°W. 6.0 ft. scribed S27 T24S R8W CS BT.  
(This BT. scribed high, 7 ft. above ground to top of scribe.)

James W. Byron, Deputy  
M. Godfrey  
S. Blilow  
May 14, 1958  
C. S. File No. 49/88

$\frac{1}{4}$  Section Corner to Sections 27 & 34.  
Found - Both Original BT's & Each has good scribing & each is  
down (Windblown)

Set Brass Cap at Corner Mkd:  $\frac{1}{4} \frac{S27}{S34}$  T24S R8W County Surveyor's  
Office, 1958

New BT's: 5" R.Fir bears N.49½°E. 25.4 ft. scribed  $\frac{1}{4}$  S27 CS BT.  
14" R.Fir bears S.50°E. 11.6 ft. scribed  $\frac{1}{4}$  S34 CS BT.

$\frac{1}{4}$  Section Corner to Sec. 35, T24S R8W, & Sec. 2, T25S R8W. <sup>11</sup>  
Found - Both Orig. BT's., both check for bearing & Dist.  
Orig. 24", now 36" R.Fir N.8°W. 18.5 ft., good bark scrib " $\frac{1}{4}$ S".  
Do not find scribing on S. E. BT., center rotted.

Set Brass Cap at corner Mkd:  $\frac{1}{4} \frac{S35}{S 2}$  T24S R8W County Surveyor's  
T25S R8W Office, 1958 ~~30~~

New BT's: 20" Cedar bears S.70°W. 38.0 ft. scribed  $\frac{1}{4}$  S2 CS BT.  
36" R.Fir bears N. 8°W. 18.5 ft. bark scribed  $\frac{1}{4}$  S35 CS BT.

Corner to Sec. 13, T24S R8W, & Secs. 18 & 19, T24S R7W. <sup>12</sup>  
Found - all three Orig. BT's:  
Orig. 40", now 60" R.Fir N.64°W. 100.3 ft., shows good scar.  
I do not open.  
Orig. 12", now 14" Cedar Snag, shows good scribing "S",  
S.56°E. 27.7 ft.  
Orig. 36", now 40" Fir Snag, shows good scribing "BT"  
N. 56°E. 60.1 ft.

James W. Byron  
S. A. Blilow  
May 20, 1959  
C.S. File No. 49/11