

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97181

33

James W. Byron  
M. Stone &  
G. Layne  
Nov. 26, 1965  
C.S. File  
No. 49/84

Section Corner to Sections 2 - 3 - 10 - 11.  
Found - All Orig. BT's which check for bearings & distances.  
S. W. BT., now snag, previously opened, shows good scribing.  
N. W. BT., now down.  
S. E. & N. E. BT's. show good scars.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

S 2	S 3	
S 10	S 11	T24S R8W

New BT's: 10" R. Fir bears N. 88° E. 14.0 ft. scribed S3 T24S R8W CS BT.  
15" Laurel bears N. 54° W. 15.0 ft. scribed S2 T24S R8W CS BT.  
7" R. Fir bears S. 58° W. 14.2 ft. scribed S10 CS BT.  
13" W. Fir bears S. 44° E. 14.7 ft. scribed S11 T24S R8W CS BT.

5/69 - Fd. O.K. - V&T - - - - - C.S. 54/55

34

Vernon "Ray"  
Tracy  
& Crew  
April 18,  
1966  
C.S. File  
No. 49/41

Closing Corner of Sec. 1, T24-8W. & Sec. 6, T24-7W.  
Found - County Brass Cap properly mkd., See Ren. #19. T23S  
All BT's. down & dead or gone completely. S 36/  
R8W S 1/S 6 R7W  
New BT's: T24S  
8" W. Fir East 32.8 ft. Mkd: "CC T24S R7W S 6 CS BT".  
6" D. Fir S. 53° W. 74.2 ft. Mkd: "CC S1 CS BT". SEE ALSO  
Note - This corner lies 30 ft. south of old logging road. RENEWAL #93

RE-RENEWED, SEE CORNER NO. 93

35

1/4 Corner to Sections 11 and 14.  
Found - Orig. 30", now 42" Fir S. 65° W. 8.6 ft., Alive, shows good scar,  
open & find bottom of "S" scribe & reverse.  
Orig. 18", now 32" Fir N. 78° W. 8.6 ft., shows good scar, Do not open  
Set - Brass Cap Mkd: County Surveyor's Office, 1966

T24S	S 11
R8W	S 14

New BT's: 8" W. Fir N. 36 1/2° W. 16.3 ft. Mkd: 1/4 S11 CS BT.  
8" D. Fir S. 19° E. 21.0 ft. Mkd: 1/4 S14 CS BT.  
Note - Corner lies in shallow, draw on bench on top of ridge.

36

1/4 Corner to Sections 22 and 23.  
Found - Orig. 10", now 22" Fir S. 25° W. 7.9 ft., opened & shows "1/4 S" scribe.  
No trace of other Orig. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T24S R8W	1/4 S 22/S 23
----------	---------------

New BT's: 8" Hemlock S. 5° W. 45.3 ft. Mkd: 1/4 S22 CS BT.  
10" Hemlock S. 61 1/2° E. 55.6 ft. Mkd: 1/4 S23 CS BT.  
Note - This corner lies on steep (40°) North slope & 50 ft. E. of small draw, course N. E.

Vernon "Ray" Tracy  
Mike Stone & Jack Heritage  
April & May, 1966  
C. S. File No. 49/84

37

1/4 Corner to Sections 5 and 4.  
Found - Mound of Stone at Corner.  
Orig. 22", now 22" Fir Snag S. 88° E. 9.2 ft., shows "1/4" scribe,  
badly rotted & burned.  
Orig. 20", now 20" Fir Stump S. 80° W. 10.6 ft., badly burned &  
rotted. No scribe found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T24S R8W	1/4 S 5/S 4
----------	-------------

New BT's: 5" D. Fir S. 24° E. 14.4 ft. Mkd: 1/4 S 4 CS BT.  
5" D. Fir S. 27° W. 20.4 ft. Mkd: 1/4 S 5 CS BT.  
Note - This corner lies on top of ridge, course N. 75° E. & S. 75° W.

38

1/4 Corner to Sections 10 and 11.  
Found - Orig. 18", now 27" Fir N. 4° E. 18.5 ft., Open & shows "1/4" scribe,  
this BT. now down & dead.  
Orig. 20", now 36" Fir, down & dead, S. 38° W. 19.1 ft.,  
shows good scar. We do not open.  
DO NOT SET BRASS CAP at this time because of proposed road construction.  
New BT's: 9" W. Fir N. 47° E. 30.2 ft. Mkd: 1/4 S11 CS BT.  
18" D. Fir N. 49° W. 26.3 ft. Mkd: 1/4 S10 CS BT.  
8" D. Fir N. 11° W. 61.7 ft. Mkd: 1/4 S10 CS BT.

SEE REN. # 44