

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

76

$\frac{1}{4}$ Corner common to Sections 8 and 9.
Found - Corner Post Gone: - 18" Hemlock, dozed out, scar visible.
22" Fir, dozed out by cat, scar visible.
 $\frac{1}{4}$ corner reset by Weyerhaeuser from road location notes.
Set - 2" Iron Pipe with Brass Cap.
Referenced with "W" Nails and Plates: 32" Fir Stump S.45°E. 31.7 ft.
74" Fir Stump North 52.3 ft.

77

Center of Section 9.
The center of Sec. 9 was determined by the intersection of
the N-S and E-W centerlines of said section.
Set - 2" Iron Pipe with Brass Cap.
Referenced with "W" Nails and Plates. 32" Fir S.63°W. 25.9 ft.
40" Fir N.01°W. 18.0 ft.

78

Section cor. common to Sec. 3-4-9-10.
(Cor. set by Proportionate Measurement)
Set- 5/8"x36" Rod and Aluminum Cap.
Scribed- 13" Hemlock N.17 $\frac{1}{2}$ °E. 55.3 ft.
54" R. Cedar S.52 $\frac{1}{2}$ °E. 105.3 ft.
50" R. Cedar S.59 $\frac{1}{2}$ °W. 73 ft.
20" R. Cedar N.11 $\frac{1}{2}$ °W. 37.7 ft.

~~Set 5/8"x36" Rod and Aluminum Cap.
Scribed- 6" Douglas Fir S.58°E. 26.9 ft.
44" Douglas Fir N.31 $\frac{1}{2}$ °W. 55.4 ft.~~

79

$\frac{1}{4}$ Corner Common to Section 3 and Section 10.
(Cor. set by Proportionate Measurement)
Set- 5/8" Iron Rod and Aluminum Cap.
Scribed- 6" Douglas Fir S.58°E. 26.9 ft.
44" Douglas Fir N.31 $\frac{1}{2}$ °W. 55.4 ft.

80

Closing Corner for Sections 3 and 4.
Orig. field notes describe the BT's., as follows:
12" Hemlock S.60°E. 59 lks.
14" Hemlock S.51°W. 95 lks.
30" Hemlock N.53°W. 37 lks.

The BT's. found at this corner are all Doug. Fir, and the bearings
& distances do not match up in any manner. The Cadastral Surveyor in
a letter to us dated 2/19/70 suggested the corner be re-established
in the following manner. "Select a common point faced by the blazes
on all the BTs. If the trees were blazed properly at the time of
marking, the point so determined should fall close to a point 2.06 ch.
west of the corner of Sec. 33 & 34, south boundary of T23S. R.8W."
Set - Iron Pipe with Brass Cap at this point which is 136.7 ft.
west of the brass cap corner for Secs. 33 & 34, T.23S., R.8W.
The Old BT's. are now: 36" D. Fir N. 4° W. 30.5 ft.
36" D. Fir N.57°E. 36.6 ft.
20" D. Fir S.78°E. 36.2 ft.
Scribed New BT's: 10" D. Fir N.74°W. 15.0 ft.
5" D. Fir S.77°E. 11.0 ft.
12" D. Fir S.46°W. 17.9 ft.

RE-NEWED CORNER #103

Nick Juliano
For Weyerhaeuser Co.
Sept., 1969
C.S. 55/120

Map M 38 - 47

Howard W. Johnstone
For Roseburg Lumber Co.
Feb., 1970
M 39 - 15

Howard W. Johnstone
For Roseburg Lbr. Co.
March 30, 1970 C.S. File 55/144

MARCH 71