

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

see 1998/99  
BLM PG 20695-6  
REUR 4-6

Burton W. Holt  
For Hult Lumber Co.  
Wit: C. Halverson  
March 27, 1960  
C.S. File No. 51/71

Section Corner of Sections 17, 18, 19, & 20.  
as determined by old BT's:  
16" Hemlock S.29°E. 21.1 ft. -- gone.  
8" Yew N.22°E. 13.2 ft.--fd. standing & dead with scribes burned off.  
10" Yew S.57°W. 26.4 ft.--fd. standing & dead with scribed clearly vis.  
14" Cedar N.48°W. 27.7 ft.--fd. down & nearly gone but scribes vis.  
Set 1/2" x 36" Iron Pipe from which:  
10" D.Fir bears S.74°W. 23.0 ft. mkd. S19 BT.  
10" D.Fir bears N.45°30'W. 19.7 ft. mkd. T25S RLW  
9" D.Fir bears S.85°E. 16.4 ft. mkd. S20 BT.  
9" D.Fir bears N.11°30'E. 34.2 ft. mkd. S17 BT.  
This corner is on a SE slope in old burn with heavy stand of reproduction.

16

FD 10/30/84  
R. GEISLER  
C.S. 58/146

Section Corner common to Sections 8, 9, 16, 17.  
The orig. surveyor thoroughly fouled up his recorded notes by misnaming the BT. species & by giving wrong bearings, but the corner was finally reset from the two remaining BT's. by observing the directions the scribes faced & by using the recorded distances for the two trees in their respective quadrants. The old blazed section lines also tie in with the restored corner.  
Orig. Notes: A basalt Stone; now missing, 18" x 10" x 8", with 4 notches on the south edge & the east edge, & from which:  
16" Fir, bears N.30°E. 7.9 ft. (Yew)  
8" Cedar " S.59°E. 21.1 ft. (now missing)  
5" Fir bears S.14°W. 33.0 ft. (Cedar)  
6" Fir bears N.42°W. 13.9 ft. (now missing)  
Restored Corner: 1/2" Brass Rod set from which:  
10" Yew, blown down, but with scribes visible & facing the corner, bears N.77°E., 7.9 ft. (Orig. BT.)  
26" Cedar, scribes visible & facing the corner, bears S. 9°W. 33.0 ft. (Orig. BT.)  
58" D. Fir, newly scribed by Shaner, "S 16 BT", bears S.89°E, 58.9 ft.  
16" D.Fir, newly scribed by Shaner, "T25S, RLW, S8, BT", bears N.36°W, 30.7 feet.

17

RE-RECORDED CORNER NO. 58

Bruce A. Shaner  
For National Plywood, Inc.  
Wit: Wm. James, & James Griffin  
April 21, 1960  
C. S. File No. 51/92

1/4" Corner common to Secs. 8 and 9.  
The orig. surveyor misnamed the species of the BT's, read the bearings from the trees to the corner instead of from the corner to the trees, and called one of the distances incorrectly. He also called the streams & ridges on the section line from the south at grossly incorrect distances & fouled up the description of the section corner to the south.  
Orig. Notes: A squared Post, from which a:  
4" Dogwood bears S.80°E., 17.2 feet.  
5" Cedar bears S.76°W., 12.5 feet.  
Restored: Set a square maple post, from which a:  
50" Fir, Orig. BT. with the scribes visible & facing the corner, bears N.80°W., 22.5 ft.  
8" Maple, orig. BT. with the scribes visible & facing the corner, bears N:76°E., 12.5 ft.  
A line bearing due south from the restored corner about 1/2 chain hits a tree, apparently marked on the original survey as a line tree.

18

SEE BLM 1998/99  
REUR PG 20699  
19  
1/4" Corner common to Sections 8 and 17.  
The Orig. Surveyor misnamed the BT. species, as shown following.  
Orig: Basalt Stone; 16" x 10" x 6", 1/4" scratched on north face, from which:  
(The above stone may or may not be present, as a cedar windfall lays over the spot.) 4" Dogwood bears N.16°E, 42 links.  
5" Hemlock bears S.35°W, 12 links.  
Restored: Placed a mark on a cedar windfall(which possibly lays over the orig. stone, from which a: 11" Hemlock, broken off, with scribed visible, bears N.16°E., 42 links.  
8" Yew, with scribes visible bears S.35°W., 12 links.

19