

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

36

$\frac{1}{4}$ Corner to Sections 30 and 31.
Found - "X" & " $\frac{1}{4}$ " in bedrock according to Gov't field notes.
Rotted Remnants of Fir Stump S.14°W. 20.5 ft.
Rotted Remnants of Fir Tree N.86°W. 52.1 ft., no scribing fd.
Impossible to Set Brass Cap in this location, solid bed rock.
New BT's: 16" D.Fir N.62°E. 78.3 ft. (slope meas.) Mkd: $\frac{1}{4}$ S30 CS BT.
10" D.Fir S.55°E. 72.6 ft. (level meas.) Mkd: $\frac{1}{4}$ S31 CS BT.

FOUND O.K. Oct. 1966 C.S. 52/30

37

Section Corner to Sections 28 - 29 - 32 - 33.
Found - Rock as called for in Gov't notes lying on ground near corner.
Rotten Fir Snag, 30", S.40°E. 15.2 ft., good scribing visible.
Clump of young chinquapins S.49 $\frac{1}{2}$ °W. 26.4 ft.
Clump of young Dogwoods N.35°W. 26.4 ft.
No trace found of N. W. BT.
Set - Brass Cap Mkd: County Surveyor's T25S RLW $\frac{S29}{S32}$ | $\frac{S28}{S33}$
Office, 1961
Set - Original Rock alongside
New BT's: 8" D.Fir N.30°W. 4.9 ft. Mkd: T25S RLW S29 CS BT.
10" D.Fir N.44°E. 26.3 ft. Mkd: T25S RLW S28 CS BT.
7" D.Fir S.39°E. 7.6 ft. Mkd: T25S RLW S33 CS BT.
5" D.Fir S.31°W. 14.6 ft. Mkd: S32 CS BT.

Milo E. Godfrey, Deputy
Vernon Tracy
Clete Putnam
October 1961
C. S. File No. 52/30

38

South Corner of Sections 35 and 36 only on Twyp. Line.
Found - "X" on Rock in place, nearly buried under loose material.
"B.O." chiseled on Rock outcrop N.45°E. 12.5 ft.
Stump Hole & Maple Sprouts N.76 $\frac{1}{2}$ °W. 48.2 ft.
Impossible to set Brass Cap solidly at corner position.
New BT's: 6" W.Oak N.39°E. 28.4 ft. Mkd: S36 CS BT.
18" D.Fir S.48°W. 12.0 ft. Mkd: T25S RLW S35 S36 CS BT.

RE-RENEWED, SEE CORNER NO. #141
C.S. 52/30 same as above.

39

$\frac{1}{4}$ Corner to Sections 22 and 23.
Found - Fir, now 10", N.32 $\frac{1}{2}$ °E. 5.9 ft. Tree has broken off and is down, good scribing "S" visible in broken portion.
No trace of Hemlock to S.W. can be found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S RLW $\frac{S22}{S22}$ | $\frac{S23}{S23}$
New BT's: 9" Hemlock S.33°W. 11.3 ft. Mkd: $\frac{1}{4}$ S22 CS BT.
18" W.Fir N.35°E. 37.3 ft. Mkd: $\frac{1}{4}$ S23 CS BT.

RE-RENEWED, SEE CORNER NO. 93

40

$\frac{1}{4}$ Corner to Sections 15 and 14.
Found - Hemlock Stump, now 11" diam.) S.63°W. 13.9 ft., cut open scar & found good scribing "B".
Red Cedar Tree, now 20", N.46°E. 14.5 ft., shows good scar.
Did not open.
Corner lies at edge of cut bank about 15 ft. high along edge of road.
Set - Wit. Cor. 10 ft. North of true corner.
Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1962
T25S RLW W.C. S15/S14 10 ft. S. to $\frac{1}{4}$ Cor.
Rescribed 20" Cedar East 11.0 ft. (from W.C.) Mkd: "W.C. $\frac{1}{4}$ S14 CS BT".
New BT: 8" Hemlock N.66°W. 16.0 ft. Mkd: W.C. $\frac{1}{4}$ S15 CS BT.

FOUND O.K. Nov. 1966 C.S. 52/30

41

Section Corner to Sections 15 - 14 - 22 - 23.
Found - Rotten Hemlock Snag N.69°W. 24.4 ft., good scribing visible on old face "R 1 W S15".
Rotten Cedar Snag N.87°E. 12.5 ft. Fragments of scribing visible on badly rotted face.
Red Cedar Tree, now 38", S.79 $\frac{1}{2}$ °E. 9.9 ft. scar faintly visible. Did not open. S. W. BT. not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S RLW $\frac{S15}{S22}$ | $\frac{S14}{S23}$
New BT's: 6" Hemlock S.51 $\frac{1}{2}$ °W. 23.8 ft. Mkd: T25S RLW S22 CS BT.
15" R. Cedar N.62°W. 29.0 ft. Mkd: T25S RLW S15 CS BT.
38" R. Cedar S.79 $\frac{1}{2}$ °E. 9.9 ft. Mkd: T25S RLW S23 CS BT.
No tree available to N.E. - Corner lies approx. 200 ft. W. of Road.

RE-RENEWED, SEE CORNER NO. 94

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Clete Putnam
June 6, 1962
C. S. File No. 52/30