

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T.S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

48

Section Corner to Sections 2 - 3 - 10 - 11.

Found - Rock as called for in Gov't. field notes, 2 notches on E. & 5 notches on S. side.

Rotted remains of 10" Fir N.43°E. 29.7 ft., scribing still visible "T2 SR S2 BT".

12" Fir S.8°W. 17.8 ft., scar plainly visible. Tree dying.

40" Pine N.21°W. 20.5 ft., has been previously opened & good scribing "S" plainly visible.

No trace of Dogwood to S.E.

Alongside Rock at Cor. Set Brass Cap Mkd: County Surveyor's Office, 1962 T25S RLW

S 3 | S 2
S10 | S11

New BT's: 17" D.Fir N.48°E. 36.7 ft. Mkd: T25S RLW S2 CS BT.

18" Hemlock S.85°E. 20.0 ft. Mkd: T25S RLW S11 CS BT.

10" D.Fir S.15°W. 29.2 ft. Mkd: T25S RLW S10 CS BT.

Pine to N.W. still in good condition.

49

Section Corner to Sections 23 - 24 - 25 - 26.

Found - 3/4" Iron Reinforcing Rod, no record.

Did not find rock called for in Gov't Notes. - *SEE COR #51*

All Orig. BT's. alive & standing vis:

5" Hemlock, now 8", S.75°W. 9.9 ft. Prev. opnd. & scrbing vis.

6" Hemlock, now 8", N.61°W. 14.5 ft., shows good scar.

5" Hemlock, now 5", S.43°E. 7.3 ft., shows good scar.

10" W.Fir, now 17", N.35°E. 12.5 ft., shows 2 good scars.

Corner & BT's. in good condition. Corner lies on E. slope approx.

150 ft. West of S. end of bridge on Canton Creek Road.

This corner found by Godfrey and Crew & everything checked so is a good corner but never has been recorded.

50

1/4 Section Corner: Section 15 and 22.

Found - 9" Cedar, North 21° East, 20.4 ft. (poor condition)

Set - 2 1/2" Aluminum Cap

16" Hemlock, N. 73 1/2° E., 36.0 ft. Mkd: 1/4 S15 BT.

9" Cedar, S. 34° W., 7.2 feet Mkd: 1/4 S22 BT.

February 1963

51

Section Corner // Sections 23, 24, 25, 26.

Found - Original Stone (broken) - *SEE COR #49*

18" D.Fir, N. 35° E., 12.5 ft.

6" Hemlock, S. 43° E., 7.3 ft.

10" Hemlock, S. 75° W., 9.9 ft.

11" Hemlock, N.61° W. 14.5 ft.

Set - 2 1/2" Aluminum Cap. - *FOUND OK.*

Oct. 1966 - C.S. 52/30

November 1962

52

Section Corner: Sections 1, 2, 11, 12.

Found - 12" D.Fir, S. 12° E., 21.1 ft. *CON #26*

11" Yew, N. 4° E., 49.0 ft., (down)

Set - 2 1/2" Aluminum Cap & 62" D.Fir Stump, N.25 1/2° E. 29.2 ft., Mkd: S1 BT.

64" D.Fir, N. 46° W., 69.3 ft. Mkd: S2 BT.

5" Vine Maple, S. 81 1/2° W., 6.4 ft., Mkd: S11 BT.

January 1963

53

Section Corner to Secs. 2 & 1, T25-1W. & Secs. 35 & 36, T24-1W.

Found - 11" Fir S.30°E. (not S.10°E) 13.2 ft., previously opened, good scrbing.

30" Fir N.14°E. 15.8 ft., shows good scar.

48" Sugar Pine S.15°W. 13.9 ft., shows good scar.

15" Fir N.26°W. 20.5 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S

Office, 1963 T25S

RLW S35 | S36
S 2 | S 1

New BT's: 21" D.Fir S.55°W. 11.0 ft. Mkd: T25S RLW S2 CS BT.

12" I. Cedar N.47°E. 24.1 ft. Mkd: T24S RLW S36 CS BT.

Milo E. Godfrey, Deputy
Mike Stone, chairman
October-
1962
C. S. File No. 52/30

Thomas E. Shrum, Jr.
By U.S. Plywood Corp.
Date noted on Corner
C. S. File No. 51/254

Milo E. Godfrey
V. Tracy & M. Stone
June 4, 1963
C. S. File No. 52/30