

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

112

$\frac{1}{4}$ Corner to Sections 3 and 10.
Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap marked.
Bearing Trees: 6" D. Fir S. 33 $\frac{1}{2}$ ° W. 30.2 ft.
40" D. Fir Stump N. 36° E. 52.1 ft.

113

$\frac{1}{4}$ Corner to Sections 9 and 10.
Set - 2 $\frac{1}{2}$ " diam. Aluminum Cap marked.
Bearing Trees: 8" Hemlock N. 45° W. 7.7 ft.
11" D. Fir N. 40° E. 33.0 ft.

114

Center $\frac{1}{4}$ Corner of Section 10.
Set - 2 $\frac{1}{2}$ " diam. Alummm. Cap marked.
7" Cedar N. 58° W. 15.5 ft.
12" Hemlock S. 3 $\frac{1}{2}$ ° W. 17.8 ft.

115

$\frac{1}{4}$ Corner common to Sections 4 & 9.
The $\frac{1}{4}$ section corner is a 4" Chinquapin tree, now broken and chopped down, but with original bear scribes (Johnson, 1900) still visible, though faint, on the north side of tree; scribes visible were " $\frac{1}{4}$ S". The original (1900) section line blazes were in line, (east-west) with this corner.

At the $\frac{1}{4}$ corner, I set a 3" square yew post, scribed " $\frac{1}{4}$ S" from which a:

4" Chinquapin, probable original bearing tree, but with face freshly chopped off, bears N. 28° E., 14.6 ft.
(record N.28°E. 12.5 ft.)

Sprouts from probable original Chinquapin bearing tree, now missing, bears S. 28° W. 5.9 ft.

26" Douglas Fir bearing tree, Stump only, I scribed " $\frac{1}{4}$ S S9 BT", bears S. 122° W. 33.7 ft.

26" Douglas Fir bearing tree, I scribed " $\frac{1}{4}$ S S4 BT" bears N. 46° W. 13.9 ft.

Note - An iron pipe at a proposed $\frac{1}{4}$ section corner set by U. S. Plywood Corp, by proportional measurement, bears N. 81 $\frac{1}{4}$ ° W., a distance of 66.0 ft. from the corner as found by me.
See Renewal No. 109 for Shrum's work. Also C.S. 52/30.

116

Closing Corner $\frac{2}{25}$ S 31 T24-1W / S 1 | S 6 T25-2W
Found - 1951 Cad. Brass Cap, properly mkd. & BT's down & out of place.
I.P. & Steel Cap (See Ren. #11-A) bears N. 21°W. 2.8 ft. The BT's. for this corner are also down.
Note - Cadastral corner lies on east slope on cutting line, course E-W with timber to north.
New BT's: 8" cedar S. 64° W. 114.6 ft. mkd. T25S R2W S1 CC CS BT.
34" D.Fir S. 79 $\frac{1}{2}$ ° E. 41.6 ft. mkd. T25S R1W S1CC CS BT.

117

$\frac{1}{4}$ Corner to Sections 19 and 20.
Found - Orig. 8", now 16" Cedar N. 85° E. 40.9 ft. Alive, we open & find " $\frac{1}{4}$ S20" scribe.
Orig. 12", now 30" fir, S. 75° W. 2.6 ft., now lying nearly face down.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 T25S R1W $\frac{1}{4}$ S 19 | S 20
New BT's: 16" cedar S. 73° E. 38.8 ft. mkd. $\frac{1}{4}$ S20 CS BT.
7" Chinquapin S. 39° W. 56.2 ft. mkd. $\frac{1}{4}$ S19 CS BT.
(Scribed 4' above ground due to log)
Note - This corner lies in logged-off area on top of spur ridge sloping W.

Thomas E. Shrum, Jr.
For. U.B. Plywood Corp.
December, 1966
CMap File N. 32-63

Bruce A. Shaner
For National Plywood, Incp.
March 25, 1967
C. S. File No. 55/31

Vernon "Ray" Tracy
Jack Heritage & E. West
May, 1967
C.S. File No. 52/30