

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S, T. S. R 2 W, R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

64

$\frac{1}{4}$ Corner to Section 30 only, T25S-R2W.
Found - GLO Brass Cap, 1943, mkd., & BT's. as follows:
24" Fir, now down & out of place, N. 49° E. 87.8 ft.,
scribe visible on burned face.
30", now 57" Fir, almost dead, S. 43° E. 104.9 ft., face
burned, scribe barely visible, Rescribe " $\frac{1}{4}$ S CS".
New BT's: 12" D. Fir N. 44° E. 87.7 ft. Mkd: $\frac{1}{4}$ S30 CS BT.
4" Pine S. 12° E. 75.5 ft. Mkd: $\frac{1}{4}$ S BT" (only)
Note - This corner lies on N.W. edge of small clearing approx.
150 x 300 ft. on south slope.

65

$\frac{1}{4}$ Corner to Section 36 only, T25-3W.
Found - 1943 GLO Brass Cap mkd., & remains of BT's.
9", now 9" Fir Stump, S. 82° W. 11.8 ft. (face) " $\frac{1}{4}$ S36BT" on
burned face.
13" Fir, now turned out, N. 38° W. 5.9 ft., face burned,
fragmentary scribe visible.
New BT's: 5" D. Fir S. 73° W. 38.9 ft. Mkd: $\frac{1}{4}$ S36 CS BT.
7" Hemlock N. 23° W. 22.4 ft. Mkd: $\frac{1}{4}$ S36 CS BT.
Note - Corner lies 25 ft. north of top of small spur, sloping S. 60° E.

66

$\frac{1}{4}$ Corner to Section 31 only, T25S-R2W.
Found - 1943 GLO Brass Cap mkd., firmly set & in good condition.
6", now 9" Fir S. 52° E. 5.9 ft., shows good scar. Alive.
36" Fir, now stump, N. 82° E. 82.1 ft., scribe visible on
unhealed blaze. (Recorded as 26" Fir)
New BT: 6" D. Fir N. 67° E. 41.3 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
Note - Corner lies approx. 650 ft. north of $\frac{1}{4}$ Cor. S.36, T25-3W,
(see above).

67

Sec. Cor. to Secs. 25 & 36, T25-3W.
Found - 1943 GLO Brass Cap mkd.
Orig. 24" Hemlock, alive, N. 61 $\frac{1}{2}$ ° W. 20.5 ft., shows scar.
Do not open.
Other Orig. BT's. are now snags or gone.
30", now 32" R. Cedar, alive & in good condition S. 43° W.
56.8 ft., scribe visible on unhealed blaze.
12", now 16" W. Fir N. 39° W. 31.7 ft., now snag, shows
good scar.
No trace of BT's. as recorded in Ren. #11, T25-3W.
New BT: 6" Yew N. 41° W. 25.4 ft. Mkd: T25S R3W S25 CS BT.
Note - This corner lies 50 ft. north of Rock Creek Road, course
E. & W.

68

Township Corner

R	3	S	36	S	31	2	T24S
W	S	1	S	6	W	T25S	

Found - GLO Brass Cap mkd. as above.
Orig. 48", now 50" Fir Stump, N. 50 $\frac{1}{2}$ ° W. 42.2 ft., shows
fragmentary scribe on burned face, we rescribe "T25SR3W S1 CS BT".
All other BT's. gone or out of place due to logging.
New BT: 54" D. Fir (Stump 8.0 ft. high) N. 37° E. 26.4 ft. Mkd:
"T24S R2W S31 CS BT.
No other trees available. Corner lies in greasewood
thicket 20 ft. E. of Cat. Road & 20 Ft. W. of bottom of small draw.

69

$\frac{1}{4}$ Corner Section 1 only, T25-3W.
Found - GLO Brass Cap(1943) mkd. & bent over. We straighten &
Reset in mound of stone. N. W. BT. gone, Stumps of S. E.
& S. W. BT's. remain.
New BT: 12" Fir, snag, 15' high, N. 73° W. 39.4 ft. mkd. $\frac{1}{4}$ S1 CS BT.
No live trees available, corner lies on very steep, N. slope, 10 ft.
N. of rock face 6.0 ft. high x 25.0 ft. long, course N. & W.

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
June and July 1966
C. S. File No. 54/27

RENEWED, SEE CORNER NO. #127
RENEWED, SEE CORNER NO. #128