

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

91

Closing Corner to Sections 31 and 32, T25-2W. (South Bdry)
 Found - 21" Cedar N.67°E. 20.3 ft., some scribing visible. See Ren. #54
 25", now 28" Cedar N.68°W. 27.8 ft., shows good scar.
 4" Fir Post at Cor. Mkd: CC S31 & S32.
 Set - Brass Cap at C.C. Mkd: County Surveyor's Office T25S R2W #103
 1972 C.C. S 31 | S 32
 S 6
 T26S
 Bearing Trees O. K. and Tagged.

Section Corner to Sections 5 and 6 only, T26-2W. (North Bdry) 92
 Found - Corner Tree, Broken Stob.
 24" D.Fir, now down, S.68°E. 49.5 ft., shows good scar.
 14" D.Fir, now down, S.30°W. 23.8 ft.
 Set - Brass Cap on Side of Corner Stump(14") Mkd: T 25 S R 2 W
 County Surveyor's Office S 32
 1972 S 6 | S 5
 T 26 S
 New BT's: 17" D.Fir N.14½°W. 8.6 ft. scribed T25S R2W S32 CS BT.
 15" D.Fir S.75°W. 35.0 ft. scribed T26S R2W S6 CS BT.
 No trees too good to the S.W. because of Rock Bluff directly south
 of corner, approximately 15 ft. high. 7/3/72

¼ Corner Sections 15 and 16. 93
 Found - No trace of Brass cap. Ren. No. 74
 15" Maple, N.49°E., 44.5 ft. Alive, scribe visible Ren. No. 5
 19" Maple, west 52.8 ft. Alive, blaze healed.
 18" Cedar, S.32°W., 109.1 ft. Alive, scribe visible
 17" Maple, N.29°E., 32.0 ft. Alive, scribe visible #130
 Set - Brass cap at cor. mkd. COUNTY SURVEYORS' OFFICE T 25 S R 2 W
 1973 S 16 S 15
 Note - This cor. lies 60 ft. west of Rock Creek and 280 ft. south of
 Rock Creek Road. Creek and road course southwest. 7/25/73

1/4 Cor. for Sec. 34 and 35 94
 Found - Steel tube & survey cap mkd. "Property Corner" &
 3 Fir BT's as described by Lecklider in 1960. Ren. #45
 We found no evidence of the purported visit by County surveyors
 office crews to this corner in 1968 as described in renewed
 corner #89.
 This corner lies on a southwesterly slope in a dense growth
 of fir and vine maple. 5/10/74

Center 1/4 Section 26 95
 Set - A 2" X 30" I.P. with a brass cap.
 A RR spike in a 42" Fir, S.55°E., 7.8 ft.
 A RR spike in a 48" Fir, N.23°W., 19.7 ft.
 Oct. 1973 96

Center 1/4, Section 20
 Set - 5/8" Iron rod
 From which:
 A 10" White fir, bears N.72°W., 5.6 ft. scribed C 1/4 S20 BT.
 A 24" Cedar, bears N.61°E., 18.5 ft. scribed C 1/4 S20 BT. 1/76

South 1/16, East boundary Section 24 97
 Found - Hosford's scribed post, out of place.
 16" Fir, now 18", face healed over, S.53°W., 31.2 ft.
 24" Cedar, now 26", scribing visible, N.10 1/2°W., (rec. N.11 1/2°W)
 64.3 ft. to face.
 Set - Drove 3/4" Pipe by Hosford's.
 Accdssories added:
 26" Cedar bears N.10°W., 63.8 ft. with "W" nail and plate.
 38" Fir, S.85°W., 15.0 ft. with "W" nail and plate. 2/26/75

John M. Powell
 Ed Monrean
 C. S. File No. 54/40

Vernon "Ray" Tracy
 J. Heritage
 CS File 56/34
 7/25/73

Gary Langlitz
 P. Earle
 C.S. 56/51
 5/10/74

Triangel Eng.
 Nick Juliano
 for
 Weyerhaeuser

Glenn Baughman
 For: Weyerhaeuser
 Company
 Jan. 1976
 M 56 - 35

Frank O. Williams
 Glen McChesney
 For: Weyerhaeuser Co.
 Feb. 26, 1975
 C.S. 59/11